

Douglas County Surveyor's Record of
Government Corners Renewed

26 T.S. 6 R.W.W.M.

F. J. Cole
Deputy
Wit.
Miles Park
May 6, 1915
F.B. 37, P. 38

E. Summers D.C.S.
Feb. 20, 1920
Wit.
Wm. McClanshan
Johnston
NO REF. FOUND

J. W. Cole Deputy
Witnesses L. H. Smick
Herman Marks
April 15, 21

J. W. Cole Deputy
April 20, 1921

F.B. 59, P. 53
Also an
Iron Pipe set
by John Watters
Feb. 1924

F.B. 59, P. 54

F.B. 59, P. 46

F.B. 59, P. 47

F.B. 59, P. 48

F.B. 59, P. 49

F.B. 59, P. 50

- 1 SEC. COR. BET. SECS. 25 and 26 SECS 25 & 36
Rock set for Cor. from which original tree bears S.25°W.,
93 lks. Marked new trees
Black Oak 6" dia. bears N.29°E., 21 lks.
Black Oak 6" dia. bears S.53°W., 20 lks. 51 & 37
- 2 SEC. COR. BET. SECS. 31 and 32
Set a Blue Lime Stone 6 x 18" marked S from which
A White Oak 9" dia. bears S.87°45'W., 4.82 ch. 146
A Black Oak 36" dia. bears N.25°15'W., 6.05 ch. Old B.T.
- 3 MEANDER CORNER ON SOUTH UMPQUA RIVER BETWEEN SECS. 31 and 32
On right bank of River. Re-set 8 chains North of $\frac{1}{2}$ Sec.
Corner by setting a lime Stone 6 x 18" form which
A Black Oak 24" bears S.22 $\frac{1}{2}$ °W., 1.35 ch. - SEARCHED FOR, NOT FOUND
A White Oak 9" bears S.22°E., 0.94 ch. July 1964 - MEG. C.S. 52/87
- 4 N.E. CORNER OF FITZHUGH D.L.C. # 40
I renewed this corner from two original B.T.s which are
alive and standing and bearing scars but do not correspond
with the Gov't. Field Notes. An old record of Mr. Thiel's
says these trees were marked by the U. S. Surveyor. I
renewed the Corner by setting an Iron Pipe 1 x 30" also
an Oak Post, from which the trees bear as follows
A White Oak 15" dia. bears N.69°30'W., 27.7 ft. 47
A Black Oak 26" dia. bears S.38°15'W., 14.5 ft.
- 5 COR. TO SECS. 20-21-29-28
I renewed this corner from the original Bearing trees
which bear as follows
A Black Oak 48" standing and bearing scribe marks bears
S.71°30'E., 80.5 ft.
A White Oak 30" standing and bearing scribe marks bears
S.53°30'W., 131.0 ft.
A Snag of a Black Oak bears scars bears N.80°45'W., 154.8ft.
A Large White Oak down bearing scars bears N.85°E., 108 ft.
Set Iron Pipe and end Oak Post 4 x 4 x 36"
- 6 COR. BET. SECS. 20 and 21.
I renewed this Corner from original Bearing trees
A White Oak S.83 $\frac{1}{2}$ °E., 186.1 ft.
A White Oak down decayed N.55°W., 178 ft. 128
Set a 4 x 4 x 40" Oak Post and Marked a new tree
A White. Oak 10" dia. bears S.12°30'W., 33 ft.
- 7 COR. TO 16-17-20-21
I renewed this corner from the rotting remains of the
original B.T.s one of which Mr. James Cooper testifies that
he had seen scribe marks on several years previously. The
remains of the trees checked for direction and distances given
in the field notes. I set an Iron Pin $\frac{1}{2}$ x 36" and marked
new trees
A White Oak 20" dia. N.42°15'E., 122.6 ft. 126
A White Oak 30" dia. N.17°50'W., 224.2 ft.
- 8 S.W. COR. OF CL. 61
I renewed this corner from the original bearing tree which
was alive and standing and which I chopped open and found the
scribe marks. I set an Oak Post for Cor. and marked new
trees as follows
A Black Oak 30" dia. S.16°15'W., 162.5 ft. 92A
A White Oak 30" dia. N.19°W., 157.1 ft.
A Rock 8 x 10 x 12" marked Cl. 61 bears N.88°E., 2 ft.
- 9 CORNER NORTH BDY OF SECTION 20
I renewed this Corner from the original bearing trees. Set
a 4 x 4 x 40" Oak Post from which the original bearing
trees bear as follows
S.57°E., 9.9 ft.
N.17°E., 30 ft. 92

25/30 7/23/64

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.

SEE CORNER NO.