

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

- 10
- N.W. CORNER OF CL. # 43  
 ✓ I set an Iron Pipe and an Oak Post from which a White Oak 12" dia. bearing scars but no scribe marks visible on account of decay bears S.83°E., 52.6 ft. A White Oak 18" dia. dead showing no marks bears S.37°W., 4.2 ft. Marked New Trees as follows  
     A White Oak 15" dia. N.62°30'W., 8.5 ft.  
     A White Oak 22" dia. N.22°30'E., 47 ft.
- 11
- S.E. CORNER OF CLAIM # 61  
 ✓ I renewed this corner from the original B.T. which I chopped open and found the scribe marks. I set an iron pipe also an Oak Post 4 x 4 x 40".  
 SEE CORNER NO. 106
- 12
- 1/4 CORNER BETWEEN SECTIONS 16 and 21.  
 ✓ I renewed this corner from the original B.T.'s. The tree N.35°30'W., was alive and standing showing scars. The tree S.21°45'W. was down and nearly burned up. The directions and distances checked. I set a 4 x 4 x 40" Post and erected a mound of rock. Marked a new tree  
     A Black Oak 14" dia. bears S.35°30'W., 11 ft.  
 SEE CORNER NO. 147
- 13
- CORNER TO SECS. 15, 16, 21 and 22.  
 ✓ Set an Iron Pipe also an Oak Post from which the original B.T.s bear as follows  
     A Black Oak alive and standing S.22°30'W., 42.2 ft.  
     A Stump showing scribe marks. S.67°30'E., 54.1 ft.  
     A White Oak B.T. standing N.56°45'E., 40.3 ft.  
     A white Oak N.13 1/2°W., 34.1 ft.  
 SEE CORNER NO. 63
- 14
- 1/4 COR. BET. 15 and 22  
 ✓ I renewed this corner from both original bearing trees which were alive and standing. Both trees show scars and check for direction and distance. Set an Oak Post 4 x 4 x 40" also 1 x 30" Iron Pipe and erected a mound of Rock.  
 SEE CORNER NO. 121
- 15
- 1/4 CORNER BETWEEN 21 and 22  
 ✓ I renewed this corner from the rotted remains of both original trees which check closely for direction and distance I set an Oak Post 4 x 4 x 40" also an Iron Pipe 1 x 30" from which mark new trees  
     A Black Oak 10" dia. bears S.54°W., 5.4 ft.  
     A Black Oak 10" dia. bears N.30° 1/4 W., 16 ft.  
 SEE CORNER NO. 64
- 16
- 1/4 CORNER BETWEEN SECS. 21 and 28.  
 ✓ I set an Oak Post 4 x 4 x 40" also an Iron Pipe 1 x 30" from which a stump of an original B.T. bears S.5 1/2°E., 181.5 ft. A Sang of B.T. bears scribe marks N.68°30'W., 171 ft. Marked new trees as follows  
     A Black Oak 16" dia. bears N.68°30' W., 4 ft.  
     A Double White Oak 24" dia. bears South 68.5 ft.  
 SEE CORNER NO. 65
- 17
- CORNER TO SECTION 27-28-33-34.  
 ✓ I renewed this corner from one original B.T. S.67°15'E., 174.2 ft. (Note--This corner is set wrong. It is 77 f. on the ground--calls for 264.lks.) which is alive and standing and bearing scribe marks also by tie to Meander Cor. which I located from one of the Bearing Trees. I set an Oak Post for Sec. Cor. also erected a mound of rock. Marked new trees as follows  
     A White Oak 10" dia. N.50°W., 47 ft.  
     A White Oak 10" dia. S.38°W., 54 ft.  
 SEE CORNER NO. 91
- 18
- 1/4 COR. BET. 28 and 29.  
 ✓ I renewed this corner from the original Bearing Trees both of which were alive and standing. I set a 4 x 4 x 40" Post also an Iron Pipe 1 x 30".  
 SEE CORNER NO. 56

J. W. Cole Deputy County Surveyor  
 May 1921  
 M 1-69

F.B. 51, P. 14  
 F.B. 50, P. 61  
 F.B. 50, P. 62  
 F.B. 50, P. 63  
 F.B. 50, P. 64  
 F.B. 50, P. 66  
 F.B. 50, P. 68  
 F.B. 51, P. 4  
 F.B. 51, P. 7