

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26 T. S. R 6 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Feb. 6, 1961  
C.S. File No. 49/79

1/4 Section Corner to Sec. 34, T26-6W. & Sec. 3, T27-6W.  
Found - Both Orig. BT's. We open N. W. BT. & find good reverse  
scribing "BT". Both BT's., now 40" W. Oaks, check  
record bearing & distance.

Also find 1" Iron Pipe at Corner.

Set - Brass Cap at Corner Mkd: County Surveyor's 1/4 S34 T26S  
O.K. 1-24 Office, 1961 S 3 T27S R6W

New BT: 11" W.Oak N.61 1/2°E. 81.0 ft. scribed 1/4 S34 CS BT.

FD. out of Ground  
Reset - M 95-71  
G. BAUGHMAN  
12/83  
FD. B.C.  
2/90  
M110-47

87

James W. Byron, Deputy  
Milo E. Godfrey  
Clete Putnam  
May 29, 1961  
C. S. File No. 52/87

Section Corner to Sections 13 - 14 - 23 - 24.  
Found - W. Oak S.67 1/4°E. 71.3 ft., Tree now 18". This tree had been  
opened and old scribing "R6W SS2" is visible in opened scar.  
20" W.Oak, not B.Oak, S.66 3/4°W. 113.5 ft., shows two good scars,  
did not cut open.

Burned remnants of Oak Stumps to N. W. and N. E., in place,  
fit bearings & distances for N.E. & N.W. BT's. Too far gone  
to find any trace of scribing or scars.

Set Iron Pipe with Brass Cap Mkd: County Surveyor's S14 | S13  
Office, 1961 S23 | S24 T26SR6W

New BT's: 20" W.Oak N.21°W. 55.3 ft. Mkd: T26S R6W S14 CS BT.  
9" W.Oak S.65°W. 36.6 ft. Mkd: T26S R6W S23 CS BT.  
9" B.Oak S.42°E. 44.5 ft. Mkd: T26SR6W S24 CS BT.  
7" W.Oak N.31°E. 18.7 ft. Mkd: T26S R6W S13 CS BT.

164  
Found O.K.  
MAY 1964  
M.E.C.  
L.L.

88

1/4 Section Corner to Sections 13 and 14.  
Found - Both Orig. BT's: 14"; now 28" W.Oak N.77 1/2°E. 301.6 ft.,  
previously opened, shows good scribing "1/4 S".

Orig. 15", now 30" W.Oak S.59 1/4°W. shows good scar. I do not open.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961

New BT: 10" W.Oak bears S.37°E. 63.9 ft. scribed 1/4 S14/S13 T26S R6W.

Note - Compass Needle is in error at corner about 4° off. NE BT reads  
N.81°E., should be N.77 1/2°E. Needle reads OK from BT's. to corner.

RE-RECORDED  
SEE CORNER NO. #186

89

1/4 Corner to Sections 27 and 34.  
Found - 5/8" I. Rod at Corner & now 12" W. Oak N. 4°W. 12.7 ft.,  
shows good scribing.

Now 8" Oak Snag S.46°W. 13.9 ft., shows good scribing. 153

New BT: Rescribe old B.T., now 30" W. Oak: 1/4 S27 CS BT. N.38 1/2°E. 41.4 ft.

FD. O.K. June 24 M.E.C. C.S. 52/87

James W. Byron, Deputy  
Dale McFarland  
J. Powell  
August 11, 1961  
C.S. File No. 52/87

Section Corner to Sections 28 - 27 - 33 - 34.  
Found - Mound of Stone at Corner & 10", now 16" W.Oak N.50°W. 47.0 ft.  
We open & find good scribing "2". REN#17

Also find S.W. BT. as recorded by Cole.

Set Brass Cap at Corner Mkd: County Surveyor's S28 | S27 T26S R6W  
Office, 1961 S33 | S34

New BT's: Rescribe, now 16" W.Oak N.50°W. 47.0 ft. T26S R6W S28 CS BT.  
10" W.Oak bears S.50 1/2°W. 67.3 ft. scribed S33 T26S R6W CS BT.  
11" W.Oak bears S.45°E. 101.3 ft. scribed S34 T26S R6W CS BT.  
7" B.Oak, Double, bears N.47°E. 68.5 ft. scribed S27 CS BT.

RE-RECORDED  
SEE CORNER NO. #188

FD. O.K.  
M 102-28  
D. STRAIN  
7/86

90

1/4 Corner to Sections 17 and 20.  
Found - Original BT., 13", now 24" B.O. S.57°E. 9.9 ft., shows good  
scribing on old face "1/4 S". Orig. N. BT. down. SEE M 28-29

Pipe set by Waters not found. REN#9

Set - Brass Cap at Corner Mkd: County Surveyor's 1/4 S17 T26S R6W  
Office, 1961 S20

Note - Corner under E. W. Fence.

New BT's: 14" Laurel bears S.24°W. 22.0 ft. scribed 1/4 S20 CS BT.

15" Laurel bears N.55°W. 18.7 ft. scribed 1/4 S17 CS BT.

RE-RECORDED  
SEE CORNER NO. #199

James W. Byron, Deputy  
D. McFarland - J. Powell  
For: Doug. Co. Park Dept.  
Oct. 26, 1961  
C.S. File No. 52/95 M 21 - 60

S. W. Corner D. L. C. No. 61. FD. OK 12/90 M 111-22  
Found - Now 34", dead, W. Oak N.17°W., not N.19°W. 157.1 ft. REN#8

Also find 1" I.R. with small flange on top & under surface 6".  
We open N.W. BT. & find scribe marks. S.W. BT. not found.

92A