

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Set - Brass Cap alongside I.R. & Mark: SW DLC 61 T 26 SR 6 W County  
(continued) New Bearing Trees: Surveyor's Office 1961.  
24" B.Oak bears S.74°E. 37.5 ft. scribed SW CL 61 CS BT.  
17" R.Fir bears N.86°W. 4.6 ft. scribed SW CL 61 CS BT.  
Note - Corner is in Channel of Creek.

C. S.  
File  
No.  
52/95

N. E. Corner D. L. C. No. 43. 93

Reset Cap from reference Hubs set August 15, 1961  
Corner falls at foot of fill on East side of County Road.  
A  $\frac{3}{4}$ " Rod (R. of W. Pin) - W. Side of Road - Eng. Sta. 131+79.93-  
P.C. bears N.53 $\frac{1}{2}$ °W. 67.5 ft.  
A  $\frac{3}{4}$ " Rod (R. of W. Pin) - W. Side of Road - Eng. Sta. 131+09.12-  
P.C. bears S.70 $\frac{1}{2}$ °W. 80.8 ft.  
A  $\frac{3}{4}$ " Rod (R. of W. Pin) E. side of Road - Eng. Sta. 131+09.12 - P.T.  
bears S.1°W. 51.85 feet. REN'S # 28455

Milo E. Godfrey  
Vernon Tracy  
Mike Stone  
July 30, 1962  
C.S. File 52/87

Sec. Cor. to Secs. 4 & 5, T26-6W. & Secs. 32 & 33, T25-6W. 94  
Found - 32" W.Oak Snag S.52°E. 117.5 ft., with scribe marks.  
Black Oak Stump S.4°W. 15.2 ft., rotted, no scribing.  
25" White Oak N.83°W. 112.9 ft., showing good scar.  
20" White Oak N.84°E. 53.5 ft., shows faint scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W S32|S33  
Office, 1963 T26S R6W S 5|S 4  
New BT's: 16" Bl.Oak bears S.49°E. 69.3 ft. Mkd: T26S R6W S4 CS BT.  
13" W.Oak bears S.29°W. 29.3 ft. Mkd: T26S R6W S5 CS BT.  
14" W.Oak bears N.39°W. 10.6 ft. Mkd: T25S R6W S32 CS BT.  
15" W.Oak bears N.57°E. 26.5 ft. Mkd: T25S R6W S33 CS BT.

$\frac{1}{4}$  Corner to Section 33, T25-6W. & Sec. 4, T26-6W. 95  
Found - 20" Bl. Oak Snag S.2°W. 16.5 ft. with good scribe.  
29" Bl. Oak N.27°W. 17.8 ft., down, dead & rotting. Didn't open.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S33  
Office, 1963 T26S R6W S 4  
New BT's: 14" D.Fir bears S.70°W. 23.3 ft. Mkd:  $\frac{1}{4}$  S 4 CS BT.  
16" D.Fir bears N.55°W. 14.4 ft. Mkd:  $\frac{1}{4}$  S33 CS BT.  
This cor. is 1.5 ft. S. of E-W fence line & approx. 165 ft. E.  
of top of ridge which bears N. & S.

Milo E. Godfrey's Crew  
Vernon Tracy and Mike Stone  
February 1963  
C.S. File No. 49/123

Sec. Cor. for Sections 33 & 34, T25-6W. & Secs. 3 & 4, T26-6W. 96  
Found - Following BT's. as recorded by H. L. Eppstein in 1930: REN # 25  
24" B.Oak S.64 $\frac{1}{2}$ °W. 7.5 ft., down, rotting, no scribing left.  
24" Fir Stump N.19°E. 22.4 ft., shows good scar.  
20" Fir Stump S.12°E. 9.0 ft., opened & fd. scribe visible.  
30" Fir N.56 $\frac{1}{2}$ °W. 25.0 ft., showing good scar.  
No trace of Orig. BT's. # 172

Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W S 33 | S 34  
Office, 1963 T26S R6W S 4 | S 3  
New BT's: 14" D.Fir bears S.85°W. 15.6 ft. Mkd: T26S R6W S4 CS BT.  
7" D.Fir bears N.46°E. 64.5 ft. Mkd: S34 CS BT.  
8" W.Oak bears S.35°E. 39.3 ft. Mkd: T26S R6W S3 CS BT.

$\frac{1}{4}$  Corner to Sec. 35, T25-6W. & Sec. 2, T26-6W. 97  
Found - 46" Fir Stump N.32°E. 30.4 ft. Cut open & found one scribe  
mk. "1". Tree had been opened previously & grown over  
again. Balance of upper face rotted.  
No trace of Cedar to S. E.  
Note - Corner falls in E. & W. fence line 33 ft. west of small stream.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S35  
Office, 1963 S 2  
New BT's: 15" W.Fir N.48 $\frac{1}{2}$ °E. 66.2 ft. Mkd:  $\frac{1}{4}$  S35 CS BT.  
9" D.Fir S.58°W. 78.5 ft. Mkd:  $\frac{1}{4}$  S 2 CS BT.

June 27, 1963

RE-RENEWED, SEE CORNER NO. #172