

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KOBE-CHAPMAN CO., EUGENE, ORE. 21861

Milo Godfrey, Deputy
Wm. Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File No. 52/87

Section Corner to Sections 3, 4, 9, 10

118

Found - Stump hole & rotten, down Oak S 27 3/4° E 71.9 ft.-opened and found good reverse scribing on old slab.
Stump hole & rotten remains of old Oak S 71° W 25.7 ft.-all reverse scribing visible on old slab.
Rotten remnants of old Madrone N 37° W (not N 70 1/2° W) 28.4 ft.-overgrowth of 2 old axe scars found, but no scribing.
No trace found of original N.E. tree.

Set - Brass Cap Mkd: "County Surveyor's Office 1964 T 26 SR 6 W
S 4 | S 3 "
S 9 | S 10

New BTs: 18" Doug. Fir S 10° W 58.1 ft. Mkd: "T 26 SR 6 W S 9 CS BT."
17" Doug. Fir N 61° W 17.5 ft. Mkd: "T 26 SR 6 W S 4 CS BT."
11" Doug. Fir N 11° E 21.4 ft. Mkd: "T 26 SR 6 W S 3 CS BT."
14" Doug. Fir S 50° E 2.0 ft. Mkd: "T 26 SR 6 W S 10 CS BT."

1/4 Corner to Sections 3 & 10

119

Found - 1" iron pipe set by Evans in 1959. (Ren. # 40)
34" Fir N 9° E 4.5 ft. Mkd. by Evans (Bark scribed "T 26 R 6
1/4 S 3 CS BT")
Rotten Laurel stump S 70 1/2° E 20.5 ft.-now markings visible at present.
No trace of N.W. tree found.

New BTs: 13" Doug. Fir S 53° E 50.4 ft. Mkd: "1/4 S 10 CS BT".
Posted yellow tag along trail on top of ridge 600 ft. South of corner.

1/4 Corner to Sections 15 & 16

120

Found - Stump hole & rotted down Oak N 13° W 66.0 ft.-shows overgrowth of upper & lower scars. faint reverse scribing visible on upper scar-portion of "S".
Stump hole & center portion of white oak S 29° E 68.0 ft.-outside rotted away-no marks visible.

Set - Brass Cap mkd: "County Surveyor's Office 1964 T 26 SR 6 W
1/4 S/S "
16/15

New BTs: 15" Incense cedar S 20° W 4.4 ft. Mkd: "1/4 S 16 CS BT".
18" Madrone N 54° E 24.2 ft. Mkd: "1/4 S 15 CS BT".
Corner lies 3.5 ft. West of N & S fence line.

1/4 Corner to Sections 15 & 22

121

Found - White Oak (now 32" diam.) S 22 3/4° W 224.4 ft. Chopped open lower scar & found good scribing "B". (ren. # 14)
Black Oak (now 30" diam.) N 19 1/2° W 194.0 ft. Shows good scar. Did not open.

Did not find iron pipe set by Cole in 1921. Rocks from mound widely scattered. Could not tell where mound had been.

Set - Brass Cap Mkd: "County Surveyor's Office 1964 T 26 SR 6 W
1/4 S/15"
S/22

New BTs: 17" white oak N 45° W 25.3 ft. Mkd: "1/4 S 15 CS BT."
16" black oak S 55° E 6.0 ft. Mkd: "1/4 S 22 CS BT."
A 3-way fence corner. Fences East, West & South-bears S 48° W 20ft.
Both original BTS alive & in good condition.
Corner is directly on top of ridge.