

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Corner to Sections 21 and 22 122
Found - $\frac{3}{4}$ " iron pipe at corner, also rotten scribed stake lying on
ground. (Ren. # 64)
25" white oak E. 459.8 ft. alive & in good condition-scar plain.
The N.W. tree is now down.
Drive auto cam shaft alongside $\frac{3}{4}$ " pipe at corner.
New BT: 13" white oak S 85° W 341.5 ft. Mkd: " $\frac{1}{4}$ S 21 CS BT".
This tree is on top of small hill.

Center $\frac{1}{4}$ Corner of Section 3. 123
This corner found by M. E. Godfrey, June 10, 1964. Godfrey found
axle (with flange) as set by Evans in 1949. See Map File M10-25. #195
This corner not posted in 1949.
Concrete barn foundation still OK. No trees available for scribing.
Corner is in garden 1.5 ft. N. of fence corner. Fences South & West.

N. W. Corner D. L. C. # 42 124
Found - Black Oak (now diam.) S. 24° W 75.7 ft. Portion of scribing
visible in now completely healed scar. #180
S.E. BT. Mkd. in 1956 bulldozed into large brush pile. No
evidence found of where it had stood. Did not find pipe
set by Cole, nor our brass cap set in 1956. (Ren. # 19 & # 61)
Set - New iron pipe with brass cap Mkd: "County Surveyor's Office
1964 T26 SR 6 W N.W. D.L.C. 42 F".
Did not find either of Cole's BTs. nor either original BT.
New BT: 20" B. Oak S 15° E 30.5 ft. Mkd: "NW DLC 42 CS BT"
A N. & S. fence line is 40 ft. west of corner (Dist. paced)

Witness Corner to Sections 28, 29, 32, 33. 125
Found - Brass Cap set by J. Byron 1956. (Ren # 69) #189
24" Doug. Fir S 43° W 125.9 ft. Still in good condition. Scar
healed over.
The Black Oak to the N.W. is dead & down.
New BT: 8" B. Oak N. 73° W 113.2 ft. Mkd: "W.C. S28 CS BT."

Section Corner to Sections 16, 17, 20 & 21. 126
Found - $\frac{1}{2}$ " iron rod set by Cole in 1921. (ren. # 7)
W. Oak (now 24" diam) N. $42\frac{1}{4}^{\circ}$ E. 122.3 ft. Both axe scars plainly
visible. Tree alive, good condition.
Badly rotted oak stub N. 18° W. 224.2 ft. Portion of a scribe
mk. visible on surface.
Did not set brass cap.
New BTs: 10" W. Oak N. 60° W. 32.0 ft. Mkd: "T 26 SR 6 W. S 17 CS BT"
11" W. Oak S 24° W 76.4 ft. Mkd: "T 26 SR 6 W S 20 CS BT"
15" W. Oak S. 27° E. 102.5 ft. Mkd: "T 26 SR 6 W S 21 CS BT"

Most Westerly NW Corner. DLC # 61 127
Found - Old Oak, down & badly rotted, N. 55° E 77.2 Ft. Kiked open &
foundslab with reverse scribing "BT" Legible. More visible.
Set - Brass Cap Mkd. "County Surveyor's Office 1964 T 26 SR 6 W
NW DLC 61 " "
New BTs: 18" B. Oak NW 1.5 ft (to center) Mkd: "NW DLC 61 CS BT"
13" W. Oak S. 30° E 10.5 ft. Mkd: "NW DLC 61 CS BT"
A N & S fence line bears West 3.0 ft.

Milo Godfred, Deputy
Mike Stone
June, 1964
C. S. File No. 52/87

FD. OK 4/85
D. BENTZ
M 98-51
M102-24