

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

New BTS: 11" W. Oak N. 73° E 18.0 ft. Mkd: "1/4 S 18 CS BT"  
6" Madrone S. 27° E. 9.7 ft. Mkd: "1/4 S 17 CS BT"  
Corner is in E & W fence line, approx. 125 ft East of foot of hill.

Section Corner to Sections 8, 9, 16, & 17.

133

Found - Rock at corner (ren. # 33)

Fir Stump (24" when mkd.-not 4") N. 5 3/4° E 21.9 ft. Fd. scribing "S9"

Fir stump S. 56 1/2° W. 49.5 ft. shows good scar.

B. Oak (now 15" diam) S. 70 1/4° E. 21.4 ft. Shows very good scar. Tree partly uprooted & down, but still alive.

Doug. Fir (now 33" diam) N. 58° W. 70.5 ft. (not 75.0ft) 2 good aze scars visible.

Remnant of old oak N. 73 1/2° W 16.5 ft. still in existence, original BT.

Set - Brass Cap Mkd: "County Surveyor's Office 1964 T 26 SR 6 W

S 8 | S 9  
S 17 | S 16

NewBTs: 11" Doug. Fir N. 78° E. 38.5 ft. Mkd: "T 26 SR 6 W S 9 CS BT"  
8" Doug. Fir S. 82° E 38.3 ft. Mkd: "T 26 SR 6 W S 16 CS BT"  
11" B. Oak S. 69° W. 16.4 ft. Mkd: "T 26 SR 6 W. S 17 CS BT"  
NW tree still good.  
Corner is 4 ft E. of N & S fence.

1/4 Corner to Sections 8 & 9.

134

Found - Old Black Oak N. 33° W. 15.8 ft. This tree was opened many years ago & entire center rotted away. Small fragments of old face found, some showing definite axe mks. No scribing found.

Portion of root system (above ground) with black oak growing out of one side. Stump hole visible S 62 1/2° E 8.6 ft.

From this evidence set corner.

Set - Brass Cap at corner mkd: "County Surveyor's Office 1964

T 26 SR 6 W 1/4 S 1 S  
8 1 9

New BTs: 15" Doug. Fir N. 18 1/2° W 13.3 ft. Mkd: "1/4 S 8 CS BT" (above fence)  
14" W. Oak N. 30° E. 23.7 ft. Mkd: "1/4 S 9 CS BT"  
An iron rod (1" diam.) apparently set for corner bears N. 44° E. 5.6 ft.  
An E & W fence line is 12.4 ft. North of corner.

Wit. Cor. 1/4 Section Corner Sections 7 and 8.

135

Found - 3/4" Iron Pipe (with elbow), See Renewals #21 & #44.

Wit. Cor. 13.5 ft. S. 46 1/2° E. of 1/4 Corner.

16" W. Oak S. 32 1/4° E. 30.0 ft. from 1/4 Corner, shows good scars.

Maple BT. to N. W. is now gone.

New BT's: Doug. Fir S. 41° W. 36.5 ft. from Wit. Cor. Mkd: WC 1/4 S 7 CS BT.

Note - 1/4 Corner is in County Road.

- COR. REF. OUT - EOE ROAD MARK - J. POWELL - 4/6/73

1/4 Corner to Sections 9 and 16.

136

Found - 40" Pine Snag N. 64 1/4° E. 70.0 ft., Dead many years & badly rotted, except for face which is pitched over, good scribing "1/4 S".

Stump Hole with remnants of old Oak Stump S. 10 1/2° E. 28.4 ft., (43 lks. instead of 34 lks.)

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S R6W 1/4 S 9  
Office, 1964 S16

New BT's: 10" Madrone S. 72° W. 19.0 ft. Mkd: 1/4 S16 CS BT.

18" D. Fir N. 71 1/2° W. 32.7 ft. Mkd: 1/4 S 9 CS BT.

Note - Corner lies on S.E. slope of hill approx. 200 ft. N.W. of Valley.

Milo E. Godfrey, Dep. Surv.  
Wm. Stoffel, Mike Darby, Mike Stone  
July, 1964  
C. S. File No. 52/87

Milo E. Godfrey, Deputy  
Wm. Stoffel - M. Darby & M. Stone  
July 1964  
C. S. File No. 52/87

SEE CORNER NO. 174