

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21887

FDOK JUNE-86
By BENTZ TM 102-16

143

$\frac{1}{4}$ Corner to Sections 35 and 36.

Found - 24" W. Oak S. $20\frac{1}{2}^{\circ}$ E. 112.2 ft., opened & found good scribng. Northwest tree not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T26S R6W $\frac{1}{4}$ S 35/S 36

New BT's: 10" W. Oak N. 30° W. 16.5 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
13" W. Oak N. 37° E. 18.3 ft. Mkd: $\frac{1}{4}$ S36 CS BT.

fd. bc 9/90
1990-0053

144

Section Cor. to Secs. 35 & 36, T26-6W. & Secs. 2 & 1, T27-6W.

Found - 20" W. Oak N. $3\frac{1}{2}^{\circ}$ W. 62.7 ft. Cut open & found scribing "S" on partially rotted face.

26" W. Oak N. $15\frac{1}{2}^{\circ}$ E. 72.6 ft., both upper & lower scars show very plainly.

30" W. Oak S. $60\frac{1}{2}^{\circ}$ W. 137.9 ft., no scars visible.

Bl. Oak, uprooted & dead several years, S. 52° E. 114.2 ft., Did not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's S 35 | S 36 T26S
Office, 1964 R6W S 2 | S 1 T27S

New BT's: 14" W. Oak S. 47° E. 15.0 ft. Mkd: T27S R6W S1 CS BT.

12" W. Oak S. 49° W. 26.2 ft. Mkd: T27S R6W S2 CS BT.

6" I. Cedar N. 64° W. 33.2 ft. Mkd: S35 CS BT.

6" W. Oak N. 52° E. 16.8 ft. Mkd: T26S R6W S36 CS BT.

Milo E. Godfrey, Deputy Co. Surv.
Wm. Stoffel and Mike Stone
July 1964 - August 1964
C. S. File No. 52/87

145

Meander Corner Sections 32 & 33. (Right Bank South Umpqua)

Found - 30" Old Pine Stump N. 60° W. 49.5 ft., opened & found good scribing "R6" & "S".

No trace of S. E. tree found.

Location for Meander Corner falls on bedrock in river channel and would be under water except in time of low water.

Set - Wit. Cor. on high bank 60 ft. N. of Meander Corner.

Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T26S R6W W.C. M. C. S 32/S 33

60 feet South to Corner.

New BT's: 16" Bl. Oak S. 80° W. 50.3 ft. Mkd: WC MC S 32 CS BT.

15" W. Oak S. 75° E. 3.5 ft. Mkd: WC MC S 33 CS BT.

Witness Corner is alongside Electric Service (on tree) for Motor & Irrigation Pump.

146

$\frac{1}{4}$ Corner to Sections 31 and 32.

Found - Old B. Oak, nearly dead, N. $25\frac{1}{4}^{\circ}$ W. 399.3 ft., fd. old axe marks & portions of overgrowth against old face, center badly rotted & burned. Didn't find any scribing. See affidavit of Mr. Ernest Trussell on Field Notes in file.

Did not find other Orig. BT., nor tree marked by Summers in 1920, 686 (Ren. #2)

Note - Position for corner falls in pear orchard.

Set - $\frac{3}{4}$ " Iron Rod 12" below ground surface. From corner a Pear Tree (not marked) bears S. 54° E. 5.7 feet.

Set - Wit. Cor. 150 ft. North of $\frac{1}{4}$ Corner.

Iron Pipe with Brass Cap Mkd: County Surveyor's Off. 1964

T26S R6W W.C. 150 ft. S.

to $\frac{1}{4}$ S31/S32.

Power Pole at entrance to Singleton Park (Pole marked "Copco B9201 27) bears N. 32° E. 30.9 ft.

New BT: 34" D. Fir (in park) N. 11° W. 89.5 ft. Mkd: WC $\frac{1}{4}$ S31 CS BT.

With Cor. is in edge of gravel at South edge of County Road.

147

$\frac{1}{4}$ Corner to Sections 16 and 21.

Found - Mound of Rock set by Cole, (See Ren. #12.)

22" Bl. Oak S. $35\frac{1}{2}^{\circ}$ W. 11.0 ft. Opnd. & fd. gd. scb. (Cole's BT.)

Bl. Oak N. $35\frac{1}{2}^{\circ}$ W. 85.1 ft., dead & down. (Orig. BT.)

Stump Hole & Remnants of very lgr. Oak S. 22° W. 176.2 ft. (Orig.)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T26S R6W $\frac{1}{4}$ S16
S22

(continued next page)