

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 6 R. W. W. M.

KDRE-CHAPMAN CO., EUGENE, ORE. 21981

171

1/4 Corner Sections 3 and 4  
 Found - 15" D. Fir, N.5°W, 25.6 ft. Shows pitched over scribing.  
 12" D. Fir, N11°E, 50.0 ft. Shows pitched over scribing.  
 Brass cap set for wit. cor. of 4/3. This brass cap was stamped backwards. I restamped sections. Ren. #117  
 Note - N.W. and N.E. bearing trees are to be out. Also a lot of clearing will be done.  
 Set - Remarked brass cap County Surveyors Office T 26 S R 6 W W.C.  
 25' south to S | S  
 1/4 4 | 3  
 1964

John M. Powell  
 J. Heritage  
 C.S. 52/87  
 11/29/72

172

Section corners for Secs. 3 & 4; and Secs. 33 & 34 of T26 R6  
 Found- Brass cap and bearing trees as noted in Ren. 96  
 This corner is now located at the toe of a slide area. The brass cap and all bearing trees except two have been subjected to movement in the slide. Measurements from the two undisturbed bearing trees:  
 A 7" now 8" D. Fir bearing N.46°E., 64.5 ft, with scribing "S34 CS BT" visible.  
 An 8" now 10" W. Oak bearing S.35°E., 39.3 ft, well-healed, are in agreement with each other and indicate the brass cap has moved approx. 4 ft. downhill.  
 Based on the measurements from the two undisturbed BT's as noted previously, we remove the brass cap & reset it at a witness cor. 100 ft. east of the true cor.  
 We remark the brass cap to read as follows:  
 County Surveyor's Office 1974 T26S Witness Corner S33 | S34 R S4 | S3 W  
 100 ft. west to Cor. T26S  
 1974  
 1963

Gary Langlitz  
 Pete Earle  
 CS 56/51  
 5-6-74

FD OK 5-91  
 M113-11

We mark the following BT's for witness corner:  
 18" D. Fir bears S.83°W., 19.2 ft. scribed: "WC T26S R6W S3 CS BT"  
 7" W.Oak bears N.52°E., 26.7 ft scribed: "WC T25S R6W S34 CS BT"  
 10" W. Oak bears S.79 1/2°E., 32.8 ft scribed: "WC S3 CS BT"  
 15" Madrone bears S.15 1/2°W., 82.4 ft., scribed "WC T26S R6W S3 CS BT"  
 Note- This witness corner lies approx. 30 ft. south of a dirt road.  
 Declination: 20° East

5-6-74

173

Section Cor. for Sec. 6; and Sec. 1 of T26-7; Sec. 36 of T25-7 and Sec. 31 of T25-6.  
 Set - Brass cap on a 1" I.P. on the inside edge of a dike of a farm pond approx. 15' from lower edge of a steep bank between field and lower field terrace.  
 BT - Only one tree close to corner which I scribed:  
 42" Oak, bears N.61°W., 46.0 ft. scribed S36 BT.

Glenn Baughman  
 for Bill Escalle  
 October 1974  
 M 49 - 76

RE-NEWED, SEE CORNER NO. #177

174

1/4 Corner for Secs. 7 and 8  
 This Corner reset from reference monuments as shown on the attached notes dated 4/5/73. At this time, we find no evidence of the orig. corn. or the witness corner, or their accessories. Ren. #135  
 At the true point for the 1/4 corner approx. 2.5 ft. westerly of the centerline of County Road #6, we drive a bridge spike, flush with the asphalt pavement from which we mark the following bearing tree and note the following bearing objects:  
 A 15" White Oak, bears S.69 1/2°E., 80.7 ft. scribed "1/4 S 8 CS BT"  
 An iron rod with aluminum cap attached marked: "Douglas County Rd. Dpt. R-W 35" at Engineers station 261+71.71 35 ft. left of centerline at the westerly R/W fence of Co. Rd. #6, bears S.55°W., 161.17 ft.  
 An iron rod with aluminum cap attached marked: "Douglas Co. Rd. Dpt R-W 50" at Engineers station P.O.C. 264+50 50 ft. left of the centerline of Co. Rd. #6 and at the westerly R/W fence bears N.23 1/2°E., 128.00 ft.  
 Compass declination setting: 20° East

Gary L. Langlitz, Surveyors Off.  
 Peter L. Earle  
 12/30/74  
 C.S. 57/12

JAN 15