

Douglas County Surveyor's Record of  
Government Corners Renewed

26 T. S. 7 R. W. W. M.

F.C. Frear  
July 15, 1920  
C.C. Long Wit.  
P. D. Wolford

COR. SECS. 11, 12, 13 and 14  
Reestablished from old B.T.'s which I remarked and set  
a 1" x 30" Iron Pipe for corner. **SEE CORNER NO. 21** 1

COR. SEC. 14, 15, 22 and 23.  
Reset from old stump and one tree. No scribe marks visible  
Drove Iron Pipe and marked the following trees 2  
Fir 36" dia. bears S.63 $\frac{1}{2}$ °W., 46.1 ft. 63  
Fir 30" dia. bears N.18°W., 27.0 ft.  
Fir 30" dia. bears S.42 $\frac{1}{2}$ °E., 22.7 ft.  
Fir 12" dia. bears East 31.9 ft.

CORNER SECTION BETWEEN 15, 16, 21, and 22.  
Reset from one O.B.T. others gone. Drove an Iron Pipe  
and marked the following trees 3  
Hemlock 24" dia. bears N.18°E., 46.2 ft. 66  
Hemlock 20" dia. bears N.57 $\frac{1}{2}$ °W., 24.0 ft.  
Fir 36" dia. bears S.50°W., 48.5 ft.

CORNER BETWEEN 15 and 22.  
Reset from 1 O.B.T. and one stump. Drove an Iron Pipe  
and marked the following trees 4  
White Fir 18" dia. bears S.41°W., 23.7 ft.  
White Fir 10" dia. bears N.54°E., 27.5 ft. 65

COR. BETWEEN 15 and 16.  
Reset midway between section corners to North and South.  
Drove Yew wood Stake and marked the following trees 5  
Fir 14" dia. bears N.46°E., 17.4 ft. 64  
Fir 14" dia. bears S.27°E., 40 ft. at 25° slope  
Corner on steep rocky hill side.

CORNER SECTION BETWEEN 13, 14, 23 and 24  
Reset from one Original Bearing Tree. Drove Iron Pipe  
8" below ground in Prune orchard and 63 ft. South of fence 6  
Marked the following trees:  
Black Oak 12" dia. bears N.16 $\frac{1}{2}$ °W., 159.8 ft. 42  
Black Oak 18" dia. bears N.36 $\frac{1}{2}$ °E., 176.5 ft.  
No other trees suitable.

CORNER BETWEEN 13 and 14  
Reset from two original B.T.'s both badly rotted. Drove  
an Iron Pipe and marked the following trees: 7  
Black Oak 18" dia. bears N.61°W., 45 ft. 39  
Black Oak 18" dia. bears N.18°E., 39.2 ft.

CORNER BETWEEN 11 and 14.  
Reset from one original B.T. rotted. Drove an Iron  
Pipe and marked the following trees 8  
Fir 14" dia. bears S.43°W., 99.1 ft. O.B.T. 61  
Black Oak 18" dia. bears N.61°W., 119.5 ft.

SECTION CORNER FOR 10, 11, 14 and 15  
Reset from old 18" black oak called for as corner. Only  
stub of corner tree is left and B.T.s are gone. Marked new  
B.T.s as follows 9  
Black Oak 16" dia. bears N.68°W., 21 ft.  
Black Oak 24" dia. bears S.77 $\frac{1}{2}$ °W., 60.5 ft. 60  
Cedar 8" dia. bears S.57 $\frac{1}{2}$ °E., 23.5 ft.  
Laurel 4" dia. bears N.71°E., 35.0 ft.

SEC. COR. BETWEEN 10 and 15.  
Reset from one original bearing tree and one stump  
drove an Iron Pipe and marked the following trees. 10  
Fir 30" dia. bears S.50°W., 28.0 ft. 62  
Fir 30" dia. bears N.9 $\frac{1}{2}$ °E., 28.6 ft.

G. C. Stewart Deputy County Surveyor  
December 1, 1922  
Wit. C. Crocker, Blumberg, Will Long, Carpenter

C.S. Vol. 3, Page 13, N.E. 8