

Douglas County Surveyor's Record of
Government Corners Renewed

26 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

35

1/4 Section Corner to Sections 35 & 36.
Found - Orig. 12", now 24" W. Oak, S.78°E. 12.2 ft., previously
opened, shows good scribing "1/4 S".

No trace of Original N. W. BT.

Milo Godfrey states that he was with Richardson about 1949 and they
opened the S.E. BT., also drove a rod at Corner which we do not find.
They scribed new BT's which we record at this time. Richardson's
work was not recorded.

Set 3/4" Iron Rod at Corner.

15" W. Oak N.56°E. 84.8 ft., shows good scars. I do not open.

16" W. Oak N.52°W. 43.2 ft., I open & find good scribing.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
C. Putnam
June 26, 1959
C. S. File No. 49/129

Section Corner to Sections 25, 26, 35, & 36.

Found - Brass Cap at Corner Mkd: County Surveyor's Office

T26S R7W	26	25
	35	36

Orig. 12", now 20" Oak Snag S.83°E. 40.9 ft., shows good
scribing "S36".

No trace of Other Original BT's. found.

I find BT's. thus, probably scribed at time Cap was Set:

Now 14" R. Fir bears N.72°E. 4.6 ft. shows some scribing.

Now 10" Laurel bears S.23°E. 12.9 ft. shows good scribing "S36 CS".

Now 11" R. Fir bears S.49°W. 33.0 ft. shows good scar.

I do not find N. W. BT.

I scribe 12" R. Fir N.73°W. 39.0 ft. S26 T26S R7W CS BT.

FD. OK 10/6/61
K. DeGant M 89-51
FO. OK 12/9/61 D. Beatz
MLR 1992-0012

36

Section Corner to Sections 3, 4, 9 and 10.

Found - Orig. 6", now 32" W. Fir S.35°E. 29.7 ft., center rotted
but shows good reverse scribing "2 S W Q".

Orig. 10", now 34" W. Fir S.4°W. 16.5 ft., now down,
center rotted but shows parts of old face, no
scribing found.

No trace of Orig. N.W. or N.E. BT's.

Set Brass Cap at Corner Mkd:

S 4	S 3
S 9	S 10

 T26S R7W County Surveyor's
Office, 1959

Note - I find Steel Post said by Neilson to be Boyer's Corner
bears S.71 1/2°E. 18.6 ft. from Brass Cap. Reset Steel Post
alongside Brass Cap.

New BT's: 14" R. Fir bears N.39 1/2°E. 27.8 ft. scribed S 3 T26S R7W CS BT.

6" W. Fir bears N.65°W. 30.8 ft. scribed S 4 CS BT.

12" W. Fir bears S.60°W. 31.6 ft. scribed S 9 T26S R7W CS BT.

32" W. Fir bears S.35°E. 29.7 ft. scribed S10 T26S R7W CS BT.

Sec. Cor. Sec. 1 & 12, T26S R7W, & Sec. 6 & 7, T26S R6W.

Found - 3 Orig. BT's: Orig. 14", now 24" W. Oak N.33°E. 25.1 ft.,
previously opened, no scribing found.

Orig. 20", now 30" W. Oak S. 8°W. 98.3 ft. I open &
find good scribing "1".

Orig. 10", now 16" B. Oak Snag S.26 1/2°E. 59.4 ft. I open
& find good scribing(reverse) "TWRS".

No trace of Orig. N.W. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S 1	S 6
R7W S12	S 7 R6W T26S

New BT's: 10" Dbl. W. Oak bears S.28°E. 24.9 ft. scribed S7T26S R6W CS BT.

8" W. Oak bears N.16°E. 35.2 ft. scribed S6 T26S R6W CS BT.

10" W. Oak bears N.49°W. 44.5 ft. scribed S 1 T26S R7W CS BT.

30" W. Oak bears S. 8°W. 97.0 ft. scribed S12 T26S R7W CS BT.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
August 26, 1959
C. S. File No. 49/129

James W. Byron
Milo Godfrey
Clete Putnam
Dec. 8, 1959
C. S. File No. 52/5
Map File M 16 -59

37

S. W. Corner D. L. C. No. 46.

Found - Orig. 16", now 48" B. Oak N.45°E. 196.0 ft. I open & find
good scribing "R7WS".

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S. W. Cer. D.L.C. 46 T26S R7W

New BT's: 5" W. Oak bears N.45°E. 27.5 ft. scribed CL 46 CS BT.

12" W. Oak bears N.11°E. 54.8 ft. scribed DLC 46 SW CS BT.

James Byron
Milo Godfrey
Clete Putnam
May 4, 1960
C. S. 49/129

39