

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 S T. S. R 7 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

N. E. Corner D. L. C. No. 42. 40

Found - 18" x 18" x 36" Stone, above ground, chisled on West face
CL 41 T26S R7W.

Base of old Oak Stump, center rotted, no scribing, N.37°W.
81.8 ft., record N.40°W. 81.8 ft.

See Statement in File by Stanley Long regarding this
B.T. and Corner Stone.

New BT: 18" W. O. bears N.87°W. 97.8 ft. scribed on south
face S.E. Cl 41 N E CL 42 CS BT. All scribing
in one blaze.

Statement by Long - I, Stanley Long, state that I have known this
Rock to be a D.L.C. Corner. Also, I remember
the orig. I remember this corner and B.T.
about 30 years ago.

FOUND M 46 - 64
RE CL 3/45 - W. BARNES - C.S. 58/40

N. E. Corner D. L. C. No. 46. 41

Note - N. E. Corner of D.L.C. is close to new house, so I set
Witness Corner 88 feet West.

Set Brass Cap at Witness Corner Mkd: Wit. Co. 88' East to NE Cor.
DLC 46 T26S R7W.

This Corner Set from BT., now 48" B. Oak, recorded by Briggs,
1892, S.35°W. 132.0 feet. I open & find good 500 REN. #15
scribing.

New BT's: 34" W. Oak bears N.69°W. 5.0 ft. scribed WC NE
DLC46 CS BT.

14" R. Fir bears S. 5 1/2°W. 34.5 ft. scribed WC NE
DLC46 CS BT. 4104

Section Corner to Sections 13 - 14 - 23 - 24. 42

Found - 1/2" Iron Pipe at Corner & N.E. BT. as recorded by Stewart
N. W. Bearing Tree gone. REN #6

Set Brass Cap at Corner Mkd: County Surveyor's

S14	S13
S23	S24

 T26S R7W
Office, 1960

New BT's: 30" R. Fir bears N.59°W. 109.2 ft. scribed S14 T26S R7W CS BT

7" Laurel bears S.88°E. 167.6 ft. scribed S24 CS BT.

12" W. Oak bears N.39°E. 166.4 ft. scribed S13 T26S R7W CS BT.

1/4 Section Corner to Sections 10 and 11. 43

FD OL PER PIESKE
M106-25 5-83

Found - Orig. 24", new 30" Oak Stump N.35°W. 106.3 ft., most
of center rotted but I do find small section of
old face that shows reverse scribing "T".

2" Iron Pipe at Corner.

No trace of Original N. E. BT. found

Set Brass Cap alongside 2" Iron Pipe marked: 1/4 S10/S11 T26S R7W
County Surveyor's office, 1960

New BT's:

7" W. Oak S.46°E. 13.5 ft. scribed 1/4 S11 CS BT.

18" W. Oak N.37°W. 31.0 ft. scribed 1/4 S10 CS BT.

RE RENEWED, SEE CORNER NO. #121

44

Meander Corner Lt. Bank

S13	S24
-----	-----

Found - Orig. 15", now 27" B. Oak N.72°W. 89.1 ft. I open
& find good scribing "T".

Orig. S. W. BT. gone.

Note - M.C. is in flood area. We set Witness Corner 40 ft.
West of true corner.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960
Wit. Cor. 40' East to M. C.

S13	S24
-----	-----

 T 26 S., R 7 W.

New BT's: 11" W. O. bears N.52°W. 12.0 ft. scribed WC MC S13 CS BT.

12" W. O. bears S.85°W. 41.0 ft. scribed WC MC CS S24 BT.

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
May 1960
C.S. File No. 49/129

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
Aug. 3, 1960
C. S. File No. 52/36