

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

56

$\frac{1}{4}$ Section Cor. to Sec. 30, T26-6W. & Sec. 25, T26-7W.
Found - $\frac{1}{2}$ " Galv. I.P. set by Eppstein, 1939. (See Ren. No. 20)
34" D.Fir N.87°E. 17.3 ft., shows very good scars.
42" Old Bl. Oak N.77°W. 79.2 ft., shows good scars.
Old Oak Stump N.76°E. 60.7 ft., old face rotted away, but
old axe marks visible.
New BT: 7" D.Fir West 25.4 ft. Mkd: $\frac{1}{4}$ S25CS BT.
Note - Eppsteins N.E. Fir BT. and Orig. N.W. Oak are still in good condition.
Corner Pipe is in N. & S. Fence Line, 15 ft. N. of fence Corner,
(Fences North, South & West.)

Aug. 11, 1964

Section Corner to Secs. 12 & 13, T26-7W. & Secs. 7 & 18, T26-6W. 57
Found - 20" D. Fir S.41°W. 52.0 ft., has been previously opened,
good scribing visible "13 T26 R7W".
27" Bl. Oak N.78 $\frac{1}{2}$ °E. 39.4 ft., shows fairly good scar.
25" Bl. Oak S.80 $\frac{1}{2}$ °E. 59.0 ft., shows very plain scar. #119
32" Bl. Oak N.23 $\frac{1}{4}$ °W. 210.0 ft., shows very good scar.
All trees alive & in good condition. See Ren. #47

Set - Brass Cap at Cor. Mkd: County Surveyor's T26S S 12 | S 7
Office, 1964 R7W S 13 | S 18 R6W

Blaze & Scribe one New BT. to replace Tree 210 ft. from Corner:
6" D.Fir N.15°W. 17.0 ft. Mkd: S12 CS BT.
Note - Corner is along N.W. Side of old Road or Trail along foot of Hill
Aug. 27, 1964

58

Sec. Cor. to Secs. 33 & 34, T26-7W. & Secs. 3 & 4, T27-7W.
Found - 18" Dead, White Oak, Old BT, N.47°W. 52.8 feet.
9" W. Oak N.37 $\frac{1}{2}$ °E. 129.5 ft., scars very plain. (See Ren. #49)
3-Way Fence Corner S.64 $\frac{1}{2}$ °W. 18 ft., fences E, W. & N.
Se Brass Cap, which had been taken out & thrown into the brush.
Set - Brass Cap at Cor. Mkd: County Surveyor's R7W T26S S 33 | S 34
Office, 1964 T27S S 4 | S 3
Set Both Caps at Corner, old cap buried.
New BT: 4" Madrone S.48 $\frac{1}{2}$ °E. 86.1 ft. Mkd: " S 3 CS BT".

Nov. 17, 1964

59

$\frac{1}{4}$ Corner to Sections 13 and 14.
Found - $\frac{1}{2}$ " I. Pipe in E - W Fence, as recorded in Ren. #7.
18", now 24", B.Oak N. 18° E. 39.2 ft., almost dead, shows
good scar. Open & find frag. reverse " $\frac{1}{4}$ ", face rotted away.
No trace of Orig. BT's. nor other BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R7W $\frac{1}{4}$ S 14 / S 13
(Set alongside I.Pipe & build Mound of Stone around Corner)
New BT's. 17" B.Oak S. 63° E. 24.6 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
7" B.Oak N. 25° W. 12.2 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
Note - This corner lies 50 ft. E. of top of ridge, course S.45°E. & N.45°W.

Sec. Cor. to Sections 10 - 11 - 14 - 15. 60
Found - Fragments of Stump of Orig. Corner Tree, See Ren. #9.
16", now 19", B. Oak N. 68° W. 21.0 ft., shows "CS" on unhealed
blaze, tree alive.
24" B.Oak S. 77 $\frac{1}{2}$ ° W. 60.5 ft., down & rotting. Open & find
"S1 CS B" reverse scribe.
8", now 20" Cedar S. 57 $\frac{1}{2}$ ° E. 23.5 ft., shows scar, Alive, Do not open
4", now 11" Laurel N. 71° E. 35.0 ft., shows faint scar, Alive, " "
No trace of Original BT's.
Set - Brass Cap at Cor. in E. - W. Fence Mkd: S 10 | S 11 T26S R7W
County Surveyor's S 15 | S 14
Office, 1966

New BT's: 5" D. Fir S. 34° W. 13.5 ft. Mkd: S15 CS BT.
Note - Corner lies 23.0 ft. West of Fence Corner, Fences N. - E. & W.

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Stone
C. S. File No. 52/87