

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
March 1966
C. S. File No. 54/23

Section Corner to Sections 15 - 16 - 22 - 21. 66
Found - 1959 Cadastral Brass Cap & I.P. recorded in Ren. # 3.
All BT's., down, dead or gone completely
New BT's: 8" W. Fir N. 44° E. 12.7 ft. Mkd: T26S R7W S15 CS BT.
9" Cedar N. 43° W. 21.2 ft. Mkd: T26S R7W S16 CS BT.
5" W. Fir S. 41° E. 11.5 ft. Mkd: S22 CS BT.
Note - This corner lies at fence corner, fences N. & E.
No tree available to S. W.

Sec. Corner to Sections 22 - 23 - 26 - 27. 67
Found - 1 1/2" I. Pipe as recorded in Ren. #16.
24", now 25", Fir Stump N. 62 1/2° E. 20.5 ft., find "BT" scribe.
14", now 16" W. Oak N. 80 3/4° W. 107 ft. Alive, "S" scribe visible
on partially healed blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T26S

S 22	S 23
S 27	S 26

 R7W
New BT's: 24" Cedar S. 22° E. 136.6 ft. Mkd: T26S R7W S26 CS BT.
12" B. Oak S. 7° E. 59.5 ft. Mkd: T26S R7W S26 CS BT.
No trees available in Sections 23 nor 27.
Note - Corner falls at 4-way fence corner, N.E.S.W.
Find rotted remains of possible Original S. E BT.

1/4 Corner to Sections 23 and 26. 68
Found - Orig. 6", now 16", B. Oak N. 45° E. 5.3 ft., Stump cut low in
B. Oak Stool piece of Oak Log that matches stump. We chop
out "BT" & notch. No trace other Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T26S

1/4 S 23
S 26

 R7W
New BT's: 10" D. Fir N. 7° E. 81.5 ft. Mkd: "1/4 S23 CS BT".
10" D. Fir S. 52 1/2° E. 150.8 ft. Mkd: "1/4 S26 CS BT".
Note - This corner lies at fence corner, fences, N.-E. & W. approx.
140 feet West of top of hill.

S. E. Corner D. L. C. No. 43. 69
Found - Orig. 8", now 19", B. Oak N. 10° W. 14.5 ft. Open & find
"C43 26S" scribe.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
T26S R7W S. E. Cor. / DLC 43
(Set B.C. 6" in the ground & build Mound of Stone)
New BT's: 9" D. Fir N. 81° W. 18.0 ft. Mkd: SE DLC 43 CS BT.
16" D. Fir S. 74° E. 31.9 ft. Mkd: SE DLC 43 CS BT.
Note - This corner lies on steep North slope.

North N. E. Corner D. L. C. No. 43. 70
Found - Rock 10"x6"x20" firmly set at very old fence corner.
Remnants of old Oak Post & 1/2 I. Rod set in top of post, Ren. # 19.
Fence Corner bears West 26.0 ft. from Rock to perpetuate Boyer's Ren.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
N. NE Cor. / DLC 43 T26S R7W
New BT: 7" B.Oak N. 73° E. 135.3 ft. Mkd: N NE DLC 43 CS BT.
Note - Corner lies at fence corner, fence N. & W. 26.0 ft. E. of
fence corner, fence W. E. & S.

Wit. Corner to 1/4 Corner to Sections 34 and 35. 71
Found - 2" I. Pipe 6" below surface of ground & BT's., as follows: Ren. #18
Orig. 12", now 26", W. Oak S. 16° E. 171.6 ft. Open & find
very faint reverse scribed axe notch.
No trace of BT's. recorded Ren. #18 nor other Orig. BT.,
Actual Corner falls in road. I. P. is 20 ft. East of Corner.
Set - Brass Cap alongside I.P. for Wit. Cor. Mkd: Co. Surv. Office, 1966
T26S R7W Wit. Cor.

1/4 S 34	S 35
----------	------

 20 ft. W. To Cor.
New BT's: 13" W. Oak N. 1° E. 134.8 ft. Mkd: W.C.

1/4 S35

 CS BT. 89
9" W. Oak S. 28° E. 39.0 ft. Mkd: W.C.

1/4 S35

 CS BT.
No trees available to West of Line.
Witness Corner falls in N - S. Fence on East Side of road, course N. & S.
& 35.6 ft. N. of fence corner, fences N. - S. and N. E.