

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 7 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Cor. for Secs. 30 & 31; and 25 & 36 of T26-8. 93
 Found - 1959 BLM Cadastral brass cap.
 1 18" D.Fir snag BT, scribing vis. bears N.14°E.,
 26.4 ft.
 10" D.Fir BT, face vis. bears S.16°E., 141.9 ft.
 12" D.Fir, face vis., bears S.11°W., 130.0 ft.
 26" D.Fir, windfall, scribing vis., bears N.83°W.,
 13.2 ft.
 22" D.Fir, scribing partially vis., bears N.43°W.,
 31.7 ft.
 23" D.Fir, snag, windfall, bears N.19°E., 31.7 ft.
 New BT - 12" hemlock, scribed "T26S, R8W S25 BT", bears N.45°W.
 105.4 ft.

1/4 Cor. for Sec. 31 and Sec. 36 of T26-8. 94
 Found - 1963 County surveyors brasscap. Ren. No. 55
 32" D.Fir snag. orig. BT, face rotted out, bears
 N.28°E., 17.2 ft.
 28" D.Fir, scribing vis., bears N.32°E., 32.6 ft.
 New BT - 6" D.Fir, scribed "1/4S S36 BT", bears S.86°W., 19.7 ft.
 Found 1/2" Aluminum pipe driven in beside brass cap.

Sec. Cor. Sec. 31 and Sec. 36, T26-8; Sec. 1, T27-8; Sec. 6, T27-7 95
 Found - 40" D.Fir stump, orig. BT, face badly burned, scribes
 "BT" vis., bears S.32°W., 54.8 ft.
 36" D.Fir stump, prob. orig. bT, badly burned and
 rotted, bears N.35°W., 59.0 ft. (rec. N.40°W.,
 61.4 ft.)
 36" cedar stump, prob. orig. BT. I re-scribed "T26S
 R7W S31 BT", bears N.20°E., 78.0 ft. (rec. 67.3 ft.)
 Set - Brass cap mkd. T26S, R8W S36; T26S, R7W S31; T27S, R8W
 S1; T27S, R7W, S6.
 New BT's - 6" D.Fir, scribed "T26S, R8W, S36 BT", bears N.64°W.,
 55.4 ft.
 8" hemlock, scribed "T27S, R7W S6 BT" bears S.62°E.,
 24.7 ft.
 8" D.Fir, scribed "T27S, R8W, S1 BT" bears S.34°W.,
 114.4 ft.

Center 1/4 cor. for Sec. 4 98
 Set - 1 1/2" Steel capped iron pipe from which:
 22" Cedar, S.52°E., 26.4 ft.
 12" Cedar, S.36°W., 33.0 ft.

1/4 Cor. for Secs. 4 and 5. 97
 Set - 5/8" Iron rod for 1/4 cor. from which:
 8" Cedar, N.33°E., 35.5 ft.
 18" Fir, West 7.4 ft.

Note: I find no remaining evidence of the remonumentation
 in the 1930's of the 1/4 corner to Secs. 4 and 5.
 Ren. No. 17 2.25/74

Section Cor. for Sec. 1; and Sec. 36 of T25-7; Sec. 31 of T25-6; 98
 Sec. 6 of T26-6.
 Set - Brass cap on a 1" I.P. on the inside edge of a dike of a farm pond #
 approx. 15' from lower edge of a steep bank between field and 107
 lower field terrace.
 BT - Only one tree close to corner which I scribed:
 42" Oak, bears N.61°W., 46.0 ft. scribed S36 BT.

1/4 Corner for Sections 1 and 12. 99
 Set - Brass cap.
 BT's - 14" White fir, bears N.52°W., 22.5 ft.
 11" Oak, bears S.35°W., 66.3 ft.
 14" Oak bears South 1.5 ft.

Shaner Engineering
 for Hub Lumber and Weyerhaeuser Company
 Dec. 21, 1973
 M 49 - 49

R. E. Stuntzner
 for Reservation
 Ranch, Coos
 Bay, OR.
 M 52 - 50
 Feb. 25, 1974

Glen Baughman
 for Bill J. Escalle
 October 1974
 M 49 - 76