

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 7 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Glenn Baughman
for Bill Escalle
October 1974
M 49 - 76

Gary L. Langlitz, Surveyors Office
John E. Nording
Jan. 27, 1975
C.S. 57/17

Witness Corner to
Center 1/4 Corner for Section 12.
Set - Brass cap.
BT's - 16" D. Fir, bears S.26°E., 160.0 ft.
20" Cedar, bears N.89°E., 112.6 ft.

W.C. 1/4 Corner for Secs. 35 and 36. 101

Found - 1" Iron pipe firmly set with brass cap attached and marked as described in Ren. #90, from which we find the following corner accessories:

A 5/8" Iron rod bears S.48°W., 46.0 ft.
A 16" W.Oak, now a stump, bears East 5.0 ft. with scribing "WC 1/4 S36 CS BT" visible.

We note a new bearing object as follows:
A 5/8" Iron Rod at Engineers Station 222+10 POC 35' left of the centerline of Co. Rd. #53 (Elgarose Rd.) (East side of road), bears S.3°E., 275.7 ft.

We note the two bearing trees are still in existence for the true 1/4 corner:
Orig. SE bearing tree with scribing "1/4S" visible
NW bearing tree reported in 1959 by Byron and Godfrey. Ren. #35

We do not search for any evidence of record monuments at the true 1/4 corner.
Note: The distance to the orig. SE bearing tree as shown in Ren. #35 is erroneous, it should be 112.2 ft. not 12.2 ft.

Compass declination setting: 20° east.

1/27/75

Steve Wetherell
BLM
C.S. 57/33
6/9/75

1/4 Sec Cor. Bet. Secs. 2 & 35 T25-7 102

Found: B.Oak Snag, 37" N89°W., 792 Lks. Scribe Mark T Vis.

B.Oak snag, 38" S89 3/4°W., 806 Lks. Scribe marks 4 S BT

Set: 2 1/2" Iron pipe 18" in grd., in M.S. 4ft. base to top, W/B.C. mkd. T25S R7W

1/4 S35

RE-RENEWED, SEE CORNER NO. #106
S 2
T26S
1975

Sand stone boulder 4'x4' in place N35°W., 85 1/2 Lks. X BO

(UNOFFICIAL-SURVEY PENDING)

Sec. Corner to Secs 2 & 3, and 35 & 36 T25-7 103

Found: B.Oak, 59" N89°W., 1196 Lks, Bt vis

- root hole N40°E., 708 Lks.

Set: 2 1/2" Iron pipe 28" long w/top 6" below surface B.E. mkd W/B.C. mkd. T25S R7W

S34 | S35
S 3 | S 2

T26S

New BT'S-A Fir 12" S80°W., 1011 Lks. T26S R7W S3 BT

A Fir 20" N65 1/2°E., 553 Lks. T25S R7W S35 BT

(UNOFFICIAL-SURVEY PENDING)

W.C. NE Corner DLC # 46 104

Found- Douglas Co. Surveyors Office Brass Cap stamped 1960 properly marked.

Old BT's - 34" now 35" dia. W. Oak bears N89°W., 5.0 ft. has good blaze, tagged

14" now 17" dia. R. Fir bears S 1/2°W., 34.5 ft. (rec. S5 1/2°W). Tree is dead

and will be removed

Ren. #41

B Oak bearing tree not found.

New BT's - R. Fir 23" dia. bears S 18 1/2°E., 57.2 ft. scribed "WC NE DLC #46

DC BT"

11/17/75

P.L.E.
L.E. Monrean
11/17/75
CS 57/39

Romanso E. Ware
For: Leonard Langley
Feb. 1977
M 63 - 29

1/4 Corner for Secs. 35 and 36.

Found - Witness Corner 60 ft. North. See Ren. #101

Set - 5/8" Iron Rod at 1/4 Corner. See Ren. #35

FD. 3/92 BY STOCKHOFF
P.P. 1992-0025

2/77