

Douglas County Surveyor's Record of  
Government Corners Renewed

T 26

T. S.

R 7

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

113

1/4 Corner for Secs. 7 and 8.  
Set - 2 1/2" alum. cap set on a 1" x 36" iron pipe.  
New BT's - 10" fir bears S.54° W., 24.9ft. scribed 1/4 S8 BT.  
4" fir bears N.22°W., 27.5 ft. scribed 1/4 S7 BT.  
A 3/4" iron pipe extending 31" above ground, set by the BLM in 1968,  
bears N.4°05'E., 1.21 ft. from the cap.

Ronald Geisler  
LS #1988  
For: Champion  
International Corp.  
Sept-Dec. 1983  
M 90 - 51

114

1/4 Corner for Secs. 7 and 18.  
Set - 2 1/2" alum. cap set on a 1" x 36" iron pipe.  
New BTs - 9" fir bears N.53°W., 10.4 ft. scribed 1/4 S7 BT.  
34" fir bears S.31°W., 15.3 ft. scribed 1/4 S18 BT.  
A 3/4" iron pipe set by the BLM in 1979, bears N.59°W., 5.91 ft. from  
the cap.

9-12/83

115

Section corner for Secs. 3, 4, 9 and 10.  
Found - (Original Post not found.)  
Fd. a 1" iron pipe with County brass cap (1959) properly mkd. #37  
Remains of roots at record bearing and dist. to orig. 6" hemlock  
S.35°E., 20.5 ft. No other orig. evidence found.  
A 14" now 22" fir with well healed double blaze bears N.39 1/2°E.,  
27.8 ft. (Rec. per BLM, N.41°W. 28.0 ft.) This tree to be  
completely removed in pasture clearing. Ren. #37  
6" fir at record N.65°W., 30.8 ft., is dead and down.  
12" W. fir now a 10" snag with "T26S R7W S9 CS BT" scribed on  
partly healed blaze, bears S.60°W., 31.0 ft. (BLM Rec. 31.0 ft.,  
Ren. #37 calls 31.6 ft. checks well to center of trunk at top  
of blaze.)  
5" fir, 10" now 16" bears S.62 1/2°E., 177.9 ft. Has a well healed  
blaze. (BLM resurvey)

Ren.

#37

Set - We reset the noted found brass cap at corner position. The mon-  
ument now protrudes 5" above ground level.  
New BTs- 16" W. fir, double blazed and scribed "T26S R7W S3 CS BT" bears  
N.58 1/2°E., 140.0 ft.  
14" W. fir double blazed and scribed "T26S R7W S9 CS BT" bears  
bears S.61 1/2°W., 33.0 ft.  
14" D. fir double blazed and scribed "T26S R7W S9 CS BT" bears  
S.26°W., 28.2 ft.

Clearing for pasture is in progress. Fences are to run north, west and  
south from corner when clearing is completed. 72 ft. east to dirt road.

8/17/84

116

1/4 Corner between Section 6; and Sec. 31 of T.25-7  
Found - 1971 BLM brass cap and  
20" fir bears S30° W., 16.2 ft.  
Note: This area was to be logged in 1984 so I removed the pipe and brass  
cap and replaced with a 5/8" x 30" iron rod set deep in the ground  
in the exact position of the pipe and brass cap. After the logging  
and slash burning, I RESET the pipe and brass cap in its original  
position putting it directly over the iron rod.

New Accessory:

The original BT is now a 20" fir stump 7 ft. tall. I rescribed  
the tree "1/4 S BT" and nailed a bearing tree tag on west side  
facing road.

Corner is on a landing 50 ft. east of road. No other trees available.

5/13/85

117

Center 1/4 Cor. sec. 10.  
Set - A 2 1/2" x 24" Alum. pipe W/3" alum. cap marked " T26S R7W  
C 1/2 S10 RLS 1651 1988".  
New BTs- A 8" fir, bears N 19°E, 14.5 ft. scribed C 1/4 S10 BT.  
A 7" Chinquapin bears S 41°E, 29.1, scribed C 1/4 S10 BT.

Burton W. Holt  
L.S. #418  
For: Sun Studs  
May 13, 1985  
C.S. 63/8

Hermen Pieske  
L.S.#1651  
For: Black Gold Ranch  
May, 1988  
M 106 - 25