

Douglas County Surveyor's Record of
Government Corners Renewed

T 26 T. S. R 8 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

24

James W. Byron
M. Godfrey
C. Putnam
April 20,
1961
C.S. File
No. 52/79

$\frac{1}{4}$ Section Corner to Section 35 and 36. #83
Found - Orig. 40", now 44" Fir Snag S. 30° 45' E. 138.6 ft., shows
good scribing on old face "S".
Parts of old Fir Stump that checks for Orig. S.W. BT.
Note - Auto Axle found bears S. 49° W. 6.8 ft.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ S35/S36 T26S R8W
New BT's: 17" R. Fir bears S. 42° W. 10.5 ft. scribed $\frac{1}{4}$ S35 CS BT.
15" R. Fir bears N. 44° E. 31.0 ft. scribed $\frac{1}{4}$ S36 CS BT.

25

Milo E.
Godfrey &
Crew
April 1, 1963
C.S. File
No. 46/129

$\frac{1}{4}$ Section Corner to Sec. 36, T26-8W. & Sec. 31, T26-7W. #56
Found - 32" D. Fir Snag showing good scar & overgrowth where it had
previously been opened. Hathorne in 1855, called for a 10" Hemlock.
We chopped Fir open & found good scribe and reverse scribe of partial " $\frac{1}{4}$ "
at about the point this tree would have been 10". Also, a ring count
showed it to be 95 to 105 years, accurate count impossible. This Fir
BT. faces the proper direction as called for in Orig. field notes.
Set - Brass Cap at Cor. alongside $\frac{1}{2}$ " Alum. Pipe & Mkd: Brass Cap
County Surveyor's Office, 1963
T26S R8W $\frac{1}{4}$ S36/S31 R7W
New BT: 26" D. Fir N. 32° E. 32.6 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
No other trees available.

MICROFILM TO HERE 10/67

26

Sec. Corner to Secs. 3 & 2, T26-8W. & Secs. 34 & 35, T25-8W.
Found - Orig. 15", now 36" Fir, alive, N. 75° E. 8.6 ft., bark scribe
in poor condition.
Orig. 18", now 24" Cedar, alive, N. 45° W. 42.9 ft., shows good scar.
Orig. 60", now 72" Fir, alive, S. 20° W. 42.9 ft., No scribe or scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968
T25S R8W $\frac{S}{3} \frac{34}{S} \frac{S}{3} \frac{35}{S} \frac{2}{2}$
New BT's: 10" D. Fir N. 42° W. 34.3 ft. mkd. T25S R8W S34 CS BT.
10" D. Fir N. 41° E. 6.7 ft. mkd: T25S R8W S35 CS BT.
5" D. Fir S. 25° E. 18.5 ft. mkd. S 2 CS BT.
11" Maple S. 6° W. 15.0 ft. mkd. T26S R8W S 3 CS BT.
This corner lies on very steep SW slope about 165' E. of creek, course NW.
7/25/68

27

$\frac{1}{4}$ Corner to Sec. 2, T26-8W. and Sec. 35, T25-8W.
Found - Orig. 20", now 24" Fir, turned out, hole fits bearing and dist.,
S. 15° E. 19.1 ft.
Orig. 40", now 48" Fir, alive, N. 35° W. 4.6 ft., shows old bark
scribe in fair condition.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968
T25S R8W $\frac{S}{4} \frac{35}{S} \frac{2}{2}$
New BT's: 6" D. Fir N. 82° E. 20.2 ft. mkd: $\frac{1}{4}$ S35 CS BT.
7" D. Fir S. 64° E. 26.1 ft. mkd. $\frac{1}{4}$ S 2 CS BT.
This corner lies on moderate changing to steep SE slope in old
growth & Rhododendron brush.
7/29/68

28

Closing Corner to Sections 11 and 12.
Found - Orig. 8", now 14" Hemlock, alive, S. 63° W. 19.1 ft., scribe
visible on partially opened blaze. We open for
ring count & find 70+ years overgrowth.
Orig. 20", now 26" Fir, alive, S. 74° E. 28.4 ft., bark scribed,
partially covered with pitch from injury above.
Unrecorded - 52" Fir N. 45° W. 18.0 ft., shows frag. bark scribe on old blaze.
Set - Brass Cap At Cor. Mkd: County Surveyor's Office, 1968
T 26 S R 8 W
CC $\frac{S}{11} \frac{S}{12}$
New BT's: 15" Hemlock S. 46° E. 30.0 ft. mkd. T26S R8W S11 CC CS BT.
11" Hemlock S. 4° W. 36.3 ft. mkd. T26S R8W S12 CC CS BT.
This corner lies 150 ft. west of Sec. Cor. Secs. 1 & 2. (Rec. 148.5).
(See Ren. #29, over)

Vernon "Ray" Tracy
Jack Heritage & V. Perron
July & August, 1968
C. S. File No. 54/72