

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

29

Section Corner to Sections 1 and 2.

From the Closing Corner of Sections 11 & 12, we measure East 150.0 ft. and find the following:

Orig. 48" now 52" Fir, S. 85°W. 18.5 ft., alive, obliterated in 1896, old axe marks & possible fragmentary bark scribe.

Orig. 30" Fir S. 70°E. 24.4 ft., only roots & decayed wood remain.

Orig. 36" now 40" Fir, N. 60° E. 38.3 ft. At point for tree there is a hole, tree slid approx. 30 ft. downhill, no scribe found, burned.

Orig. 12" Fir N. 30°W. 17.2 ft., point falls under log, we find burned & decayed remnants of old fir, no scribe.

Because the distance west to C.C. fits so closely & remains of possible original bearing trees, we renew:

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 26 S R 8 W S 2 | S 1

New BT's: 8" Hemlock N. 43°W. 24.8 ft. mkd. T26S R8W S2 CS BT.

9" Hemlock N. 57° E. 25.0 ft. mkd. T26S R8W S 1 CS BT.

This corner lies on moderate northerly slope, 150 ft. E. of CC., Ren. #28.

30

SEPT. '68

Section Corner to Secs. 4 & 5, T26-8W. and Secs. 33 & 32, T25-8W.

Found - Orig. 8" Cedar, now 20" snag, decayed center, S. 60°W. 15.2 ft., no scribing found.

Orig. 8" now 24" Cedar, alive, N. 20°E. 25.1 ft., Open & find "S33" scribe & reverse.

Only decayed remains of N.W. Orig. BT. - No trace S.E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 R8W T25S S 32 | S 33 T26S S 5 | S 4

New BT's: 20" Cedar N. 24°W. 26.6 ft. mkd: T25S R8W S32 CS BT.

9" Hemlock N. 34°E. 12.2 ft. mkd: T25S R8W S33 CS BT.

7" Hemlock S. 9° E. 21.8 ft. mkd: T26S R8W S 4 CS BT.

9" Hemlock S. 40°W. 23.9 ft. mkd: T26S R8W S 5 CS BT.

This corner lies on moderate easterly slope approx. 100 ft. west of bench, course N. & S.

31

1/4 Corner to Sections 13 and 14.

Found - Orig. 18" now 24" Hemlock, alive, N. 63°E. 18.5 ft., shows scars. We do not open. Rescribed: "1/4 S13 CS BT".

Orig. 10" Hemlock, now 12" decayed stump, 18" high with "BT" scribe exposed, N. 23°W. 15.2 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 26 S R 8 W 1/4 S 14 | S 13

New BT: 44" D. Fir N. 86° W. 24.9 ft. mkd: "1/4 S14 CS BT".

This corner lies on moderate east slope in old growth timber.

32

1/4 Corner to Sections 12 and 13.

Found - Orig. 18" now 33" Fir, alive, N. 62°W. 10.6 ft., find "1/4" bark scribe in poor condition.

Orig. 20" now 42" Fir, alive, S. 68°W. (Rec. No. 88) 6.6 ft., shows "B" bark scribe in poor condition, upper axe blaze chopped off previously.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T 26 S R 8 W 1/4 S 12 | S 13

New BT's: 30" D. Fir N. 4° W. 6.8 ft. mkd: "1/4 S12 CS BT".

42" D. Fir S. 68 1/2 W. 6.6 ft. (Orig. BT) mkd: "1/4 S13 CS BT".

This corner lies on top of ridge, course E. & W.

33

1/4 Corner to Sections 10 and 11.

Found - Orig. 18" now 30" Fir, alive, N. 32°E. 40.9 ft., bark scribe in poor condition.

Orig. 8" now 14" Yew, alive, N. 65°W. 33.0 ft., blaze decayed, no scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 26 S R 8 W 1/4 S 10 | S 11

New BT's: 7" Hemlock N. 68°E. 2.4 ft. mkd: "1/4 S11 CS BT".

18" Hemlock S. 79° W. 13.1 ft. mkd: "1/4 S10 CS BT".

This corner lies on very gentle N. W. slope.

John M. Powell
Frank Jones & W. Penley
August, 1968
C. S. File No. 54/72

RE-RENEWED, SEE CORNER NO. #75
RE-RENEWED, SEE CORNER NO. #80