

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 8 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon R. Tracy
Jack Heritage & V. Perron
C.S. File No. 54/72

$\frac{1}{4}$ Corner to Sections 11 and 14. 34
Found - Orig. 36", now 54" Fir, alive, N.55°W. 35.6 ft., opened,
blaze pitched over.
Orig. 8" Hemlock, now 16" shattered stump, S.54°W. 21.8 ft.,
find " $\frac{1}{4}$ S BT" scribe on pieces.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 8 W
Office S 11
 $\frac{1}{4}$ S 14
New BT's: 36" D. Fir S. 38° E. 9.6 ft. mkd: " $\frac{1}{4}$ S14 CS BT".
24" Hemlock N. 8° E. 7.0 ft. mkd: " $\frac{1}{4}$ S11 CS BT".
This corner lies on moderate east slope 50 ft. W. of old logging road.

Section Corner to Sections 13 - 14 - 23 - 24. 35
Found - Orig. 6", now 14" Hemlock, down, N.29°E. 21.1 ft., scar on bottom.
Orig. 20" Fir, now 30" x 12' high Snag, S.55°W. 18.5 ft., good scars.
Orig. 20", now 28" Fir, alive, N.39°W. 19.1 ft., opened prev.,
scribe visible on burned blaze.
No trace of S. E. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 8 W
Office S 14 | S 13
1968 S 23 | S 24
New BT's: 24" D. Fir N. 55° W. 4.9 ft. mkd: T26S R8W S14 CS BT.
18" D. Fir N. 88° E. 27.8 ft. mkd: T26S R8W S13 CS BT.
9" Hemlock S. 23° E. 9.2 ft. mkd: T26S R8W S24 CS BT.
5" Hemlock S. 30° W. 17.4 ft. mkd: S23 CS BT.
This corner lies on gentle westerly slope about 100 ft. N. of shallow
draw, course west. Sept. 16, 1968

$\frac{1}{4}$ Corner to Sections 14 and 23. 36
Found - Orig. 6" Cedar, now 16" Snag, 11' high, N.72°W. 21.1 ft.,
shows good scar.
Orig. 30", now 34" Fir Snag, S. 78° W. 10.6 ft., Open &
find " $\frac{1}{4}$ S" scribe & reverse.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 8 W
Office S 14
1968 S 23
New BT's: 10" W. Fir S. 84° E. 70.8 ft. mkd: $\frac{1}{4}$ S23 CS BT.
9" W. Fir N. 52° E. 9.1 ft. mkd: $\frac{1}{4}$ S14 CS BT.
This corner lies on southwest moderate slope.

Section Corner to Sections 11 - 12 - 13 - 14. 37
Found - Orig. 6", now 14" Hemlock, alive, N.52°E. 17.8 ft., scribe
visible on open blaze. #78
Orig. 30", now 40" Fir, alive, S.60°E. 37.0 ft., shows good scars.
Orig. 16", now 24" Chinquapin, S.56°W. (Rec. S.60W. 37.0') 39.6 ft.,
bearing & distance turned around. Alive, scribe visible
on nearly healed blaze (hoop).
No trace Orig. N. W. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 26 S R 8 W.
Office S 11 | S 12
1968 S 14 | S 13
New BT's: 18" Hemlock S. 58° E. 32.8 ft. mkd: T26S R8W S13 CS BT.
17" Hemlock N. 17° E. 27.0 ft. mkd: T26S R8W S12 CS BT.
5" D. Fir N. 74° W. 17.6 ft. mkd: S11 CS BT.
Orig. 24" Chinquapin S.56°W. 39.6 ft. mkd: T26S R8W S14 CS BT.
This corner lies on top of Mt. in dense rhododendron thicket.

Sec. Cor. to Secs. 33 & 34, T25-8 and Secs. 4 & 3, T26-8W. 38
Found - Orig. 15", now 30" Cedar, alive but leaning badly, S. 85° E.
2.6 ft., faint scar.
Orig. 20", now 36" Cedar, 8' high snag, S.40°W. (Rec. S40E) 3.3 ft.,
open & find reverse scribe.
Orig. 12", now 22" Cedar, alive, N.88°W. 5.3 ft., shows faint scar.
Rescribed: T25S R8W S33 CS BT."
No trace of N.E. Maple Orig. BT.

(continued over)