

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 26 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Set - Brass Cap at Cor. Mkd; County Surveyor's Office, 1968 T25S R8W  $\frac{S}{S} \frac{33}{4} | \frac{S}{S} \frac{34}{3}$

New BT's: 60" D. Fir S. 25\*E. 30.8 ft. mkd: T26S R8W S3 CS BT.  
26" Hemlock S. 16\*W. 32.2 ft. mkd: T26S R8W S4 CS BT.  
8" Hemlock N. 41\*E. 21.2 ft. mkd: T25S R8W S34 CS BT.

This corner lies on very steep west slope about 150 ft. E. of bench.

**39**

$\frac{1}{4}$  Corner to Sec. 36, T25-8W. and Sec. 1, T26-8W.

Found - Orig. 30" Fir, now 48" Stump, S. 35\*E. 26.4 ft., only small trace of bark scribe remains. Cruiser's marks & yellow tag on SE BT., recorded in forest appraisal survey, dated Nov. 1951 by Lecklider & Givens. No trace of N.E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T25S R8W  $\frac{S}{S} \frac{36}{1}$

New BT's: 14" Hemlock S. 68\*W. 50.4 ft. mkd:  $\frac{1}{4}$  S 1 CS BT.  
10" Cedar N. 87\*E. 28.4 ft. mkd:  $\frac{1}{4}$  S36 CS BT.

This corner lies on very steep N. slope about 100 ft. S. of creek, course E. We put yellow line tag at creek about 100' N. of corner.

9/26/68

**40**

Sec. Cor. to Secs. 31 & 32, T25-8W. & Secs. 6 & 5, T26-8W.

Found - Orig. 42", now 60" Fir, alive, S. 10\*E. 21.8 ft., bark scribe visible, poor condition.

Orig. 34", now 52" Fir, alive, S. 10\*W. 26.4 ft., bark scribe visible, poor condition.

28", now 40" Fir, alive, N. 70\*E. 42.9 ft., no scribe nor scar found, injured. (1896 BT)

72", now 82" Fir, alive, N. 8\* W. 66.0 ft., bark scribe visible, fair condition.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T25S R8W  $\frac{S31}{S6} | \frac{S32}{S5}$

New BT's: 11" Hemlock N. 12\*E. 23.8 ft. mkd: T25S R8W S32 CS BT.  
10" Hemlock N. 12\*W. 18.8 ft. mkd: T25S R8W S31 CS BT.  
8" Hemlock S. 65\*W. 18.7 ft. mkd: S 6 CS BT.  
13" Hemlock S. 72\*E. 26.1 ft. mkd: T26S R8W S5 CS BT.

This corner lies on precipitous SE slope in large old fir & hemlock.

+

**41**

$\frac{1}{4}$  Corner to Sec. 33, T25-8W. and Sec. 4, T26-8W.

Found - Orig. 16", now 28" Hemlock, S. 15\*E. 29.0 ft., open & find, "T" scribe. No trace of other Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyors' Office, 1968 T25S R8W  $\frac{1}{4} \frac{S}{S} \frac{33}{4}$

New BT's: 35" Hemlock S. 60\*W. 33.1 ft. mkd:  $\frac{1}{4}$  S4 CS BT.  
32" Hemlock N. 29 $\frac{1}{2}$ \*E. 26.0 ft. mkd:  $\frac{1}{4}$  S33 CS BT".

9/23/68

$\frac{1}{4}$  Corner to Section 5, T. 26-8W. and Sec. 32, T25-8W.

Found - Orig. 18", now 25" Fir, alive, N. 10\*W. 5.3 ft., bark scribe visible in fair condition  $\frac{1}{4}$  BT" (1881 BT)

No trace of other Orig. BT or 1902 Resurvey BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T25S R8W  $\frac{1}{4} \frac{S}{S} \frac{32}{5}$

New BT's: 25" Fir N. 10\* W. 5.3 ft. (Orig. BT) mkd:  $\frac{1}{4}$  S32 CS BT", (alongside old scribe)  
38" Fir S. 2\* W. 27.1 ft. mkd:  $\frac{1}{4}$  S 5 CS BT".

This corner lies on very steep west slope.

9/24/68

**43**

$\frac{1}{4}$  Corner Common to Sec. 34, T25-8W. and Sec. 3, T26-8W.

(Cor. Set By Proportionate Measurement)

Set- 5/8" Iron Rod and Aluminum Cap.

Scribed- 24" R. Cedar S. 80°E. 29.1 ft.  
6" Hemlock N. 66°W. 12.5 ft.

Vernon R. Tracy  
Jack Heritage & V. Perron  
C.S. File No. 54/72

Howard Johnstone  
Rsbrg. Lbr.  
Feb., 1970  
Map M 39 - 13