

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 1 W. R. W. W. M.

ROBE-CHAPMAN CO., EUGENE, ORE. 21801

Witness Corner to Sections 30 and 31.

This corner originally set as cor. to secs. 25 & 36, T27-2W. & secs. 30 & 31, T27-1W. All 4 Orig. trees found, but bearings given are all wrong, The N.W. tree is actually N.E.. The S.E. tree is actually S.W. The S.W. tree is actually N.W. The N.E. tree is actually S. E.

Found - Cedar, now 30", S.46 $\frac{1}{2}$ °E. (not N.46 $\frac{1}{2}$ °E.) 39.6 ft., scribing plainly visible on open face. "T27S RLW S31 BT" #161

Stump of 12" Hemlock S.22 $\frac{1}{2}$ °W. (not S.22 $\frac{1}{2}$ °E) 25.7 ft. Axe marks on old face where scribing had been cut off.

20" Hemlock N.52°W. (not S.62°W.) 25.1 ft. Broken off & dead. Axe marks & a few traces of scribing plainly visible on old face where scribing was cut off.

Cedar, now 36", N.69°E. (not N.69°W.) 21.0 ft. (not 25.1 ft.) scribing visible on open face "T27S RLW".

Corner falls in White Creek. Could not set corner in this location. Set Wit. Cor. 10 ft. East of Cor.

Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R2W W.C. S30 RLW Office, 1962 10' W. to Cor. S31

Did not find Rock set for corner.

Blaze & Rescribe the N. E. Tree: 36" Cedar N.51°E. 11.9 ft. Mkd: T27S RLW W.C. S30 CS BT.

Did not rescribe S.E. BT. which bears S.36°E. 32.0 ft. from Brass Cap. FOUND O.K. 10/68 V.R.T.

Closing Corner for Sections 25 and 36., T27S R2W. 8

Find - Old Cedar Stake, some scribing still visible "S25".

Hemlock, broken off & dead, S.76 $\frac{1}{2}$ °W. 33.7 ft. perfect scribing still visible on open face "T27S R2W S36 B". #20

Hemlock, now 12", N.76°W. 25.1 ft., scribing visible "27S R2W"

Set- Brass Cap at Cor. Mkd: County Surveyor's T27S R2W S25 RLW CC Office, 1962 S36

Set Original Post alongside and erect rock Mound.

New BT's: 20" Hemlock S.22°W. 42.3 ft. Mkd: T27S R2W CC S36 CS BT.

19" R.Cedar N.64°W. 23.0 ft. Mkd: T27S R2W CC S25 CS BT.

Note - Corner falls in White Creek near East Bank.

Section Corner for Sections land 12 only on Range Line, T27-2W. 9

Found - 5" x 6" x 8" Stone, 5 notches on South Side.

28" W.Fir S.50°E. 17 lks. (wood scribe visible) #135

30" Fir N.73°W. (record N.80°W.) 20 lks. (faint bark scribe)

34" Fir S.52°W. (record S.45°W.) 33 lks. (bark scribe destroyed)

Set - $\frac{3}{4}$ " x 30" Iron Pipe

Scribed - 10" Fir N.31°W. 22.4 ft.

34" Fir S.52°W. 23.8 ft.

FOUND O.K. 10/68 VRT

Howard W. Johnstone
For Rsbrg. Lbr.
Aug. 18, 1962
C.S. File No. 51/163

&

$\frac{1}{4}$ Corner between Sections 7 and 18.- Witness Corner 10

Found - Both Orig. BT's. and the Stone marked " $\frac{1}{4}$ ". Removed the stone because of road construction through the corner. The BT. in Sec. 7 was removed due to const. but the BT in Sec. 18 still remains. #172

Set - 1" x 36" Iron Pipe with Brass Cap 18 ft. South of the true corner for a witness corner. Mkd: Cap T27S RLW W.C. $\frac{1}{4}$ S 7 Cor. is 18' North 1963 S18 L. S. 418

New BT's: 40" D.Fir bears S.12°W. 9.1 ft. Mkd: $\frac{1}{4}$ S18 BT(bark scribed)

22" D.Fir bears N.55°E. 99.8 ft. Mkd: $\frac{1}{4}$ S 7 BT(This BT. lies North of Road)

The true $\frac{1}{4}$ corner lies on the cut bank of the Shadow Sale Road and the witness corner is above the cut bank. Placed original stone beside the brass cap, which is approx. 32 ft. S. of road center.

Burton W. Holt #418
March 13, 1963
C. S. File No. 51/100