

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

125

1/4 Corner, Section 36 only, T26-1.
Found - 28" D. Fir, :N.74°W., 94.5 ft. Face pitched over. Ren. No. 30
R. R. Spike in rock cut bank, N.36°E., 47.1 ft. 4' above road.
Orig. 10" W. Fir, N.6°E., 37.6 ft.
Witness Cor. Brass cap out of ground mkd.
County Surveyors Office 1969
W.C. S5' East to T 26 S R 1 W
S 36
1/4 T27S

John M. Powell
J. Heritage
May 21, 1973
C.S. File 56/25

Renewal - Reset Brass cap at correct location for wit. corner
5/21/73

126

1/4 Corner for Sec. 12 only, T.27-2.
Set - Brass cap
BT's - 12" Fir, scribed 1/4 S12 BT., N.4°W., 19.0 ft.
6" Fir, scribed 1/4 S12 BT., S.49°W., 44.8 ft.

Baughman Surveying
for Cal Willis
M 52 - 77
February, 1974

2/74

127

Section Corner for Sections 33 and 34 only.
Found - Brass cap mkd. as described in Ren. #79 by Co. Surveyors Office in 1969.
From which: An approx. 40" Pine stob bears N.40°E., 7.3 ft. No marks visible, area has been disturbed by logging.
A 15" D.Fir bears N.14 1/2°W., 38.3 ft. shows good scar.
No trace of NE BT, a Hemlock mkd. in 1969.
New BT - a 24" D.Fir bears N.52°E., 61.2 ft. scribed "T27S R1W S34 CS BT."
6/24/74

Gary L. Langlitz, County Surveyors Office
Peter Earle
June 24, 1974
C.S. 56/51

128

CC corner for Sections 3 and 4 only, T28-1.
Found - Orig. 12" now 17" Red cedar with scribing visible on opened face.
Orig. SW bearing tree, A Fir, is now gone.
The Brass cap set in 1969 by Co. Surveyors Office has been destroyed in logging operations. Ren. No. 80
Set - Brass cap mkd.
COUNTY SURVEYORS OFFICE 1974
T 27 S
S 34 R
S 4 | S 3 1
CC W
T 28 S

At record measurements from the only remaining bearing tree, a 12" now 17" Red cedar bearing S. 12°W., 21.1 ft. we mark the following BT:
A 17" Hemlock bears S.77°E., 194.6 ft. scribed "CC T28S R1W S3 CS BT."

JAN 75

129

Closing Corner For Sec. 24 & 25 only, T27-2
Found - 42" Fir snag scribed "T27S R2W S24 BT"
Other bearing tree not found. Corner Post not found.
Set - Brass cap at closing corner, stamped
County Surveyors Office 1975
T27S R
R S24 S30 R
2 CC S25 1
W W

L.E. Monrean
P.L. Earle
C.S. 57/30
5/21/75

BT's - A 17" Hemlock bears S51°W., 40.2 FT. Scribed "CC S25 T27S R2W CS BT"
A 16" Hemlock bears N.63°W., 26.0 ft - Scribed "CC S24 T27 S R2W CS BT"
A Stone 16" 10"x8" with 4 notches on one edge & 2 notches on the opposite edge, lying on surface of ground bears N.4°W., 58.9 ft. (rec. N.0° 45'W., 60.7 ft)

130

1/4 Corner to Sec. 29 & 32
Found: A stone, approx 8"x9"x12" Approx 4" in the ground & loose, with a faint "1/4" marked on the apparent northface.
We find no evidence of any corner accessories. The area adjacent to this corner has been logged and burned. We do not monument the corner at this time.

Gary L. Langlitz
Cliff E Goodwin
A.V. Cangie
M. Lenora Ladig
C.S. 57/30
6/5/75

RE-NEWED CORNER NO. #153