

Douglas County Surveyor's Record of  
Government Corners Renewed

T 27 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

Section Corner for 1 and 12 only - T27-2

Found - 3/4" Iron Pipe. Ren. #9

A 30" Hemlock snag, S.50°E., 11.2 ft. (scribing visible)

A 30" D. Fir snag, S.52°W., 23.8 ft. (scribing visible)

A 12" Fir, W.31°W., 22.4 ft. (good face)

A 42" D. Fir, N.73°W., 13.2 ft. (no scar or scribe visible)

New BT - A 16" D. Fir, S.30°W., 104.5 ft. (scribed "T27S R2W S12 BT")  
washer set in face.

135  
Romanso E. Ware  
For: U.S. Forest Service  
March 1977  
M 65 - 13

1/4 Corner for Sec. 13 only, T27-2.

Set - 2 1/2" I.P. with brass cap in rock mound stamped T27S R2W S13 | R1W  
1977 L.S. 1005.

New BT's - A 6" W. Fir bears N.61°W., 7.7 ft. scribed "1/4 S13 BT".

A 6" W. Fir bears S.29°W., 45.1 ft. scribed "1/4 S13 BT".

136  
Romanso E. Ware  
For: U.S. Forest  
Service

Section Corner for Secs. 18 and 19 only. West boundary.

Found - 1968 County Surveyors Office Brass cap restamped BLM 1971 on a  
1" I.Pipe. 3/4" I. Rod bears 0.5 ft. West. Ren. #21.

32" Fir stump bears N.34°E., 60.0 ft. scribed "T27S R1W S18 CS BT"

New BT's - 10" Maple bears S.45°E., 50.5 ft. scribed T27S R1W S19 BT.

6" Fir bears N.52°E., 43.6 ft. scribed T27S R1W S18 BT.

137  
May 1977  
M 65 - 20

CC for Secs. 13 and 24 only, T27-2.

Set - A 2 1/2" I. Pipe with brass cap in rock mound stamped T27S  
R2W CC S13 S24 S19 R1W L.S. 1005 1977.

New BT's - 7" Maple bears N.2°W., 52.2 ft. scribed "T27S R2W S13 CC BT".

8" Maple bears South, 45.9 ft. scribed "T27S R2W S24 CC BT".

138  
Romanso E. Ware  
For: U.S. Forest  
Service  
May 1977  
M 65 - 19

1/4 Corner for Sec. 24 only, T27-2.

Set - a 2 1/2" I. Pipw with brass cap in rock mound stamped T27S R2W  
CC S24 R1W OLS 1005 1977.

New BT's - 8" D. Fir bears N.43°W., 35.8 ft. scribed 1/4 S24 CC BT.

6" D. Fir bears S.62°W., 32.2 ft. scribed 1/4 S24 CC BT.

Section Corner for Secs. 1 and 12 only, T27-2

Found - 3/4" Iron rod set by Johnstone in 1962 with corner stone  
lying alongside. Ren. #9. Corner stone has five notches  
on one edge.

A 31" W. Fir snag bears S.50°E., 11.5 ft. scribing visible on  
previously opened blaze.

A 11" D. Fir bears N.31°W., 22.2 ft. Has healed scars.

A 37" D. Fir bears N.71°W., 14.5 ft. No scar or scribing visible.

A 33" D. Fir snag bears S.52°W., 23.8 ft. Has a healed scar.

A 17" D. Fir bears S.28°W., 104.2 ft. (Rec. S.39°W., 104.5 ft.)  
scribing visible T27S R2W S12 BT" on a double blaze. Ren. #135.

Lower blaze has an alum. washer set in face mkd. "LS 1005"

(All measurements to center of BT's.)

Set - Removed 3/4" Iron pipe and in its place I SET a 2 1/2" Brass  
cap on a 1" Pipe stamped County Surveyors Office T27S R2W S 1 | S6  
1977 S 12

No new accessories. I placed County BT signs on all BT's.

Corner lies 75 ft. east of F.S. Road No. 2612D.

140  
Dennis Gaylord, U.S. Forest Service  
Deputy, Doug. Co. Surveyors Office  
Travis Worthen  
July 7, 1977  
C.S. 59/38

1/4 Corner for Secs. 31 and 32.

Found - A stone set solidly in place marked "1/4" on the west face.  
Stone measures 14" x 12" x 6".

A 60" D. Fir snag bears N.60°W., 10.9 ft. (Rec. 11.9 ft.) Bark  
shows old aze marks.

Orig. BT to the SE is down & badly decomposed.

Placed County BT sign on snag.

Set - Moving orig. stone aside, I Set in it's place a 2 1/2" brass cap  
on a 1" I.P. Brass cap stamped County Surveyor's Office  
T 27 S R 1 W

1/4 S 31 | S 32

1978 / CONT NEXT PAGE

141  
Dennis Gaylord, USFS  
Deputy, Doug. County  
Surveyors Office  
Jan. 12, 1978  
C.S. 59/46