

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 T. S. R. 1 W. R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21851

Ronald A. Quimby LS#1654
Romanso E. Ware LS#1005
For: U.S. Forest Service
March 1980
M 79 - 32

152

See Ren. #75 =

Section Corner for Sections 29 - 30 - 31 - 32

- Fd- 1" Iron pipe with brass cap.
- 30" D. fir snag bears N.15°E., 44.2 ft. with visible scribes.
- 42" D. Fir stump bears S.78°E., 61.4 ft. with visible scribes.
- 28" D. Fir bears S.69°E., 78.5 ft. with visible face.
- 26" D. Fir bears S.40°W., 17.2 ft. with visible scribes.
- 52" D. Fir stump bears N.15°W., 66.0 ft. with good scar.
- 26" Hemlock bears N.89°W., 46.1 ft. with visible scribes.
- 24" D. Fir bears N.58°E., 15.7 ft. with good scar.

Set fiberglass post 4.5 ft. south of corner.

153

1/4 Corner to Sec. 29 and 32

See Ren. #130

- Fd- Rock out of place with "1/4", unable to determine original location of corner stone.
 - Set - 2 1/2" iron pipe with brass cap at proportionate location.
 - BT's- 6" Pine bears S.11°W., 19.6 ft. scribed "1/4 S32 BT".
 - 8" Hemlock bears N.4°E., 24.3 ft. scribed "1/4 S29 BT".
- BT's have brass washers RLS# 1654 in BT's face.

See Ren. #131

154

Sec. Corner for Sections 28 - 29 - 32 - 33

- Fd- 1 1/2" Iron pipe with brass cap.
- Bearing object #1 5/8" Iron Rod and alum. cap in stump bears N.75°E., 3.8 ft.
- Bearing object #2 5/8" Iron Rod and alum. cap in 48" cedar stump bears S.26°E., 64.4 ft.
- Bearing object #3 5/8" Iron rod and alum. cap bears S.75°W., 22.2 ft.
- Bearing object #4 5/8" Iron Rod and alum. cap in 30" Fir stump bears N.59°W., 70.8 ft.

New accessories - Set post and signs 3.0 feet west of corner.

155

1/4 Corner to Sections 19 and 30

See Ren. #103

- FD: County Surveyor's Brass Cap.
 - 16" Cedar bears S.5°E., 12.5 ft. with visible scribe.
 - 30" Cedar bears N.17°E., 49.0 ft. with good scar.
 - 42" D. Fir bears S.32°E., 56.0 ft. with good scar.
 - New BT'S - 14" Cedar bears S.30°E., 41.6 ft. scribed "1/4 S30 BT".
- Brass washer in B.T. face RLS #1005.

RE-RENEWED, SEE CORNER NO. #199

156

Center 1/4 Corner for Section 19.

- Set - 2 1/2" Iron pipe with brass cap.
 - BT's - 7" Hemlock bears N.63°E., 55.7 ft. scribed "C1/4 S19 BT".
 - 7" Hemlock bears N.86°W., 26.6 ft. scribed "C1/4 S19 BT".
- Brass washers RLS#1005 in B.T. faces. Set post and signs 5.0 ft. south and 3.0 ft. east.

RE-RENEWED, SEE CORNER NO. #198

157

1/4 Corner for Sections 18 and 19

- Fd - 60" D. Fir snag bears N.30°E., 31.7 ft., opened and found visible scribes "4".
 - 40" Hemlock snag bears S.39°E., 33.0 ft. with good face but rotted out.
 - Found stone but unable to identify marks.
 - Set - 2 1/2" Iron pipe with brass cap in a mound of stone.
 - BT's - 6" D. Fir bears N.74°W., 6.9 ft., scribed "1/4 S18 BT".
 - 12" D. Fir bears S.70°E., 12.1 ft. scribed "1/4 S19 BT".
 - 9" D. Fir bears N.20°E., 4.8 ft. scribed "1/4 S18 BT".
- Set fiberglass post with sign. Brass washers in B.T. faces RLS#1654.

Ronald A. Quimby LS#1654
Romanso E. Ware LS#1005
For: U.S. Forest Service
March 1980
M 82 - 70

OVER