

Douglas County Surveyor's Record of
Government Corners Renewed

Ta 27 S. T. S. R. 1 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

(continued)

Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1967 T26S R2W CC | S 31 | R1W
T27S R2W CC | S 6

New BT: 14" W. Fir S. 35° E. 30.9 ft. mkd. T27S R1W S6 CC CS BT.

Note - This corner lies on steep north slope approx. 450 ft. south of E. Mile Creek.

8/7/67 - C.S. 54/40

MICROFILM TO HERE 10/67

17

SEPT 28

Standard Corner to Sec. 31, T27-1W. and Sec. 36, T27-2W.,

Found - Orig. 16", now 38" Fir, alive, N.71°W. 40.9 ft., shows faint scar, we open & find scribe marks.

No trace of corner stone or mound of stone called for.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T27S R2W S 36 | S 31 | R1W
T28S

New BT's: 16" D. Fir N.61°E. 34.0 ft. mkd: T27S R1W S31 SC CS BT.

Orig. 38" R. Fir N.71°W. 40.9 ft. mkd: T27S R2W S36 SC CS BT.

This corner lies on very steep, southerly slope approx. 300 ft. south of high rock bluff. The C.C. of T28S - R's. 1 & 2W. bears W. 413 ft.

18

1/4 Corner to Sec. 31, T27-1W. and Sec. 36, T27-2W.

Found - Corner Stone mkd: "1/4" on west face firmly set at corner point.

Orig. 14", now 36" Hemlock, alive, S.49°E. 51.5 ft., shows faint scar. Recorded to be Fir. Rescribe: "1/4 S31 CS BT".

Orig. 20", now 40" Hemlock, alive, N.78°W. 68.6 ft., shows "1/4" on open blaze. Rescribe "1/4 S36 CS BT".

No smaller trees near to scribe for bearing trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 27 S R2W 1/4 S36 | S31 | R1W
(Reset stone alongside)

This corner falls 50 ft. N. of small creek, course N.W. in dense thicket of vinemaple.

10/18/68

19

West 1/4 Corner to Section 7 only, T27-1W.

Found - Corner Stone mkd. with "X" on top & "1/4" on W. face, firmly set.

Orig. 24", now 38" Pine, alive, S.18°E. 42.9 ft., open & find scribe.

Orig. 24", now 30" Pine Stump, N.31°W. 55.4 ft., shows scribe on open blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T27S R2W 1/4 | S 7 | R1W

New BT's: 13" W. Fir S.24°E. 12.0 ft. mkd: 1/4 S 7 CS BT.

11" W. Fir N.52°E. 16.8 ft. mkd: 1/4 S 7 CS BT.

This corner lies on westerly slope. Reset old corner stone alongside B.C.

20

Wit. Corner-C1. Corner Sections 25 and 36, T27-2W. REN #8

Found - No trace of 1962 C.S. Brass Cap due to 1964 flood, See Ren. #11, T27-2W.

Orig. 12" Hemlock, alive, N.76°W. 25.1 ft., scribe visible.

Orig. S.W. Bearing Tree gone, due to logging.

20" Hemlock, alive & O.K., S.22°W. 42.3 ft.

19" R. Cedar, alive & O.K., N.64°W. 23.0 ft.

We measure 25 ft. W. from true corner & at point set Witness Corner:

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T27S Wit. Cor. R2W S 25 | S 36 | CCR1W
25' E. to Corner.

Rescribe Ren. #11 BT's: 20" Hemlock S.12°E. 40.0 ft. mkd: W.C. T27S R2W S36 CC CS BT.

19" R. Cedar N.23°E. 12.0 ft. mkd: W.C. T27S R2W S25 CC CS BT.

True Corner falls in center of creek, 25 ft. E. of Wit. Corner.

This corner bears S.19°W. 99.4 ft. from W.C. to Secs. 30 & 31, T27-1W.

11/6/68

21

Sec. Cor. to Sections 18 & 19 only, T27-1W. REN #14

Found - 3/4" I.R. under 40" Log & 40" Fir Stump N.34°E. 60.0', See Ren. #44, T27-2W.

24" Hemlock Snag, now down & only decayed remains of stump in place.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 2 T 27 S R
(Reset I.R. Alongside) W | S 18 | 1 #137
(Also Set 6' Steel Fence Post) 1968 W | S 19

No trees or stumps available for Bearing Trees.

This corner lies about 125 ft. W. of Road #274L in logged off area, now densely covered with greasewood brush.

11/13/68

VERNON "RAY" TRACY
Jack Heritage & V. Perron
October, 1968
C. S. File No. 54/40

RE-RENEWED, SEE CORNER NO. #170
RE-RENEWED, SEE CORNER NO. #197