

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 1 R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 91881

173

1/4 Corner for Section 2 only. (north)
Found - 1" iron pipe with Alum. cap marked U.S.P.C. Property Corner
T27S R1W 1963 1/4 S2 only RE 4287 Do Not Disturb". Ren. #43
20" Hemlock snag S.69°W., 72.0 ft. vis. scribes.
26" Hemlock S.26°W., 105.0 ft. visible scribes.
New BT - 24" Hemlock S.61°W., 107.0 ft. "1/4 S2 BT".
Brass washer marked RLS #1654 set in BT face. Set post and sign 4.0 ft. south

174

1/4 Corner for Secs. 3 and 2.
Found - 1971 BLM brass cap on 2 1/2" iron pipe, properly marked.
New BT's- 9" Fir, S.73°W., 101.3 ft. "1/4 S3 BT".
6" Pine, N.72°E., 108.0 ft- "1/4 S2 BT".
Brass washer marked RLS #1654 set in BT faces. Set post & sign 5.0 ft. W.

175

Center 1/4 Corner for Section 2.
Set - 2 1/2" I.P. with brass cap marked "T27S R1W C 1/4 S2 RLS 1654 1980"
New BT's- 36" Hemlock, N.14°W., 69.0 ft. "C 1/4 S2 BT"
30" Hemlock S.30°E., 33.4 ft. "C 1/4 S2 BT". 201
Brass washer marked RLS #1654 set in BT faces. Set post & sign 4.0 ft. North
and 4.0 ft. East.
Found - 3/4" Iron rod, S.4°40'W., 20 ft. Unrecorded.

176

1/4 Corner for Sec.s 2 and 1.
Set - 2 1/2" I.P. with brass cap marked "T27S R1W 1/4 S2 S1 RLS 1654
1980".
New BT's- 36" W. Fir, S.78°E., 103.6 ft. "1/4 S1 BT"
20" W. Fir, S.83°W., 156.5 ft. "1/4 S2 BT". 201
Brass washers marked RLS #1005 set in BT faces. Set post & sign 3.0 ft. North
and 3.0 ft. West.

177

Witness Corner For 1/4 Cor. for Secs. 2 and 1.
Found - 2 1/2" I.P. with brass cap marked U.S. Dept. of the Interior
T S R W WC S2 1/4 S1 1971".
10" D. Fir, N.87°W., 38.3 ft. vis. scribes.
24" Hemlock stump, S.77°W., 15.1 ft.
New BT's- 7" Fir, S.2°W., 8.9 ft. "W.C. 1/4 S2 BT".
6" Fir, S.70°E., 12.0 ft. "W.C. 1/4 S1 BT"
Brass washer marked RLS #1654 set in B T faces. Set post & sign 4 ft. West.

178

Section corner for Secs. 11, 12, 13 and 14.
Found - 1969 County brass cap properly marked. Ren. #33
12" Yew, N.73°E., 5.9 ft. Good scar.
40" Fir, S.30°E., 29.0 ft. Good scar.
23" Hemlock, S.69°W., 6.6 ft. vis.scribes
22" Hemlock, N.26°W., 26.4 ft. vis scribes.
down 30" D. Fir, N.68°E., 21.8 ft. good scar.
Rescribed: 12" Yew, N.73°E., 5.9 ft. "T27S R1W S12 BT Face".
Brass washer marked RLS 1654 set in BT face. Set post & sign 4 ft. South.

179

1/4 Corner for Secs. 13 and 14.
Found - Original stone with vis 1/4 on west side.
Down 24" D. Fir, N.45°E., 13.9 ft. vis. scribes "S 13 BT".
Set - 2 1/2" iron pipe with brass cap marked "T27S R1W 1/4 S14 S13
RLS 1654 1980". Set cap at location of corner stone. Buried
Stone along side.
New BT's- 8" D. Fir, N.55°W., 3.9 ft. "1/4 S14 BT"
10" D. Fir, N.36°E., 13.8 ft. "1/4 S13 BT"
Brass washer marked RLS 1654 set in BT faces. Set post & sign 2 ft. North.

180

Center 1/4 Corner for Sec. 13.
Set - 2 1/2" I.P. with brass cap marked "T27S R1 W C 1/4 S13 RLS
1320 1980".
New BT's- 9" Hemlock, S.35°E., 18.4 ft. "C 1/4 S13 BT"
6" Hemlock, S.58°W., 22.8 ft. "C 1/4 S13 BT"
Brass washer mkd. RLS 1654 in BT faces. Set post & sign 5 ft. South & East.

Ronald Quimby - Romanso E. Ware
BHW, Eng.
For: U.S. Forest Service
M 79 -55
August 1980

Ronald Quimby
Duane Scroggins
BHW, Eng.
For: U.S. Forest Service
M 79 - 57 and M 79 - 56
August 1980