

Douglas County Surveyor's Record of  
Government Corners Renewed

T 27 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

195

Section Corner for Section 20, 21, 28 and 29

Found - Original 15"x12"x4" stone with 2 notches on a side, and 4 notches on another side found laying flat on top of ground loose and apparently out of position. (Corner position as determined by BTs is 2 ft. southerly from found position of stone.)

DCSO BC/IP set per Ren. #60 is gone.

14" now 20" dia. 10 ft. high D. fir stob with a previously opened blaze and scribing visible "T27S" bears N.34°W., 66.0 ft. (agrees with record.) Original.

36" now 42" dia. down D. fir with a previously opened blaze, illegible scribing visible, bears S.60°E., 52.8 ft. to root hole. (agrees with record) Original.

24" now 30" dia. 1½ ft. high burnt D. fir stump, no blazes or scribing visible, bears N.29°E., 70.6 ft. (agrees with record) Original

30" Pine now 30" dia. 1½ ft. high rotted tipped out stump (unable to identify species) bears S.86°W., 24.4 ft. to root hole. (agrees with orig. record.)

4" now 12" dia. D. fir with a fully healed double blaze, bears N.7½°E., 22.6 ft. (Rec. N.9°E., 23.0 ft. dist. to center of trunk.) Ren. No. 60.

6" now 12" dia. D. fir with a fully healed double blaze, bears N.59½°E., 9.4 ft. (agrees with record.)

6" now 8" dia. maple with a partially healed single blaze scribing visible "R1W S28" bears S.3°E., 16.1 ft. (Rec. S.3°E., 15.7 ft. is to center of trunk.) Ren. No. 60

7" now 11" dia. Maple with a partially healed double blaze, scribing visible "1W S29 CS BT" bears S.61°W., 20.4 ft. (Rec. S.61°W., 20.1 ft. dist. to center of trunk.) Ren. No. 60

Set - Corner position determined from original and Ren. No. 60 bearing trees. A DCSO brass cap on a 1½" O.D. x 32" long I.P. is set and protrudes 6" above ground. The original corner stone is set along south edge of BC/IP with 2 notches on south and 4 notches on east edge, top of stone protrudes 6" above ground and measures 9" x 3" wide. A 2½ ft. dia. mound of stone surrounds corner. Cap is mkd. "Douglas County Surveyor T27S S20 S21 S29 S28 R1W 1988".

No new accessories. Corner is approx. 60 ft. north of Forest Service Rd.# 2792-086.

6/29/88

1/4 Corner for Section 30 only.

196

Found - 2½" iron pipe with brass cap mkd. as per Ren. #160  
An 8" cedar bears S.64°W., 15.8 ft. visible scribing  
An 8" hemlock bears N.9°W., 17.8 ft. visible scribing.  
A 16" hemlock stump bears S.44°E., 19.9 ft. visible scribing.  
New BT - A 7" cedar bears S.25°E., 14.9 ft. scribed "¼S30BT".  
Set ½" brass washer in BT face marked "LS 1035".

10/12/88

Witness Corner For Closing Corner Sections 25 and 36, T.27-2

197

Found - A 1½" iron pipe with brass cap extending 14" above ground marked as per Ren. #20.  
An 18" cedar bears N.23°E., 12.0 ft. visible scribing.  
A 20" hemlock, dead and down, bears S.12°E., 40.0 ft.  
New BT - 5 ft. D. fir bears S.14°E., 30.7 ft. scribed "WC" on small upper blaze and "BT" on small lower blaze. Set ¼" brass washer in BT face marked "LS 1035".

198

Center 1/4 Corner, Section 19

Found - 2½" iron pipe with 3" brass cap with trees which bear: Ren. #156  
10" hemlock bears N.63°W., 55.7 ft. healed face. (Rec. N.63°E.)  
12" hemlock bears S.86°E., 26.6 ft. healed face. (Rec. N.86°W.)

I recorded correct bearings on BT tags.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
June 29, 1988  
C.S. 62/52

Gerald V. Nygren  
October, 1988  
C.S. 63/69

James D. Artman  
For: U.S.F.S.  
May 1990  
C.S. 63/104