

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 27 T. S. R 1 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

199

James Artman
For: USFS
May 1990
C.S. 63/104

1/4 Corner for Sections 19 and 30
Found - A 1" iron pipe with a 2½" brass cap 16" above the ground, in a 20" dia. rock mound. Ren. #103
16" cedar (stump) now down (record) S.5°E., 12.5 ft.
30" cedar (snag) bears N.20°E., 49.0 ft. scribing visible. (Record N.17°E.) Ren. No. 103
42" D. fir (stump) bears S.32°E., 56.0 ft. scribing visible.
16" cedar (stump) bears S.32°W., 41.6 ft. scribing visible. (Rec. S.30°E.) Ren. No. 155
New BTs - 4" D. fir bears N.16°30'E., 55.4 ft. I scribed "1/4 S19 BT" alum tag marked "ARTMAN RLS 2268" nailed flush to BT face.
4" D. fir bears S.88°W., 60.8 ft. I scribed "1/4 S30 BT" alum. tag marked "ARTMAN RLS 2268" nailed flush to BT face.
Painted and tagged all BTs. Enlarged rock mound to 36" dia.

May 1990

Mark Smalley
For: Rsbg For Pr
Sept. 1990
C.S. 63 / 104

1/4 Corner for sections 9 and 16. Ren. # 112 & 194
Found - 2" brass cap on an iron pipe found pulled out by logging. Ren. # 186
26" D. fir N.6 3/4°W., 89.2 ft., now a stump. Ren. # 186
Aluminum cap on an iron rod stamped "B02" N. 6 3/4°W., found at 62.3 ft. not 63.2 ft. Ren. # 186
34" D. fir N.60°E., 30.4 ft., now a stump. Original B.T.
13" D fir S.11½°E., 17.3 Ft. Now bent over stump. Ren. # 112
15" Chinquapin S.89½°W., 74.9 Ft. now a stump. Ren. # 186
Aluminum cap on an iron rod stamped "B01" S.89½°W., 94.8 Ft Ren. # 186
Set - Reset the county surveyors brass cap and iron pipe in their proper location from the bearing trees.
No new BTs available, as area has recently been clearcut.
Location - Just below toe of fill on forest service road.

200

Sept. 1990

Douglas County Surveyors Office
Randall Smith
Terrie Franssen
July 1, 1991
C.S. 64/17

East 1/4 Corner for Sec. 12 only, T.27-2
Found - A 2½" dia. brass cap on a 1¼" O.D. iron pipe leaning south of plumb, protrudes 12" above ground. Ren. No. 126
12" now 16" dia. D. Fir with a fully healed single blaze bears N.4°W., 18.6 ft. (Rec. N.4°W., 19.0 ft. dist. is a slope measurement) Ren. No. 126
6" now 9" dia. D. fir with a fully healed single blaze bears S.49°W., 46.8 ft. (Rec. S.49°W., 44.8 ft.) Ren. No. 126
Set - BC/IP returned to plumb position, protrudes 2" above a 2 ft. mound of stone. # 202
New BTs - 5" dia. Cedar double blazed and scribed "1/4 S12 CS BT" bears N.41½°W., 15.8 ft.
8" dia. D. fir double blazed and scribed "1/4 S12 CS BT" bears S.63°W., 51.7 ft.
BC/IP is in a cut bank on the north side of a grav31 road, 25 ft. from centerline.

201

7/1/91

Douglas County Surveyors Office
Randall Smith, Stephen Flause
June 3, 1993 C.S. File 64/43

East 1/4 Corner for Sec. 12 only, T.27-2
Found - 2½" dia. Brass cap. on a 1¼" O.D. iron pipe, protrudes 2" above a 2 ft. dia. mound of stone. See Ren. # 201
12" now 16" dia. D. Fir with a fully healed single blaze bears N.4°W., 18.0 ft. (rec. N.4°W., 18.6 ft.)
5" now 5" dia. Cedar with a partially healed double blaze, scribing visible "¼ S12 CS BT" bears N.41½°W., 15.8 ft.
BT's in slide area -
6" now 10" dia. D. Fir with a fully healed single blaze, bears S.50½°W., 48.6 ft. (rec. S.49°W., 46.8 ft.)
8" now 8" dia. D. Fir with a partially healed double blaze, scribing visible "¼ S12 CS BT" bears S.62°W., 54.2 ft.
32" dia. D. Fir with BT tag on ground numerous axe mark and blazes or scribing dated by ring count approx. 30 yrs old. Tag marked "¼ S12 only on new BT Hendrikson S.33°W., 56.8 ft" bears S.37½°W., 66.5 ft. (unrecorded BT?)
New Accessories -
20" dia. D. Fir double blazed and scribed "¼ S12 CS BT" bears N.82°W., 118.3 ft.
10" dia. Cedar double blazed and scribed "¼ S12 CS BT" bears N.43½°W., 37.7 ft.

202