

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 1 W. R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

28

Section Corner to Sections 35 and 36 only, T26-1W.
Found - 16x10x5" Stone, firmly set mkd. with 1-5 notches.
20" Fir, now down, N.76°E. 17.8 ft., broken face & scribe
marks visible.
9" Fir, now down, N.87°W. 6.6 ft., tree opened, pitched
over scribe visible.

Set - Brass Cap at Cor.Mkd: County Surveyor's T26S R1W S 35 | S 36
Office, 1969 T27S S 1

New BT's: 30" D.Fir N.74°E. 22.0 ft. mkd: T26S R1W S36 CS BT.
30" D.Fir N.11°E. 22.4 ft. mkd: T26S R1W S36 CS BT.

This corner lies in E. edge or clear cut unit 49.5 ft. E. of Cor. 1 & 2.
10/27/69

29

Section Corner to Sections 1 and 2, T27-1W.
Found --Unrecorded Alumn. Cap Mkd: USPC Prop.cor. S 35
RE 4287 S 2 | S 1
Possible S.E. BT. down, and out of place lying on face.
20" Hemlock S.63°E. 52.6 ft. mkd: S 1 BT.

New BT: 18" Hemlock S.47°E. 62.0 ft. mkd: T27S R1W S1 CS BT.
This corner lies on E. side of cut unit on top of ridge, running N.
10/22/69

30

W. C. 1/4 Corner to Section 36 only, T26-1W. (South Boundary)

Found - No trace of Stone or N.W. BT as they fall in road.
10" W.Fir, now dead, N. 6° E. 37.6 ft., scribe visible. #125

Set - Brass Cap at Witness Corner Mkd: County Surv. T 26 S R1W 1/4 S36
Office, 1969 T 27 S
W.C. 55' East to

New BT: 28" D.Fir N.74°W. 94.5 ft. mkd: W.C. 1/4 S36 CS BT.
Bearing Object: RR Spike in Rock cut Bank 4' above Road, N.36°E. 47.1 ft.
10/27/69

31

Section Corner to Sections 7 - 8 - 17 - 18.
Found - Large Stone at Corner about right size, but no marks found.
36", now 47" D.Fir, N.23°E. 31.0 ft., opened for scribe, found
old axe work & parts of scribing badly burnt & rotten.
No trace of N.W.-SW-or SE BT's. N.W. tree went down Little River.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
Office S 7 | S 8
1969 S 18 | S 17

New BT's: 6" W.Fir N.2°E. 21.9 ft. mkd: T27S R1W S8 CS BT.
12" W.Fir N.16°W. 20.2 ft. mkd: T27S R1W S7 CS BT.
6" D.Fir West 11.0 ft. mkd: T27S R1W S18 CS BT.
8" Cedar S.50° E. 93.5 ft. mkd: T27S R1W S17 CS BT.

10/20/69

32

1/4 Corner to Sections 6 and 7.
Found - Stone set at 1/4 Cor. mkd. "1/4" on the north face. #169
24", now 34" Cedar, S.21°E. 11.2 ft., shows good scar.
8", now 22" Fir, N.52°E. 10.0 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
Office 1/4 S 6
1969 S 7

All Bearing Trees O. K. and Tagged.
10/21/69

Section Corner to Sections 11 - 12 - 13 - 14.
Found - No trace of Corner Stone. #178

10", now 11" Yew, N.73°E. 5.9 ft., face rotted, no scribe.
34", now 39" D.Fir, S.30°E. 29.0 ft., shows good scar.
18", now 21" Hemlock, S.69°W. 6.6 ft., scribe visible.
18", now 20" Hemlock, N.26°W. (Rec N32°W) 26.4 ft., scribe visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
Office S 11 | S 12
1969 S 14 | S 13

New BT's: 30" D.Fir N.68°E. 21.8 ft. mkd: T27S R1W S12 CS BT.
10/23/69

John M. Powell
Frank Jones & W. Penley
October, 1969 C. S. File No. 54/94

RE-RENEWED, SEE CORNER NO.

RE-RENEWED, SEE CORNER NO.

RE-RENEWED, SEE CORNER NO.