

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 1 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 5 - 6 - 7 - 8. 40
 Found - 12x12x6 Stone, firmly in ground mkd. with correct notches.
 14", now 26" D. Fir, N. 12½° E. 34.3 ft., shows good scar.
 14", now 26" D. Fir, S. 77° E. 19.1 ft., shows good scar.
 16", now 28" D. Fir, S. 81° W. 6.6 ft., shows good scar.
 12", now 39" D. Fir, N. 25½° W. 54.8 ft., shows good scar.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969

T 27 S	R 1 W
S 6	S 5
S 7	S 8

All Bearing Trees O.K. and tagged.
 This corner lies about 35 ft. west of ravine, course S. 20° W.
10/28/69

East ¼ Corner to Section 24, T27-1W. 41
 Found - 1" Iron Bolt at ¼ corner, See Ren. #1.
 Orig. 22" D. Fir, now out of ground, S. 61° E. 19.8 ft., tree on face.
 Orig. 30" D. Fir, now stump, out of ground, N. 59° W. 14.5 ft., scribe visible.
 Orig. 32", now 34" D. Fir, S. 40° W. 26.4 ft., tree opened, scribe visible. Ring count in correct to face.
 42" D. Fir S. 72° W. 29.8 ft. (face), bark scribed "¼ S24 BT".
 No trace of 1927 GLO Brass Cap.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1969

R	T 27 W	R
1 ¼	S 24	1
W		E

Reblzd. & Resbd: 42" D. Fir S. 72° W. 31.6 ft.
 Orig. Distance btwn. corner of 19 & 24 is 88.4 ft. I find it 46.0 ft.
10/22/69

South ¼ Corner to Section 35 only, T26-1W. 42
 Found - No trace of Corner Tree due to logging.

10" Hemlock, now burnt stump, N. 46° E. 13.7 ft., scribe visible but burnt.
 24" Fir, now stump, N. 50° W. 13.2 ft., shows good scar.
 - Old Bearing Tree N. 50° W. 13.2 ft., high stumped & tagged.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969

T26S ¼	S 35	R1W
T27S	¼	

New BT: 55" D. Fir N. 82½° W. 189.3 ft. scribed "¼ S35 CS BT".
 This corner lies 70 ft. E. of ¼ Corner Sec. 2, T27-1W, see below.
11/3/69

North ¼ Corner to Section 2, T27-1W. 43

Found - Corner Stone 20x18x15, mkd: "¼" on west face. #173
 Unrecrd. Alum. Cap by Corner Stone Mkd: U.S.P.C. Prop. Cor. T27-1W
 RE 4287 1963

10" Hemlock S. 56° E. 49.9 ft., remains of old stump. S 2 only
 New BT's: 22" Hemlock S. 69° W. 72.0 ft. mkd: ¼ S 2 CS BT.
 22" Hemlock S. 26° W. 105.0 ft. mkd: ¼ S22 CS BT.
 This corner lies in west side of large cutting unit 125 ft. E. of timber and ¼ cor. Sec. 35 only lies East 70 ft.
11/3/69

RE-RENEWED. SEE CORNER NO. #173

Section Corner to Sections 1 and 12, T27-1W. 44

Found - 1927 GLO Brass Cap buried and marked incorrectly. Not having any stamps, I remove marks referring to Sec. 6-7.

Reset Brass Cap at Sec. Cor., now mkd: General Land Office 1927

Found - Orig. Corner Stone in place.
 34", now 38" D. Fir, S. 20° W. 19.8 ft., shows good scar.
 6", now 10" Hemlock N. 89° W. 4.0 ft. shows good scar.
 The Section Corner to Secs. 6 & 7, T27-1E found O.K.
10/30/69

¼ Corner to Section 6 only, T27-1E. (W. Bdry) 45

Found - 1927 GLO Brass Cap at ¼ Corner, properly marked.
 6", now 20" D. Fir, N. 53° E. 79.2 ft., shows scar.
 8", now 20" D. Fir, N. 84° E. 161.0 ft., shows scar.
 New BT's: 13" D. Fir N. 82½° E. 16.0 ft. mkd: "¼ S6 CS BT".
 14" D. Fir S. 68° E. 23.7 ft. mkd: "¼ S6 CS BT".
10/30/69

John M. Powell
 Frank Jones & W. Penley
 Oct. & Nov. 1969 C.S. File No. 54/94