

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 1 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

John M. Powell
Frank Jones & W. Penley
December, 1969 C. S. File No 54/94

Wit. Cor. $\frac{1}{4}$ Corner to Section 4 only, T27-1W. 82
 Found - Stone, firmly set, at Wit. Corner.
 14", now 37" D. Fir, S. 30° E. 15.4 ft. (13.9 Rec.), shows good scar.
 24", now 31" Hemlock S. 26° W. 4.6 ft., shows good scar.
 Set - Brass Cap at Wit. Cor. Mkd: County Surveyor's T26S R1W $\frac{1}{4}$
 Office, 1969 T27S S 4
 W. C. 13.2 ft. East to $\frac{1}{4}$ Corner
 Bearing Trees O.K. and Tagged. This corner lies 4.0 ft. south of 40' bluff.
12/1/69

$\frac{1}{4}$ Corner to Sections 26 and 27. 83
 Found - 12x8x8 Stone, firmly set, mkd: " $\frac{1}{4}$ " on west face.
 16", now 26" D. Fir, S. 32 $\frac{1}{2}$ ° E. 12.9 ft., shows good scar.
 6" D. Fir, now dead, S. 37 $\frac{1}{2}$ ° W. 9.9 ft., opened for scribe, " $\frac{1}{4}$ ST".
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
 Office, 1969 $\frac{1}{4}$ S 27 | S 26
 New BT: 8" D. Fir S. 39° W. 25.4 ft. mkd: " $\frac{1}{4}$ S27 CS BT".
12/3/69

Section Corner to Sections 22 - 23 - 26 - 27. 84
 Found - 15x12x10 Stone, firmly set, mkd: 2 notches on S & E. sides.
 12", now 19" D. Fir, N. 69° E. 21.1 ft., shows good scar.
 12", now 19" Pine, N. 44° W. 11.2 ft., shows good scar.
 40" D. Fir, now down, all rotted, S. 18° W. 34.3 ft.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
 Office 1969 S 22 | S 23
 S 27 | S 26
 New BT's: 14" Pine S. 24° E. 35.2 ft. mkd: "T27S R1W S26 CS BT".
 13" D. Fir S. 52 $\frac{1}{2}$ ° W. 12.0 ft. mkd: "T27S R1W S27 CS BT".
12/3/69

$\frac{1}{4}$ Corner to Section 17 and 20. 85
 Found - No trace of Iron Rod as of Ren. #5, but found squared stake.
 12", now 14" D. Fir, S. 26 $\frac{1}{2}$ ° W. 38.7 ft., pitched over scribe visible.
 Orig. 14" D. Fir, now burnt stump, N. 62° E. 26.4 ft.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T. 27 S R 1 W
 Office 1969 $\frac{1}{4}$ S 17
 S 20
 Bearing Object: $\frac{3}{4}$ " Iron Rod N. 40° E. 25.0 ft.
 This corner falls in clear cut unit about 490 ft. west of logging road.
 (Marker on Road) 12/2/69

Section Corner to Sections 16 - 17 - 20 - 21. 86
 Found - 15x12x8 Stone, firmly set, 4 notches on East Side.
 14", now 24" Cedar, N. 71° E. 25.7 ft., has rotted face.
 30", now 38" Cedar, S. 65° W. 39.6 ft., has rotted face.
 28", now 35" Hemlock S. 70° E. 33.0 ft., scribe visible, "T".
 30", now 40" Hemlock, N. 48° W. 18.5, scribe visible.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
 Office 1969 S 17 | S 16
 S 20 | S 21
 New BT's: 13" Hemlock S. 38° E. 19.0 ft. mkd: "T27S R1W S21 CS BT".
 30" Hemlock N. 19° E. 30.3 ft. mkd: "T27S R1W S16 CS BT".
 8" Hemlock S. 76 $\frac{1}{2}$ ° W. 35.5 ft. mkd: "T27S R1W S20 CS BT".
12/2/69

$\frac{1}{4}$ Corner to Sections 20 and 21. 87
 Found - No trace of Corner Stone.
 20", now 30" Hemlock N. 34° E. 30.4 ft., scribe visible.
 12" Fir, now down, S. 65° W. 23.1 ft., opened for scribe, " $\frac{1}{4}$ S20 BT".
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 1 W
 Office, 1969 $\frac{1}{4}$ S 20 | S 21
 New BT: 42" D. Fir N. 57° W. 39.2 ft. mkd: " $\frac{1}{4}$ S20 CS BT".
12/2/69