

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 11 and 12. 103
Found - 1957 C.S. Brass Cap, See Ren. #4, & stumps of BT's., burned.
52" R.Fir Stump N.57 $\frac{1}{2}$ °W. 38.0 ft., scribe visible on burned blaze.
58" R.Fir Stump, N.26°E. 113.7 ft., scribe visible on burned blaze.
Orig. BT's. badly burned.
Set - 5/8" I. R. 10.0 ft. south and 5/8" I.R. 15.0 ft. south.
6.0 ft. Steel fence post alongside Brass Cap.
This corner lies in clear cut area grown up to dense greasewood brush.

Section Corner to Sections 1 - 2 - 11 - 12. 104
Found - 1962 C. S. Brass Cap set in mound of stone 2 ft. high, See Ren.#16.
Orig.30" D.Fir, alive, S.79°E. 30.4 ft., opened blaze, pitched & healing.
Orig.24" D.Fir, alive, S.39°W. 35.6 ft., shows good scar.
Orig. N.E. and N.W. Bearing Trees down.
New BT's: 20" R.Fir S.17°E. 31.1 ft., mkd: T27S R2W S12 CS BT.
22" D.Fir N. 6°W. 11.3 ft. mkd: T27S R2W S 2 CS BT.
8" Yew N.35°E. 27.1 ft. mkd: T27S R2W S1 CS BT.
14" R.Cedar blazed but not scribed bears South 14.0 ft.
Left bank of creek 10 ft. wide, flowing N. curving to N.W. bears
East 42.0 ft. and same creek bears North 38.0 ft.

West $\frac{1}{4}$ Corner to Section 32. 105
Found - 3/4" I.R. at corner point, unrecorded.
Orig. 12", now 18" Fir, alive, S.44°E. 10.6 ft., shows good scar,
Rescribed: " $\frac{1}{4}$ S32 CS BT".
Orig. 12", now 13" Fir, 5' high stub, N.3 $\frac{1}{2}$ °W. 12.5 ft., scribe
visible on unhealed blaze, badly decayed. #207
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W
Office, 1968 $\frac{1}{4}$ S 32
New BT: 30" D.Fir N. 32° E. 21.6 ft. mkd: " $\frac{1}{4}$ S32 CS BT".
This corner lies on steep N.E. slope in old growth fir timber
approx. 460 ft. north of ridge top.

$\frac{1}{4}$ Corner to Sections 22 and 23. 106
Found - U.S. Plywood Alum. Cap in place & BT's., See Ren. #26.
60" Cedar Stump N.37°W. 53.0 ft. scribed " $\frac{1}{4}$ S22" & tag #4287.
30" Cedar Stump S.58°E. 39.6 ft. scribed " $\frac{1}{4}$ S23".
New BT's: 10" Hemlock (Schoolmarm) N.53°W. 47.2 ft. mkd:" $\frac{1}{4}$ S22 CS BT".
8" D.Fir S.39°E. 45.5 ft. mkd:" $\frac{1}{4}$ S23 CS BT".
Set - 6.0 ft. steel fence post alongside Brass Cap.
This corner lies at foot of N.W. slope in marshy area.

$\frac{1}{4}$ Corner to Sections 23 and 26. 107
Found - 1 $\frac{1}{2}$ " I.P. & alum. cap, see Ren. #27.
Orig.36", now 38" Hemlock Stump, S.88°E. 16.5 ft., scribe visible
on open blaze.
Orig.20", now 24" Hemlock Stump N.61°W. 14.5 ft., scribe visible
on open blaze.
New BT's: 6" D.Fir S.12°W.5.6 ft. mkd:" $\frac{1}{4}$ S2 CS BT"
6" D.Fir N.41°E. 26.2 ft. mkd: " $\frac{1}{4}$ S23 CS BT".
This corner lies on top of spur sloping north in D.Fir reproduction.
FO. O.K. 4180 R.L.S.#1654 SEE M 79-44

$\frac{1}{4}$ Corner to Sections 23 and 24. 108
Found - No trace of 2 $\frac{1}{2}$ " Alum. Cap as called for in Ren. #28, probably
removed during recent logging.
Orig. 10", now 18" Hemlock stump, S.85°E. 21.1 ft., scribe visible
on opened blaze.
Orig. 8", now 10" Yew, N.80°W. 15.2 ft., down under logging debris,
scribe visible. #189
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W
Office, 1968 $\frac{1}{4}$ S 23 | S 24
New BT's: 5" Hemlock S.21°E. 20.7 ft. mkd:" $\frac{1}{4}$ S24 CS BT".
10" Yew N.75°W. 154.6 ft. mkd:" $\frac{1}{4}$ S23 CS BT".
This corner lies 135 ft. N. of creek 6 ft. wide, course N.E.

11/26/1968

Vernon "Ray" Gray
Frank Jones & V. Perron
November, 1968
C. S. File No. 54/40