

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

120

Section Corner to Section 29 - 30 - 31 - 32.  
Found - 2 1/2" Alum. Cap set by U.S. Ply., See Ren. #24.  
17" Hemlock, now badly burnes tump, N.51°W. 58.8 ft., blaze destroyed.

All other BT's. destroyed by logging.  
Set -6 ft. Steel Fence Post alongside Alum. Cap.  
New BT's: 26" D.Fir N. 8° W. 161.0 ft. mkd: "T27S R2W S30 CS BT".  
16" W.Fir N.89°E. 117.6 ft. mkd: "T27S R2W S29 CS BT".  
No trees available to south. This corner lies in logged-off unit on moderate N.E. slope.

121

Closing Corner to Sections 16 and 15.  
Found - 1 1/2" I.P. with 1" Pipe & U.S. Plywood Alum. Cap, See Ren. #50.  
Orig. 7",now 16" Cedar Snag, S.55°W. 33.0 ft., scribe visible on prev. opened blaze.

Shrum's BT. to S.E., also Snag.  
New BT's: 10" D.Fir S.12°W. 41.2 ft. mkd: T27S R2W S16 CC CS BT.  
13" D.Fir S.61°E. 17.6 ft. mkd: T27S R2W S15 CC CS BT.

This corner lies on moderate northerly slope, See sketch below.  
Cad. S 9 | S 10 N. 88 3/4° E. U.S. Ply.  
B. Cap 1957 142.4 ft. S16 | S15 Alum. Cap

122

South 1/4 Corner to Section 3 only.  
Found - 1957 Cad. Brass Cap, in place.  
13", now 14" Fir, alive, N.61°W. 28.4 ft., face burned.  
Rescribed: "1/4 S 3 BT CS".

No trace of N.E. Bearing Tree, due to logging.  
New BT: 10" D.Fir N. 7° E. 47.6 ft. mkd: "1/4 S3 CS BT".  
This corner lies 74 ft. E. of creek 6 ft. wide, flowing N.W.  
The N 1/4 Sec. 10, See Ren. #51, bears S.60°E. 47.3 ft., a U.S. Ply.Alum. Cap and live BT.

123

1/4 Corner to Sections 9 and 10.  
Found - 1957 Cadastral Brass Cap, in place.  
Orig. 22", W. Fir, now snag, S.73 3/4° W. 14.5 ft., scribe visible.  
No trace of Orig. Madrone S.E.

1951 BT to S.E. Lying face down & in falling hit 1957 N.W. BT, leaving only a 6 ft. high stub, showing scribe.  
New BT's: 16" Cedar N.78°W. 17.9 ft. mkd: "1/4 S9 CS BT".  
10" Hemlock N. 38° E. 42.0 ft. mkd: "1/4 S10 CS BT".  
This corner lies on N - S cutting line, cut-off in section 10.

124

1/4 Corner to Sections 2 and 3.  
Found - 1957 Cadastral Brass Cap, in place.  
8",now 10" Cedar, N.86°E. 36.3 ft. scribed 1/4 S2 BT Dan Boone", healing.

8",now 10" Cedar, S.34°E. 57.4 ft., scribed: "1/4 S BT NN", healing.  
New BT: 9" D.Fir S.71°W. 5.3 ft. mkd: "1/4 S3 CS BT".  
This corner lies about 280 ft. N. of Little River Road on moderate S. slope.

125

1/4 Corner to Sections 32 & 33.  
Found - Orig. 36",now 40" Fir, sawed stump, N.53 2/3° E. 23.8 ft., Open, and find 1/4 S33 scribe and reverse.  
36",now 40" Fir, sawed stump, N.30°W. 5.9 ft., prev. opened, shows scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W  
(Set 6' steel fence post) Office, 1968 1/4 S 33 S 32  
New BT's: 10" Hemlock N.80°E. 14.6 ft. mkd: "1/4 S33 CS BT". #209  
12" Hemlock S.45 1/2°E. 23.5 ft. mkd: "1/4 S33 CS BT".

No trees available west of line in section 32.  
Note - The 1/4 corner recorded in Ren. #23, bears S.63°E. 20.3 ft., a 1 1/2" I.P. with 1" Steel Pipe & 2 1/2" Alum. U.S.Ply.Cap with BT. apparently set from wrong bearing & distance from Orig. BT to N.W.  
SHRUM'S COR. - REMOVED CAP. JAN. 1969 - C.S. FILE 511254  
12/13/68

Vernon "Ray" Tracy  
Frank Jones & V. Perron  
December, 1968 C. S. File No. 54/40

Fl. ok 4/84  
By GEISLER  
11/90-55

RE-RENEWED SEE CORNER NO. #174  
RE-RENEWED SEE CORNER NO. #209