

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

126

1/4 Corner to Sections 17 and 20.  
Found - 1964 C.S. Brass Cap, properly marked & set, See Ren. #45.  
Orig. 11" W. Fir, alive, N. 11° W. 6.6 ft., "S" scribe visible  
Orig. 20" Hemlock S. 30° W. 21.1 ft., shows good scar.  
New BT: 10" R. Fir N. 45° E. 10.8 ft. mkd: "1/4 S17 CS BT."  
This corner lies on flat approx. 75 ft. W. of logged unit,  
cutting line N. & S.

RE-RENEWED, SEE CORNER NO. #219

127

South 1/16 for Sections 3 and 2.  
Found - 1957 GLO Brass Cap, properly marked.  
13" Cedar, now 15", S. 37° E. 32.3 ft., shows good scribing.  
45", now 50" D. Fir, S. 66 1/2° W. 66.7 ft., shows good scar.  
New BT: 6" Hemlock N. 63° W. 33.2 ft. scribed S 1/16 S 3 CS BT.  
Note - This corner lies on swampy ground.

FOOK 9/84  
BY GEISLER  
M 90-55

128

Section Corner to Sections 27 - 28 - 33 - 34.  
Found - 1 1/2" I.P. with 1" Steel Pipe & Alum. Cap mismarked for  
sections 27 and 28 by U.S. Plywood, See Ren. #95.  
Stumps of Orig. BT's. and new BT. All old stumps in place  
and scribe visible.  
Set - 6 ft. Steel Fence Post. (Tom Shrum will correct cap)  
New BT's: 4" D. Fir N. 25 1/2° E. 64.0 ft. mkd: S27 CS BT.  
4" D. Fir N. 73° W. 4.2 ft. mkd: S28 CS BT.  
5" D. Fir S. 69° E. 32.1 ft. mkd: S34 CS BT.  
This corner lies in flat logged off area, growing reproduction  
of D. Fir, Hemlock and Cedar.

129

1/4 Corner to Sections 14 and 23.  
Found - U. S. Plywood Alum. Cap, properly marked, See Ren. #37. #190  
Orig. 15", now 24" Fir, alive, S. 34° E. 17.8 ft., shows good scar.  
We Rescribe: "1/4 S23 CS BT"  
Orig. 15", now 24" Fir, N. 26° W. 4.6 ft., open & shows scribe marks.  
New BT: 18" D. Fir N. 78° W. 10.4 ft. mkd: "1/4 S14 CS BT".  
This corner lies on very gentle N.E. slope in old growth timber.

RE-RENEWED, SEE CORNER NO. #190

12/23/68

130

South 1/4 Corner to Section 11.  
Found - Orig. 22" W. Fir, now 36" sawed stump, S. 23° E. 17.2 ft.,  
open & find "1/4 S14 BT" scribe & reverse.  
Old N.E. BT. down, shows scar.  
No trace of corner stone due to fire trail at corner point.  
Set - Brass Cap Mkd: County Surveyor's T 27 S R 2 W  
Office, 1968 1/4 S 11  
New BT's: 10" Cedar S. 44° E. 51.0 ft. mkd: "1/4 S11 CS BT".  
10" Cedar S. 50° W. 53.2 ft. mkd: "1/4 S11 CS BT".  
The S 1/4 Sec. 11 recorded Ren. #444 bears N. 19° E. 27.1 ft.  
Note - On subsequent visit to this corner, we find U.S. Plywood, Ren. #444,  
Aluminum Cap removed & logging activity beginning.  
Mark More BT's: 40" D. Fir Stump N. 84° E. 37.1 ft. mkd. "1/4 S11 CS BT".  
48" D. Fir Stump N. 75° W. 43.3 ft. mkd: "1/4 S11 CS BT".  
U.S. Plywood's BT. recorded in Ren. #444:  
10" Yew N. 9° E. 54.2 ft., scribe visible & Alum. Tag #4287.  
Cedar BT's. mkd. by U. S. in Sec. 14. (Both O.K. at this time)  
12/23/68

131

1/4 Corner Section 31 only, T27-2W. See ALSO #94  
Set - 2 1/2" Aluminum Cap mkd: "1/4 S31 only, T27S R2W R.E. 4287".  
6" D. Fir N. 39° E. 73.5 ft. "1/4 S31 BT R.E. 4287".  
40" Cedar Stump N. 65° W. 45.2 ft. "1/4 S31 B.T. R.E. 4287".

By Thomas E.  
Shrum, Jr.  
For: U.S. Ply  
Dec. 1968  
C. S. File  
M 37 - 17

132

1/4 Corner Section 6 only, T28-2W. See ALSO #94  
Set - 2 1/2" Aluminum Cap mkd: "T28S R2W S6 R.E. 4287".  
12" Cedar S. 30° E. 11.9 ft. mkd: "S6 BT R.E. 4287".  
18" Cedar S. 70° W. 34.3 ft. mkd: "S6 BT R.E. 4287".