

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

169

Section Corner for 1 and 12 only.

Found - 3/4" Iron rod set by Johnstone in 1962 with corner stone lying alongside. Ren. #10 Corner stone has five notches on one edge.

A 31" W. Fir snag bears S.50°E., 11.5 ft. scribing visible on previously opened blaze.

A 11" D. Fir bears N.31°W., 22.2 ft. Has healed scars.

A 37" D. Fir bears N.71°W., 14.5 ft. No scar or scribing visible.

A 33" D. Fir snag bears S.52°W., 23.8 ft. Has a healed scar.

A 17" D. Fir bears S.28°W., 104.2 ft. (Rec. S.30°W., 104.5 ft.) scribing visible "T27S R2W S12 BT" on a double blaze. Ren. #157.

Lower blaze has an alu. washer set in face mkd. "LS 1005".

(All measurements to center of BT's.)

Set - Removed 3/4" Iron pipe and in its place I SET a 2 1/2" Brass cap on a 1" Iron pipe stamped County Surveyors Office T27S R2W S 1 | S6
1977 S12

No new accessories. I placed County BT signs on all BT's.

Corner lies 75 ft. east of F.S. Road No. 2612D

7/7/77

Section Corner for Secs. 21, 22 28 and 27.

170

Found - A 24" stump (well rotted) bears N.68°40'E., 49.5 ft. Open and find scribing and reverse, "22 BT".

All other BT's have been destroyed by logging activities.

Set - Using the only remaining BT stump for reference, I SET a 2 1/2" brass cap on a 1" galv. I.P. stamped County Surveyors Office T27S R2W S21 | S22 1977.
S28 | S27

New BT's- A 6" D. Fir bears S.26°30'W., 49.2 ft. scribed "T27S R2W S28 CS BT" on a double blaze.

A 6" D. Fir bears N.83°W., 52.2 ft. scribed "T27S R2W S21 CS BT" on a double blaze.

A 9" D. Fir bears N.5°E., 19.1 ft. scribed "T27S R2W S22 CS BT" on a double blaze.

A 9" D. Fir bears S.48°E., 20.9 ft. scribed "T27S R2W S27 CS BT" on a double blaze.

Note: Corner lies in an old clearcut 200 ft. east of logging spur.

Note: Approx. 150 ft. north of this corner are two stumps with BLM BT signs & healed blazes. I opened both & found the scribing nearly all destroyed. These may be BT's from Derricks survey. Creek called for in GLO notes is 653 ft. north of corner as renewed. (Record, 653.4 ft.)

10/3/77

171

Section Corner for 3 and 4 only. (south)

Found - Orig. stone set on 7/17/05 by Roberts. Stone is firmly set & covered with 2" of soil. Stone, 16"x10"x6" is marked with 5 grooves on the south face, and 3 notches on the east edge.

A 30" Fir stump bears N.51 1/2°W., 93.06 ft. scribing & reverse visible "T27S R2W S4 BT". Orig. BT.

A well decomposed stump (root crown) bears N.31°E., # 258 31.68 ft.

There are no other remaining orig. BT's. Placed a County BT sign on the stump.

A 1 1/2" I.P. set by Lecklider, bears N.26°E., 1.75 ft. Ren. #7

A 3" brass cap set by BLM bears N.42 1/2°W., 14.70 ft. stamped: "Bureau of Land Management T27S R2W S4 | S3 1957"

Set - Referencing the corner stone, I move the stone aside and in its place I set a 2 1/2" Brass cap on a 1" Gal. Iron pipe. Cap stamped County Surveyor's Office T27S R2W S4 | S3 1977
S9

I deposit the corner stone alongside.

Also found - Bearing trees which were set by BLM:

A 16" Cedar bears N.24 1/2°W., 81.0 ft. from this renewal.

A single blaze is nearly healed over. Some scribing visible.

A 10" D. Fir bears N.24 1/2°E., 46.3 ft. from this renewal. Has a single healed blaze.

Placed County BT signs on both trees.

No new BT's set.

12/22/77

Jan 78

Dennis Gaylord
U.S. Forest Service
Deputy - Doug. Co.
Surveyors Office
Travis Worthen
July 7, 1977
C.S. 59/38

Dennis Gaylord
U.S. Forest Service
Deputy - Doug. Co.
Surveyors Office
Randal Lopez
Oct. 3, 1977
C.S. 59/40

Dennis Gaylord
USFS - Deputy
Doug. County
Witness: Randal
Lopez
Dec. 22, 1977
C.S. 59/42