

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

172

Center 1/4 Corner for Section 11.
Set - 2 1/2" Galv. I.P. with 3" brass cap stamped T27S R2W C 1/4
S11 RLS 1005 1978.
BT's - 22" D. Fir bears S.87°W., 22.2 ft. scribed "C 1/4 S11 BT"
22" D. Fir bears S.51°E., 48.8 ft. scribed "C 1/4 S11 BT"
Nailed brass casher marked RLS 1005 to lower blaze of each BT.

Romanso E. Ware
PLS #1005
For: U.S. Forest
Service
May 1978
M 70 - 16

5/78

173

1/4 Corner for Section 10 only. (North)
Found - 8" Hemlock, S.8°E., 38.1 ft. scribed "S10 N 1/4 BT".
3/4" I.R. with 2 1/2" alum. cap bears S.13°23'E., 7.4' from
true corner. Ren. #51
Set - 2 1/2" I.P. with 3" brass cap mkd. T27S R2W 1/4 S10 1978 RLS
1005, in mound of stones.
Scribed: 13" W. Fir bears S.85°W., 45.7 ft. "1/4 S10 BT"

174

1/4 Corner for Secs. 9 and 10.
Found - 10" W. Fir bears N.38°E., 42 ft. Good scar (Rec. Hemlock)
20" Cedar bears N.78°W., 17.9 ft. "1/4 S9 CS BT"
8" Cedar snag bears N.40°W.- 46.2 ft. "1/4 S9 BT". Ren. #123
Set - 2 1/2" galv. i.p. with 3" brass cap marked T27S R2W 1/4 S9
S10 1978 RLS 1005 in rock mound.

Center 1/4 Corner for Sec. 10 *FOOK & DeGroot 8/2007 2007-117*
Set - 2 1/2" Gal. I.P. with 3" Brass cap marked T27S R2W C 1/4 + S10
1978 RLS 1005, in rock mound.
Scribed- 10" Cedar bears N.57°W., 31 ft. "C 1/4 S10 BT"
8" D. Fir bears N.57°E., 31 ft. "C 1/4 S10 BT".
Each tree has brass washer marked RLS 1005 nailed to lower blaze.

176

Closing corner for Secs. 16 and 15 only
Found - 3/4" I. Rod with 2 1/2" Alum. cap marked U.S.P.C. Property
Corner T27S R2W 16/15 RE 4287. Ren. #121
10" D. Fir bears S.12°W., 41.2 ft. scribes visible.
16" Cedar snag S.50°W., 33 ft. scribes visible.
New BT's-8" W. Fir bears N.81°W., 40.5 ft. "T27S R2W S10 CC BT"
14" Maple bears S.62°E., 73.6 ft. "T27S R2W S15 CC BT".

177

1/4 Corner for Sec. 10 only. (South)
Found - 3/4" I.R. with 2 1/2" Alum. cap marked T27S S10 only 1/4 cor.
R2W, alongside original stone. See M29 - 27 & M29 - 28
24" Cedar N.55°W., 29.4 ft. visible scribeds.
28" D. Fir S.3°W., 9.1 ft. good scar.
New BT-s 12" Cedar S.47°W., 10.7 ft. "1/4 S10 BT" nailed alum. washer to
face.

178

1/4 Corner for Sec. 15 only. (North)
Found - 10" D. Fir bears S.40°W., 4.2 ft. from true corner.
3/4" I.R. with 2 1/2" Alum cap which bears S.74°W., 3.65 ft.
from true corner. Ren. #56
Set - 2" x 30" Galv. I.P. with 3" brass cap marked T27S R2W 1/4 S15
RLS 1005 1978, in rock mound.
Scribed: 14" Hemlock N.57°W., 9.3 ft. "1/4 S 15 BT" with brass washer "RLS
1005" nailed to lower blaze.

179

Section corner for Secs. 10, 11, 15 and 14.
Found - 2 1/2" Alum. cap on 3/4" I.R. marked "U.S.P.C. property corner
T27S 10 11 15 14 R 2 W RE 4287" Ren. #31
9" Madrone bears N.26°E., 24.6 ft. visible scribes.
11" D. Fir bears N.19°W., 34.1 ft. good scar
12" Live Oak, bears N.59°W., rotted face, badly leaning

Romanso E. Ware, PLS #1005
For: U.S. Forest Service
June, 1978
M 70 - 24 (Also see M70-27)