

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner: Sections 28, 29, 32, 33. 21
Found - 1 1/2" Iron Pipe & 15" Cedar, N. 55° W., 19.1 ft. Mkd: S29 BT.
Set - 2 1/2" Aluminum Cap and 9" Cedar, N. 26 1/2° E., 40.5 ft. Mkd: S28 BT.
44" D. Fir Stump S. 30° E., 61.5 ft. Mkd: S33 BT. 76
48" Cedar Stump, S. 1° W., 62.1 ft. Mkd: S32 BT.

1/4 Section Corner: Sections 27 and 28. 22
Found - 28" D. Fir Stump N. 84 1/2° E., 14.5 ft. Mkd: 1/4 S27 BT.
Set - 2 1/2" Aluminum Cap and 24" D. Fir Stump S. 28° W., 34.5 ft. Mkd: 1/4 S28 BT. 77

1/4 Section Corner: Sections 32 and 33. - Jan. '69 - DESTROYED CORNER 23
Found - 1 1/2" Iron Pipe & 38" D. Fir Stump, N. 53 1/2° W., 23.8 ft. (good condition)
Set - 2 1/2" Aluminum Cap & 11" Cedar, S. 48° E., 20.3 ft. Mkd: 1/4 S33 BT.
COR. IN WRONG PLACE - SEE REN. NO. 125 & NOTE. SEE C.S. 51/254

Section Corner: Sections 29, 30, 31, 32. 24
Found: - 1 1/2" I. Pipe set in 1954 from Orig. BT's. All trees have
blown down or destroyed. I now replace iron pipe
with 2 1/2" aluminum cap and reference. 120
Set - 2 1/2" Aluminum Cap
7" Yew, S. 39° W., 45.8 ft. Mkd: S31 BT.
15" Hemlock Stump N. 3° E., 33.7 ft. Mkd: S29 BT.
17" Hemlock, North 51° West., 58.8 ft. Mkd: S30 BT.
16" Cedar S. 45° E., 14.9 ft. Mkd: S32 BT.

1/4 Section Corner: Sections 29 and 32. 25
Found - 15" Cedar, N. 50° E., 11.2 ft. Rescribed: 1/4 S29 BT.
9" Cedar, S. 36° W., 19.2 ft. Mkd: 1/4 S32 BT.
Set - 2 1/2" Aluminum Cap. 84

1/4 Section Corner: Sections 22 and 23. 26
Found - 1 1/2" I. Pipe. This I.P. was set by me in 1954 from the
Orig. BT.; subsequent logging destroyed all Orig. BT's.
I now set a 2 1/2" Alum. Cap in place of the pipe. 106
Set - 2 1/2" Aluminum Cap
60" Cedar Stump N. 37° W., 53.0 ft. Mkd: 1/4 S22 RE4287
30" Cedar Stump, S. 58° E., 39.6 ft. Mkd: 1/4 S23 RE4287

1/4 Section Corner: Sections 23 and 26. 27
Found - 38" Hemlock Stump S. 88° E., 16.5 feet.
24" Hemlock Stump N. 61° W., 14.5 feet.
Scribing clear & Legible. No other trees suitable
for scribing within limits. 107
Set - 2 1/2" Aluminum Cap.

1/4 Section Corner: Sections 23 and 24. 28
Found - 18" Hemlock S. 85° E., 20.4 ft.
10" Yew, N. 80° W., 15.2 ft.
Set - 2 1/2" Aluminum Cap. 108

1/4 Section Corner: Sections 30 and 31. 29
Found - Truck Axle. Axle set by me in 1954 from Orig. BT's. which
have subsequently been destroyed. I now scribe
new references. 109
Set - 20" D. Fir Stump N. 52 1/2° E., 36.7 ft. Mkd: 1/4 S30 BT.
18" Hemlock Stump S. 23° W., 72.8 ft. Mkd: 1/4 S31 BT.

1/4 Section Corner: Sections 13 and 14. 30
Found - 14" Cedar N. 22 1/2° E., 19.3 feet.
18" Cedar Stump N. 72° W., 15.4 feet.
Set - 2 1/2" Aluminum Cap

Thomas E. Shrum, Jr.
For U. S. Plywood Corp.
November 1962
C. S. File No. 51/254

ALSO SEE SAME CORNER
date #33