

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 27 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

217

Witness Corner for Closing Corner for Secs. 32 and 33 only.
 Found - Orig. Cor. tree fd. 7.0 ft. S.0°0'45"E., 26" D. Fir with healed
 blazes & 4 notches on the East side & healed blazes on the North
 & West sides, Ren. #152
 26" D. Fir, N.44°E., 23.1 ft. Good scar
 32" D. Fir N.59°W., 25.1 ft. Good scar.
 Set - 2 1/2" I.P. with brass cap marked T27S R2W WC CC S32 S33 S4 T28S
 R2W 1980 RLS 1005 S 7.0.
 New BT - 12" D. Fir, S.50°E., 12.4 ft. "W.C. T27S R2W S32 S33 BT"
 Rescribed 26" D. Fir, N.53°E., 18.6 ft. "W.C. T27S R2W S33 BT"
 Rescribed 32" D. Fir, N.70°W., 22.0 ft. "W.C. T27S R2W S32 BT".
 Set - Fiberglass post & sign 3.0 ft. West.

218

1/4 Corner for Section 7 only of T.27-1.
 Found - 1968 County Surveyors brass cap. Ren. #89
 12" Fir, N.52°E., 16.8 ft. Scar
 16" Fir, S.24°E., 12.0 ft. Scar
 24" Fir, S.18°E., 42.9 ft. vis scribes
 Set - Post & sign 5.0 ft. North.

219

1/4 Corner for Secs. 17 and 20.
 Found - A 1964 Doug. Co. Surveyors Office brass cap on a 30" by 1 1/2" I.P.
 properly marked, disturbed by logging work. Cap leans northeast
 and protrudes 2" from ground. Ren. #45
 An orig. 14" Hemlock now a split open and down tree bears S.30°W.,
 21.0 ft. (Rec. S.29°50'W., 21.1 ft.) Tree has evidence of blaze.
 An orig. 8" Fir now a rotted stump nearly gone, bears N.11°W
 6.6 ft. (Rec. N.10°50'W., 6.6 ft.)
 a loose fragment of rotted stump has scribing in reverse reading
 "7 BT"
 A 10" R. Fir now a rotted and broken apart fir stump, bears N.45°E.
 10.8 ft. A fragment of this tree lying near stump hole has the
 scribing 1/4 S17 CS BT on the remains of an unhealed double
 blaze. Ren. #126
 Set - After determining corner position from bearing trees found (this is
 approx. the center of the location occupied by the disturbed
 knocked over brass cap & pipe), we reference out said location
 & reset 1964 brass cap. Monument is now firmly set and protrudes
 5 inches from soil.
 New BT's- A 10" DBH Cedar bears N.78°E., 7.7 ft. Tree is marked with a double
 blaze scribe 1/4 S17 CS BT.
 A 9" DBH W. Fir bears S.32°E., 13.4 ft. Tree is marked with a
 double blaze scribed 1/4 S20 CS BT.
 A 28" DBH D. Fir bears N.24°W., 46.3 ft. Tree is marked with a
 double blaze scribe 1/4 S17 CS BT.
 All new trees are tagged with DCSO BT tags.

2/17/81

220

Section corner for Secs. 17, 18, 19 and 20
 Found - A 1964 DCSO brass cap, properly marked, on a 1" I.P. protrudes
 16" from ground & is leaning northeast apparently dislodged by
 a falling tree. Ren. #46
 A cedar stake is lying near the brass cap monument, 3"x4"x18" long
 shows possible scribe marks. Ren. #46
 An orig. Fir 30" now a 33" DBH D. Fir, bears N.19 1/2°E., 33.7 ft.
 Tree has healed double blaze, no scribing visible.
 An orig. Cedar, 50" is now gone, removed by road work.
 An orig. Fir, 18" recorded as a rotted stump & log in Ren. #46 is
 no longer in evidence.
 An orig. Cedar 24" now a 32" DBH cedar bears N.25 1/2°W., 11.2 ft.
 Tree has fully healed double blaze.
 A 37" D. Fir now a 37" DBH D. Fir bears S.69°W., 24.2 ft. Tree has
 fully healed double blaze.
 Set - Location of base of brass cap pipe monument is referenced out
 (measurement of accessories were checked from this location.)
 Monument is lowered, plumbed and set firmly at above referenced
 location. Monument now protrudes 7" from ground. Cedar stake
 is lain next to monument.
 New BT's-

Romanso E. Ware
 Ronald Quimby
 For: U.S. Forest
 Service
 July 1980
 M 79 - 49

Roma-so E. Ware
 Ronald Quimby
 For: U.S. Forest
 Service
 July 1980
 M 79 - 50

Stephen J. Flause
 Deputy, for Doug.
 Co. Surveyors Off.
 D. Stewart, witness
 Feb. 17, 1981
 C.S. 16/19

S. J. Flause, Deputy
 Doug. Co. Surveyors
 Office
 D. Stewart
 March 30, 1981
 C.S. 61/19