

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 27                      T. S.                      R 2                      R.W.W.M.

220

ROSE-CHAPMAN CO., EUGENE, ORE. 97101

C O N T - - - - -  
Dougl. Co. Surveyors  
Off. March 30, 1981  
C.S. 61/19-

New BT - A 12" DBH Cedar bears S.15 1/2°E., 7.2 ft. and is scribed T27S R2W  
S20 CS BT on a double blaze.  
New DCSO bearing tree tags are placed on all bearing trees.                      3/30/81

221

Center 1/4 Corner for Section 13  
REFERENCED NOTES ONLY  
Found - 2 1/2" I.P. with properly marked brass cap, firmly set, projecting  
2" above 3 ft. diam. mound of stone, set by R. Ware LS #1005 in  
1977. A steel fence post, firmly set with USFS signs #54-2  
and #54-9 attached bears North 3.0 ft.                      Ren. #162  
1977 BT, a 12" Hemlock (1/2 dead) bears N.69°E., 35.2 ft. with  
scribe marks "C 1/4 S13 BT" and alum. washer stamped "LS  
1005" visible on partly healed double blaze.  
A 25" Hemlock bears S.32°W., 28.7 ft. with scribe marks "C 1/4  
S13 BT" and alum. washer stamped "LS 1005" visible on partly  
healed double blaze.

REFERENCED:  
I reference corner position as described below and remove I.P.  
with brass cap and steel fence post.  
Set 60d nail in base of 68" D. fir snag (on east side of tree)  
bears N.68 3/4°W., 32.9 ft. to center of nail head.  
Set 60d nail in top of 48" D. fir stump (6" from NE edge) bears  
S.74 1/2°E., 27.6 ft. to center of nail head.

**RE-RENEWED, SEE CORNER NO. #228**

All available trees are scheduled to be cut.  
Corner lies in old dirt road which is now new road construction. I.P. with  
brass cap will be reset when timber harvesting and new construction has  
ended.

5/17/82

222

1/4 Corner for Section 13 (north)  
Found - 2 1/2" diam. I.P. with properly marked brass cap, firmly set, flush  
with 2 ft. diam. mound of stone.                      Ren. #161  
1" I.R. with alum cap projecting 8" above 2 ft. diam. mound of stone  
marked U.S. P.C. bears west 0.86 ft.  
4" x 4" wooden post bears 3 ft. west.  
8" alder, S.34°E., 15.0 ft. with fragmentary scribe marks & alum.  
washer visible on partly healed double blaze.                      Ren. #161.  
12" hemlock S.88°W., 38.1 ft. with fragmentary scribe marks &  
alum. washer visible on partly healed double blaze.                      Ren. #161.  
Set - 6 ft. steel fence post East 2 ft.  
This corner lies on east edge of old dirt road, now undergoing new road  
construction.

5/17/82

223

1/4 Corner for Secs. 8, & 9.  
Found - 1" I.P. w/B.C. at fence corner.                      Ren. #2.  
Note: Did NOT locate original basalt stone.  
BTs - Orig. 18", now 30" diam. fir stump, 3-1/2-ft. high w/partially  
healed blaze bears N.63°W., 22.9-ft. (agrees w/Ren. #111. -  
Orig. notes, and 1971 B.L.M. notes call N.66°W., 24.4-ft. &  
23.1-ft., respectively.)  
Orig. SW BT NOT found.  
8" fir (new BT scribed in Ren. #2) bearing N.21°E. NOT fnd.  
11" cedar, now 14" w/well healed dbl. blaze bears S.58°W., 43.8-ft.  
New BTs- 12" hemlock, dbl. blazed & scribed "1/4S8CSBT" bears N.52°W.,  
49.6-ft.

Note: As there are no suitable trees in the area to the East, we  
reference the following:  
- The most Westerly SW corner of a concrete foundation (house)  
w/stone veneer, bears N.32-1/2°E., 33.7-ft.  
- 3-1/4" O.D. I.P. for a basketball hoop pole bears S.78°E.,  
56.4-ft. This pipe is located near the westerly edge &  
approx. at midpoint of a 20' x 30' concrete slab.

Note - Monument is along the westerly edge of a government housing area  
w/fences running generally N, S, W, & Easterly-see sketch in file

2/84

C.S. 59/30- MOVED TO CS 62/15-11

C.S. 61/32

Jim Landrum, U.S.F.S.  
Leonard Herzstein  
May 17, 1982

Larry (Ed) Monrean  
Deputy, Doug. Co. Surveyor  
Douglas County Surveyors Office  
Randy Smith  
Steve Flause  
February 14, 1984  
C.S. 62/16