

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 17 & 20. 45
 Found - W. Fir (now 11" diam.) N 11° W 6.6 ft. Scribing visible on
 previously opened face "1/2 S"
 Hemlock (now 20" diam.) S 30° W 21.1 ft. Shows good axe scar.
 Set - Brass Cap mkd. "County Surveyor's Office 1964 T 27 SR 2 W
 1 S17"
 4 S20
 #126
 Both original BTS in good condition. Did not mark new BTS.

Section Corner to Sections 17, 18, 19 & 20. 46
 Found - Red Cedar (now 32" diam.) N. 25 1/2° W 11.2 ft. Shows good scar.
 Doug. Fir (now 32" diam.) N 19 1/2° E 33.7 ft. Shows very plain
 axe scar.
 Incense Cedar (now 52" diam.) S 67 1/2° E. 41.6 ft. Scribing
 visible in not completely covered scar. #220
 Stump (rotten) & rotten fir log S. 25° W 15.2 ft. Scribing
 visible on log.
 Partly rotted stake, showing scribing, lying on ground at
 corner.
 Set - Brass Cap mkd: "County Surveyor's Office 1964 T 27 SR 2 W
 S18 | S17"
 S19 | S20
 New BT: 37" Doug. Fir S. 69° W 24.2 ft. Mkd: T 27 SR 2 W S19 CS BT.

Milo Godfrey, Deputy
 Wm. Stoffel, Mike Darby
 June, 1964
 C. S. File No. 49/28

Section Corner to Sections 16, 17, 20 & 21. 47
 Found - Doug. Fir (now 14" diam.) S. 22° W 11.2 ft. Opened & found
 scribing on old face.
 Doug. Fir (now 27" diam.) S. 66° E. 15.8 ft. Good scar
 visible.
 Doug. Fir (now 32" diam.) N. 11° E 95.7 ft. Shows scar.
 Doug. Fir (now 33" diam.) N. 62 1/2° W 13.9 ft. Shows very
 plain axe scar.
 Set - Brass Cap mkd: "County Surveyor's Office 1964 T 27 SR 2 W
 S17 | S16"
 S20 | S21
 12/68 FOUND O.K. V.R.T.
 All original BTS. alive and in good condition.
 New BT: In place of fairly distant N.E. tree.
 9" Doug. Fir N 41° E 34.7 ft. Mkd: T 27 SR 2 W S 16 CS BT."

Section Corner to Sections 20 - 21 - 28 - 29. 48
 Found - Old, squared Cedar Stake, dim scribing visible.
 19" Cedar, dead on W. face, good scribing visible.
 36" Cedar S. 22 1/4° E. 40.3 ft., faint traces of old scribing
 visible on partly rotted face.
 24" Cedar N. 28 1/2° W. 61.4 ft., No scar visible.
 Cedar, uprooted & dead, S. 20 1/2° W. 43.6 ft., no scars.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R2W S 20 | S 21
 Office, 1964 S 29 | S 28
 Place old stake alongside.
 New BT's: 8" Red Cedar N. 23 1/2° E. 24.0 ft. Mkd: T27S R2W S21 CS BT.
 9" White Fir S. 20° E. 17.8 ft. Mkd: T27S R2W S28 CS BT.
 8" Red Cedar S. 52° W. 6.4 ft. Mkd: T27S R2W S29 CS BT.
 Note - Corner is approx. 175 ft. north of centerline Wolf Ck. Access Road.
 FOUND O.K. Dec. 1968 V.R.T.

Milo E. Godfrey & Crew
 November 17-18, 1964
 C. S. File No. 49/28

Section Corner to Secs. 19 - 20 - 29 - 30. 49
 Found - 12" Fir Snag N. 31° W. 7.9 ft., cut open & fd. good scribing.
 17" Cedar N. 48° E. 24.4 ft., shows good scar, good condition.
 19" Fir S. 64° E. 17.8 ft., shows good scar, Tree in good condition.
 20" Cedar S. 62° W. 26.4 ft., shows good scar, " " "
 Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R2W S19 | S20
 Office, 1964 S30 | S29
 New BT: 31" Hemlock N. 22° W. 36.0 ft. Mkd: T27S R2W S19 CS BT.
 Note - Corner is approx. 200 ft. S. of Centerline of Wolf Creek Access Rd.
 FOUND O.K. Nov. 1968 V.R.T.

#231