

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21001

69  
Township Corner - T.26 & 27S., R's. 1 & 2W.  
Found - No trace of Orig. Corner Stone or other obliterated BT.  
Orig. 40", now 48" down Fir, S. 74° W. 16.5 ft., open & shows "S W" scribe.  
Orig. 24", Fir, now down & almost completely buried, N. 3° W. 15.2 ft.  
Orig. 6", now 16" Fir, down, S. 60° E. 20.5 ft., open & find obliterated blaze as called for.  
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W S 36 | RLW  
Office, 1967 T27S S 1 |  
New BT's: 10" Cedar N. 70° W. 36.5 ft. mkd. T26S R2W S36 CS BT.  
18" D. Fir S. 88° W. 41.7 ft. mkd. T27S R2W S 1 CS BT.  
Note - This corner lies on southerly slope.

70  
Closing Corner of Township.  
Found - Corner Stone mkd. "CC" & 6 notches on N. & S. edges.  
Orig. 28", now 38" Cedar, alive, S. 62° E. 21.1 ft., scribe visible on unhealed blaze. (Rescribe: "T27S RLW S6 CC CS BT".)  
Orig. 12", now 22" W. Fir, alive, N. 80° E. 25.7 ft., scribe visible on unhealed blaze. (Rescribe: "T26S RLW S31 CC CS BT".)  
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R2W CC S 31 | RLW  
Office, 1967 T27S S 6 |  
New BT: 14" W. Fir S. 35° E. 30.9 ft. mkd. T27S RLW S6 CC CS BT.  
Note - This corner lies on steep north slope approx. 450 ft. south of E. Mile Creek.

71  
1/4 Corner to Sec. 1, T27-2W. & Sec. 36, T26S-2W.  
Found - 1" Iron Pipe, firmly set, unrecorded.  
Orig. 16", now 24" Cedar, turned out stump, N. 30° W. 23.1 ft., prev. opened & shows "S36" scribe.  
No trace of other Orig. BT.  
DO NOT SET BRASS CAP.  
New BT's: 7" W. Fir N. 26° W. 18.4 ft. mkd. 1/4 S36 CS BT.  
7" Hemlock S. 77° E. 33.8 ft. mkd. 1/4 S 1 CS BT.  
Note - This corner lies on southerly slope in dense vinemaple brush.

MICROFILM TO HERE 10/67 72

Section Corner to Sections 14 - 15 - 22 - 23.  
Found - Orig. 26" Fir, now 28" Stump, N. 67° E. 23.1 ft., scribe visible.  
Orig. 30" Fir, now 36" Stump, pushed out of place, S. 83 1/2° E. 22.4', shows scar.  
Orig. 30", now 34" Fir, alive, S. 45° W. 63.4 ft., shows good scar.  
Orig. 30", now 34" Fir, alive, N. 65° W. 44.9 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W  
(N. Side of Cat. Road) Office S 15 S 14  
1968 S 22 S 23  
New BT's: 15" Pine N. 77° E. 53.7 ft. mkd. T27S R2W S14 CS BT.  
8" D. Fir S. 72° E. 65.0 ft. mkd. T27S R2W S23 CS BT.  
Note - This corner lies on N. side recent Cat. skid road in thinned area.

73  
Section Corner to Sections 22 - 23 - 26 - 27.  
Found - Orig. 24", now 28" Hemlock Corner Tree, high stumped, 7' high, scribe on all four sides.  
Orig. 36" Fir, now 40" Stump, N. 4° E. 37.6 ft., shows scar.  
Orig. 24", Hemlock, now 26" stump, S. 44° E. 35.0 ft., scribe visible.  
No trace of Orig. N.W. or S.W. BT's.  
Set - Brass Cap at Cor. Mkd: County Surveyors T 27 S R 2 W  
(1.5 ft. E. of center Office S 22 S 23  
of Corner Tree) 1968 S 27 S 26  
New BT's: 5" D. Fir S. 32° W. 12.6 ft. mkd. "S27 CS BT.  
5" D. Fir S. 15° E. 21.4 ft. mkd. "S26 CS BT.  
5" D. Fir N. 16° E. 18.8 ft. mkd. "S23 CS BT.  
6" D. Fir N. 32° W. 34.3 ft. mkd. "S22 CS BT.  
Note - Bearings & Distances to new BT's. are from brass cap.

Vernon "Ray" Tracy  
Jack Heritage & E. West  
August, 1967  
C.S. File No. 54/40

FO 6/19/86  
R. Gaisler  
C.S. 63/84  
Vernon Ray Tracy  
Jack Heritage & V. Perron  
April, 1968  
C. S. File No. 54/40