

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97811

97

$\frac{1}{4}$ Corner to Sections 24 and 25.
Found - No trace of Brass Cap called for in Ren. #13.
Orig. 68" Fir, now sawed stump, N. 22 $\frac{1}{2}$ °E. 23.8 ft.
9" Yew N. 17°W. 24.0 ft., dying, scribe visible.
22" Hemlock S. 65°W. 12.0 ft., now sawed stump, scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 2 W
(Set 6 ft. steel fence Office $\frac{1}{4}$ S 24
post alongside B.C.) 1968 $\frac{1}{4}$ S 25
New BT's: 8" Hemlock N. 43°W. 65.0 ft. mkd: $\frac{1}{4}$ S 24 CS BT.
14" Hemlock S. 25°E. 53.3 ft. mkd: $\frac{1}{4}$ S 25 CS BT.
This corner lies 2.0 ft. south of sid road in logged area.

98

$\frac{1}{4}$ Corner to Sections 13 and 24.
Found - 6", now 10" Live Oak Corner Tree, open & find scribe & reverse.
Orig. 6", now 11" Live Oak, alive, shows good scar.
Orig. 8", now 17" Fir, alive, S. 5°W. 15.2 ft., shows good scar.
Set - Brass Cap Under Corner Tree Mkd: County Surveyor's T 27 S R 2 W
Office $\frac{1}{4}$ S 13
1968 $\frac{1}{4}$ S 24
New BT's: 8" R. Fir N. 55°E. 8.0 ft. mkd: $\frac{1}{4}$ S 13 CS BT.
Orig. 17" D. Fir S. 5°W. 15.2 ft. mkd: $\frac{1}{4}$ S 24 CS BT. (above old scar)
This corner lies 15 ft. E. of top of 75 ft. high vertical bluff.

99

$\frac{1}{4}$ Corner to Sec. 7, T27-2W. and Sec. 12, T27-3W.
Found - $\frac{1}{2}$ " I. Rod & BT's. as recorded in Ren. #8.
10", now 12" D. Fir, alive, S. 57°W. 26.5 ft., blaze nearly healed over.
6", now 8" D. Fir, alive, S. 11°E. 21.0 ft., scribe visible on
partially healed blaze.
Orig. N.W. BT., now burned out stump, no scribe, only opening
facing corner point.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S
(Reset I.R. alongside) Office, 1968 R3W $\frac{1}{4}$ S12/S 7 R2W
This corner lies on N-S fence line 50 ft. S. of left bank of Little River.

11/8/68

100

Sec. Cor. to Sections 18 & 19 only, T27-1W.
Found - 3/4" I.R. under 40" Log & 40" Fir Stump N. 34°E. 60', See Ren. #44.
24" Hemlock Snag, now down & only decayed remains of
stump in place, we saw 40 out.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 27 S R
(Reset I.R. alongside & Office 2 S 18 1
Set 6' Steel Fence Post) 1968 W S 19 W
No trees or stumps available for bearing trees.
This corner lies approx. 125 ft. west of Rd. #274L in logged off area,
now densely covered with greasewood brush.

101

$\frac{1}{4}$ Corner to Sections 11 and 12.
Found - U. S. Plywood Alum. Cap & BT's. & old corner stone, See Ren. #39.
Orig. 7", now 10" Fir, burned, S. 72°E. 34.3 ft., Open higher &
find scribe & reverse, dead snag. (See Shrum's Survey M 37-18)
8" Hemlock S. 30°W. 26.3 ft., scribed $\frac{1}{4}$ S11 BT".
New BT: 10" D. Fir S. 18°E. 3.9 ft. mkd: $\frac{1}{4}$ S12 CS BT".
This corner lies on N - S cutting line, clear cut in Section 12.

102

Closing Corner to Sections 13 & 14.
Found - 1957 C.S. Brass Cap, in place, See Ren. #5.
70" R. Fir Stump, good cond., burned, S. 88°W. 67.0 ft., scribe visible.
Orig. now 24" Fir Stump, badly burned, S. 35°E. 47.5 ft., scribe visible.
Orig. now 40" Hemlock Stump, S. 37 3/4°W. 35.0 ft., shows scar.
Set - 5/8" I.R. 10.0 ft. west & 5/8" I.R. 15.0 ft. west.
6.0 ft. Steel Fence Post alongside Brass Cap.
The Sec. Cor. Secs. 11 & 12 bears S. 86°E. 71.9', see corner over.
This corner lies in dense greasewood brush in clear cut area.

11/15/68

Vernon "Ray" Tracy
Frank Jones & V. Perron
November, 1968
C. S. File No. 54/40

RE-REVIEWED, SEE CORNER NO. #214
RE-REVIEWED, SEE CORNER NO. #229
RE-REVIEWED, SEE CORNER NO. #164
RE-REVIEWED, SEE CORNER NO. #245
RE-REVIEWED, SEE CORNER NO. #158