

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

Ben B. Irving Co. Surveyor
Witnesses
H. C. Carey
R. C. Kerchner

SEE NOTES IN C.S. FILE 38/46

✓ 1/4 Cor. Bet. Secs. 11 & 14
Orig. B. Ts. in place, Reblazed and Scribed old trees
Drove 3/4" x 5' 4" in ground
RE-RENEWED, SEE CORNER NO. #141
FD. 2/8/6 GRUBB M 26-55 Mar. 13-45

1

✓ Cor. Secs. 11-12-13-14
Location identified from O.B.T.
Set Stone 8x8x20" 10" in Ground for Cor.
60" Fir N.46°45'E. 71.9 ft.
32" " S.72°23'E. 90.0 ft.
16" " N.54°45'W. 16.0 ft.
10" " S.10°22'W. 12.4 ft.

CORNER REPORT
C.S. 63/54
2/25/46

2

✓ 1/4 Cor. Bet. Secs. 11-12
Location identified from O.B.T. 18" Fir 3 lks. and
O.B.T. Stump 26 lks. Remarked O.B.T.
18" Fir S.70°W. 1.9 ft. 58.19 ft. (see notes)
30" Fir N.80 1/2°E. 31.0 ft.
Set Stone 6x8x14" Marked 1/4 on N. Face
Mar. 14-45

3

✓ Cor. Secs. 1-2-11-12
As described by Boyer and recored--Cedar in Sec. 2 REN #14
broken off, O.B.T. Sec. I will burn out
Marked Yew 8" N.49°W. 39.7 ft.
Fir 36" N.68°E. 29.8 ft.
Mar. 15-45

4

✓ Cor. Secs. 2-3-10-11
Identified from 3 O.B. Ts.
Remarked O.B. Ts.
Marked a Fir 24"N.10°E. 24.6 ft.
Set Stone 12x15x24" Marked 5 Notches S. 2 Notches E.
1 Notch N. 4 Notches W.
Mar. 22-45

5

✓ Cor. Secs. 10-11-15-14
Set Yew Wood Post 4 Rocks
O.B.T. 48" Fir N.38°W. 54 lks. Remarked
" " " 20" Fir S.55°E. 19 lks. "
New B.T. 8"Cedar S.58°W. 19.4 ft.
" " 8"Cedar N.66°E. 28.7 ft.
Mar. 26-45

SEE CORNER NO. 41

6

✓ Cor. Secs. 13-14-23-24
Set 4x14x22" Rock
20" Fir N.45°E. 4.2 ft.
8" Fir N.22°W. 28.3 ft.
42" Fir S.35°E. 47 lks. O.B.T.
18" Fir S.39°W. 42.3 ft.
Remaining Fir B. Ts. down but scribe marks visible
Mar. 29-45

SEE CORNER NO. 112

7

✓ 1/4 Cor. Bet. Secs. 13-14
Set Stone 8x14x24" Marked 1/4 S. on face
Remarked O.B.T.
RE-RENEWED, SEE CORNER NO. 108
Apr. 3-45

8

✓ 1/4 Cor. Bet. Secs. 14-15
Set 6x8x16" Stone
60" Fir N.60°E. 3.0 ft.
20" Fir N.75°W. 18.8 ft.
SEE CORNER NO. 97
Apr. 4-45

9