

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

SEE CORNER NO. 37

✓ $\frac{1}{4}$ Cor. Bet. Secs. 14-23
Set by porportional dist. bet. Secs. Cors.
2"x48" Pipe 36" in ground
15" Fir N. $24\frac{1}{2}^\circ$ E. 22.2 ft.
15" Fir S. 77° W. 18.2 ft.

10

Ben B. Irving
Co. Surveyor
Wit.
H. C. Carey
R. C. Kerchner
Apr. 1945

S. E. COR. OF EXTERIOR "L" CLAIM 38

11

Set corner from running East interior "L" Corner of Cl. 39 and making tie to township line between sections 1 and 6. Set $1\frac{1}{2}$ " x 36" iron pipe to a Curby Reaper. Marked the following trees:
White Oak 8" dia. bears N. 51° E., 54.9 ft.
White Oak 12" dia. bears N. 52° E., 82 ft.

H. L. Epstein
Witnesses
W. S. Creer
R. I. Cammon
W. Smith
W. E. Chapman

SECTION CORNER BETWEEN 15, 14, 22, and 23.

12

Identified location by old post badly rotted and all original B.T.s. Set a new 4" Fir Post for corner. Reblazed and scribed all original B.T.s. Post replaced with 1"x36" iron pipe with brass cap stamped "C.S.O."

$\frac{1}{4}$ SECTION CORNER NORTH SIDE SECTION 6 T. 27 S R 3 S 14, S. 15, S. 22, S. 23

12-A

Identified location from original B.T.s. Drove 1" Iron Pipe for corner from which
Fir 16" dia. bears S. $5^\circ 54'$ E., 144 ft.
Fir 18" dia. bears N. $31^\circ 33'$ E., 66 ft.

Ben B. Irving
Dep. Co. Sur.
Witnesses
Ed Russell
F. E. Chapman
Dec. 26, 1922

$\frac{1}{4}$ SECTION CORNER BETWEEN SECS. 5 and 6

13

Identified location from Original B.T.s. Set a fir post for corner from which a
Fir 10" dia. bears S. 25° E., 10.5 ft.
Fir 14" dia. bears N. 30° W., 3.3 ft. O. B.T.

Ben B. Irving
Dep. Co. Sur.
Witnesses
O. J. Noice

SECTION CORNER BETWEEN 2, 1, 11, and 12

14

Found trees in N.E. Sec. 1 and S.W. Sec. 11 quadrants O.K. but scribe marks gone so that they are hard to read but could be identified so renewed scribe marks on these trees. Found Laurel, gone Sec. 2, except stump so renewed it: Maple in Sec. 12 gone renewed for this quadrant. Set Fir Post and set pole of Rocks for Corner from which
Cedar 8" dia. bears N. $58\frac{1}{2}^\circ$ W., 12.5 ft.
Maple 14" dia. bears East 48.7 ft.

Arthur Boyer
D.C.S.
Witnesses
N. E. Richardson
Jno. LeBoite
O. J. Noice

50. $\frac{1}{16}$ th CORNER BETWEEN 1 and 2.

15

Set Fir Post and Pile of Rocks for corner form which
A Oak Stump 12" dia. bears S. $80\frac{1}{2}^\circ$ W., 70.9 ft.
A Pine Stump 36" dia. bears N. $57\frac{1}{2}^\circ$ E., 84 ft.

SECTION CORNER BETWEEN 35, 36, 1, and 2.

16

Identified location from scribe marks on Oak Tree, which was down, tree was in Sec. 2, found stump hole and cut out scribed face, no other evidence. Set Fir post and rocks for corner from which
A 12" Fir bears N. 36° W., 8.0 ft.
A 15" Fir bears N. 11° E., 1.75 ft.
A 12" Fir bears S. 72° W., 19.0 ft.
A 20" Fir bears S. 34° E., 22.5 ft.

Arthur Boyer
D.C.S.
March 1936
Witnesses

$\frac{1}{16}$ th CORNER ABOUT $\frac{1}{4}$ MILE NORTH OF $\frac{1}{4}$ CORNER OF SECTION 1 and 2.

17

Set Post, Fir, for corner from which
Fir 12" dia. bears S. 61° E., 18.7 ft.
Pine 40" dia. bears S. 20° W., 34.6 ft.

N. E. Richardson
F. V. Gurney
O. J. Noice
S. J. Noice

Township Corner - Northwest Corner Section 6, T27-3W.

Reset from 3 Old BT's., badly deteriorated.

Set - $1\frac{1}{2}$ " I. Pipe with Brass Cap 24" ground Mkd: R4W T26S S36 | S31 T27S S1 | S6 R3W
36" Fir, bearings S. 6° E. 543.8 feet.
10" W. Oak bears S. 81° W. 195.8 feet
30" W. Oak bears N. $15\frac{1}{2}^\circ$ W. 231.5 feet.

Jan. 7, 1947

N. E. Richardson
Wit: Milo Godfrey & L. Kershner