

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FDOK 2/2002
D. Edwards CS 65/41-4 109

Thomas E.
Shrum, Jr.
For: U.S.Ply.
Jan. '69
C. S. File
No. 51/254

$\frac{1}{4}$ Corner to Sections 25 and 26.
Found - 18" Doug. Fir, now 42", N. 39° E., 52.8 ft., faint bark scribe.
30" Cedar, S. 80° W. 28.4 ft., down & burned.
Set - 2 $\frac{1}{2}$ " Alum. Cap: Section 26, Section 25, 1969
New BT's: 12" Cedar S. 60 $\frac{1}{2}$ ° E. 30.0 ft. mkd: $\frac{1}{4}$ S 25 BT.
9" Doug. Fir S. 20° W. 3.8 ft. mkd: $\frac{1}{4}$ S 26 BT.
Jan. 6, 1969

$\frac{1}{4}$ Corner to Sections 6 & 5
Found - .B.T.S as follows:
Orig. 32" now 38" Fir S. 60°E. 14.5 Ft. Alive frag.
barkscribe visible.
Orig. 30" now 48" Fir S. 80°W. 34.3 Ft. Alive barkscribe
" $\frac{1}{4}$ S BT" visible at Cor. point Set 1" I.P.
Set - Brass Cap Mkd:

T 27 S County Surveyors T 27 S R 2 W
Office, 1969 $\frac{1}{4}$ S 5 S 6

And Mkd. new BT's
9" Pine N. 49°E 26.3 Ft. Mkd. $\frac{1}{4}$ S 6 CS BT
This Cor. lies on Southerly slope in old growth timber 6-4-69

Cl. Cor. of Sections 19 and 30 T 27-2.
Found - O.B.T.s as follows:
Orig. 30" Now 40" Fir N. 65 $\frac{1}{2}$ ° E. 22.4 Ft. Alive--shows good
scar. Orig. 36" Fir S. 64°E 48.8 Ft. Now badly decayed remains of
stump. Blaze intact. Shows "T 27 S R 2 W S 30 B $\frac{1}{4}$ Scribe, At point
for closing Cor.
Set - 1" I.P. & Brass cap Mkd:

County Surveyors T 27 S
Office, 1969 R 3 W S 19 R 2 W
S 30

8" D. Fir, N.76°E. 10.6 ft. mkd: "T27S R2W S19 CC CS BT".
8" D. Fir S. 27° E. 15.2 Ft. Mkd. T 27 S R 2 W S30 CC CS BT
This Cor. lies on S. W. slope & approx. 217.8 Ft. South of the Sec.
Cor. of Sec's 24 & 25 of T 27 S R 3 W. 4-22-69

THIS IS NOW AN AMENDED
CLOSING CORNER-SEE BEN 110
#142 FOR NEW CC - 8185
BY RON GEISLER
M 90-71

Section Corner to Sections 24 & 25 ONLY.
Found - OBTS as follows:
Orig. 20" now 30" Fir S. 78°W 28.1 Ft. now badly decayed
remains of stump bark scribe "R3W S 25 R 1"
Orig. 28" now 48" Fir S. 65°E. 29.0 Ft. Alive axe Mk. on bark.
No scribe or scar. No trace other O.B.T.S. at Cor. point.
Set 1" I. P. & Brass Cap. Mkd:

County Surveyors T 27 S
Office, 1969 R 3 W S 24 R 2 W
S 25

& Mkd. new Bt's
6" Hemlock N. 83 E. 33.7 Ft. Mkd. T 27 S R 2 W S 19 CS BT
1 $\frac{1}{2}$ " D. Fir S. 10°W 2.0 ft. Mkd. T 27 S R 3 W S 25 CS B $\frac{1}{4}$
8" Cedar N. 71°W. 51.5 Ft. Mkd. T 27 S R 3 W S 24 CS BT
This Cor. lies on very steep N. slope of spur & 217.8 Ft. No. of
Closing Cor. of Sec's 19 & 30 of T 27 S R 2 W. 4-22-69

Fd Aug 1/1985
BY RON GEISLER
M 90-71

Section Corner to Sections 13 - 14 - 23 - 24.
Found - 4x14x22" Corner Stone mkd. with 5 notches on W. & 3 notches on S.
20", now 24" Fir, alive, N.45°E. 4.2 ft., shows good scar.)
8", now 13" Fir, alive, N.22°W. 28.3 ft., shows good scar.) Ren.#7.
Orig. S.E. BT., now sawed stump. Other BT to S.W. now sawed stump.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 3 W
(Reset Stone alongside) Office S 14 S 13
1969 S 23 S 24
New BT's: 11" D.Fir S.81°W. 26.8 ft. mkd: T27S R3W S23 CS BT".
10" D.Fir S.49°E. 38.5 ft. mkd: T27S R3W S24 CS BT.
This corner lies on moderate S.W. slope.

9/9/69

Vernon "Ray" Tracy
Jack Heritage, V. Perron
4/22/69
C. S. File No. 54/40