

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 S T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 9 & 10
Found - O.B.T. as follows:

Orig. 8" now 24" Cedar N. 69°W. 10.6 Ft. now 25 Ft. hi snag,
Previously opened, possible scribe mark on upper blaze. Chop out lower
blaze & find "BT" scribe & Reverse. No trace of other O.B.T. except
probable stump hole in ground at bearing & Dist. at cor. point.
Set - 1" I.P. & Brass cap mkd. "

County Surveyors T 27 S
Office, 1969 1/4 S9/ S 10 R 3W

6" Maple N. 37° E. 27.2 ft. mkd: "1/4 S10 CS BT.
8" Hemlock N. 73°W. 16.2 ft. Mkd. 1/4 S 10 CS BT.

Also - As reference monument, Set 3/4" x 36" Iron Rod N. 42°W. 29.0 Ft.
on South shoulder of access Road. Jim Creek access Road bears South
Approx. 100 Ft. 1/4 Cor. lies on steep S.W. slope between roads. 5-7-69

112A

1/4 Corner to Sections 29 & 32

Found - O.B.T.s as follows - (See also Ren. #52)

Orig. 36" Now 50" Fir N. 10°E. 37.6 Ft. Alive - Orig. bark scribe
& shrums bark scribe. *SD per research 8/1/2008 JC*

Orig. 16" now 36" Fir S. 88°W. (Records 30°W.) 57.4 Ft. Alive-
Orig. bark scribe only. Fragmentary - shrums bark scribe o.k.
at cor. point.

Set - 1" I.P. & Brass Cap Mkd:

County Surveyor's T 27 S
Office, 1969 1/4 S 29 R 3 W
S 32

Mk. new B.T.s

13" D. Fir N. 63°W. 12.6 Ft. Mkd. 1/4 S32 CS BT

This Cor. lies on E. W. cutting line - clear cut in Sec. 32 6-20-69

113

Sections Corners to Sections 29,28,32,33

Found - 3/4 I. R. Not set & B.T.s as follows:

See Ren. #53

Orig. 50" Now 60" Pine S. 55°W. 59.4 Ft. Now sawed stump - scribe
visible.

Ren. B.T.s

44" D. Fir N. 40°W. 40.8 Ft. alive & O.K. good scribe

28" Madrone S. 8°E. 56.4 Ft. Alive O.K. good scribe.

N. E. B. T. gore - at Cor. point

Set - 1" I.P. & Brass Cap. Mkd:

County Surveyor's T 27 S R 3 W
Office, 1969 S 29 S 28
S 32 S 33

Reset I.R. along side Brass Cap & Mk New B.T.

16" D. Fir N. 71°E. 60.6 Ft. Mkd. T 27S R 3 W S 28 CS Bt

No suitable trees available in Sec. 32. This cor. lies on very
steep northerly slope. 6-20-69

114

Section Corner to Sections 4 - 5 - 8 - 9.

Found - Scribed Stake, out of ground.

24", now 28" D. Fir, N. 45°W. (face) 9.9 ft., bark scribe visible. *Ren. #19*

48", now 50" D. Fir, N. 10°E. 19.8 ft., shows good scar & bark scribe.

10", now 13" Cedar, S. 30°E. (face) 9.1 ft., partly overgrown, scribe
marks visible.

24" W. Fir, now down, S. 73°W. (Rec. S50W) 30.4 ft., bark scribe found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 3 W

Office S 5 S 4
1969 S 8 S 9

New BT: 15" W. Fir S. 25°W. 26.7 ft. mkd: "T27S R3W S8 CS BT".

Reblzd. & Rescrbd: 28" D. Fir N. 45°W. 9.9 ft. mkd: "T27S R3W S5 C S BT.

This corner lies at old fence corner, fences running N. & W.

10/10/69

*Fd OK
D. Edwards
11/2006
H151-61*

115

Vernon "Ray" Tracy
Jack Heritage & V. Perron
6-20-69 C. S. File No. 54/40