

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 275 T.S. 3 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

David Edwards  
For: Roseburg  
Resources  
May 2001  
M138-18 &  
C.S. File 65/34-8

Corner Secs. 5, 6, 7, & 8  
Found - BLM brass cap  
10" dia., Mad. bears N.47½°E., 14.52 ft.  
9" dia., Mad. bears S.66°W., 8.58 ft.  
9" dia., Mad. bears N.36°W., 41.58 ft.  
New BT - 8" dia., Mad bears S.40°E., 14.40 ft.

FD OK by K. DeGroot  
8/2005 M146-27

170  
FDOK  
D Edwards  
11/2006 M151-61

Douglas Co.  
Surveyors Office  
Randall W. Smith  
Stephen J. Flauser  
12/2/2002  
C.S. File 66/48-15

SE Cor. Ext. L DLC 38  
Found - 1½" dia., iron bar with center punch 1" below ground. See old ren #11.  
12" now 24" dia., W.Oak we open and find good line scribe mark bears N.52°E. 82.0 ft. (ren #11)  
8" now rotted down W.Oak bears N.51°E., 54.9 ft. (ren. #11)  
New - 18" dia., W.Oak double blazed & scribed "SE L DLC 38 CS BT" bears N.7°E., 61.5 ft.  
16" dia. I.Cedar double blazed & scribed "SE L DLC 38 CS BT" bears N.32½°W., 89.4 ft.  
Compass decl. 17½°E.  
Renewed corner as determined by Ren. #11

171

Douglas Co.  
Surveyors Office  
Randall W. Smith  
Stephen J. Flauser  
12/5/2002  
C.S. File 66/48-17

NE Cor. DLC 38  
Found - 1964 DCSO brass cap/iron pipe, protrudes 6" out of ground. Ren. #95  
30" now 42" dia., W.Oak snag previously opened, circular scribing visible, bears N.85°W., 6.6 ft. to blaze (OBT)  
30" now 36" dia., 2½ ft. D.Fir stump we open and find scribing "BT" N.78°E., 8.6 ft. (1964 Ren.#95)  
7" now 28" dia., D.Fir with a fully healed blaze, bears S.69°W., 50.7 ft. (1964 Ren. #95)  
New - 19" dia., D.Fir double blazed & scribed "NE DLC 38 CS BT" bears S.25°E., 6.4 ft.  
12" dia., D.Fir double blazed & scribed "NE DLC 38 CS BT" bears N.3½°W., 13.9 ft.  
7" dia., D.Fir double blazed & scribed "NE DLC 38 CS BT" bears N.36°E., 13.9 ft.  
Compass decl. 17½°E.

172

Ron Quimby  
For: Rsbg  
Resources  
5/2005  
M147-62

1/4 Cor. Secs. 1 & 2  
Found - 1958 BLM BCIP, properly marked.  
19" Fir bears N.3°E., 51.8 ft., healed scar.  
26" Fir bears S.75°W., 22.4 ft., healed scar.  
40" Fir stump N.51°E., 80.7 ft. (Ren. #32)  
New BTs - 8" Fir bears S.52°E., 22.9 ft. scribed ¼ S1 BT.  
6" Fir bears N.5°W., 13.8 ft. scribed ¼ S2 BT.

173

Center 1/4  
Found - Alum. cap on IP (ren #159)  
8" D.Fir bears S.71°E., 39.2 ft.  
New BTs - 5" Oak bears N.34°W., 49.8 ft. scribe ¼ S2 BT.  
4" Oak bears S.53°E., 6.0 ft. scribed S BT.  
Set 5/8" iron rod with yellow plastic cap marked "IE ENGINEERING" bears N.53°E., 6.0 ft. (BO)  
No trees to East small Oak to West.

174

Cont. next Pg.