

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

3

R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 91881

Douglas Co.
Surveyors Office
Stephen Flause
John Pike
12/13/2006
C.S.67/14-50

1/4 Secs. 7 & 8

175

- Found - 2 1/2" dia., DCSO brass cap (properly mkd) projects 3" above ground, firmly set.
Orig. 24" now 26" dia., x 30 ft. tall burnt Fir snag no marks visible, bears S.80°E., 13.9 ft. (agrees w/rec.) Orig. BT.
13" now 27" dia., I.Cedar, partially burned on South side - is alive - fully healed single blaze visible, bears N.65°W., 37.6 ft. (agrees w/rec.) 1958 BT
22" now 12" dia., x 4 ft. tall madrone stump, east portion of tree rotted away, illegible scribing on opened rotted face bears S.84 1/2°E., 35.6 ft. (agrees w/rec.)
13" dia., D.fir, fully healed single blaze w/BT tag. This tree not of previous rec. Tag indicates tree was marked by Devore., bears N.23 1/2°E., 37.6 ft. (We agree w/information posted on tag.)
- New - 6" dia., D.Fir double blazed & scribed "1/4 S8 CS BT" bears S.66°E., 38.3 ft.
9" dia., D.Fir double blazed & scribed "1/4 S7 CS BT" bears S.27°W., 26.2 ft..
- Note - Lies on moderately steep north facing slope in area of burned trees approx. 50 ft. N or ridge top, ridge bears ENE
Compass decl. 16 1/2°E.

David Edwards

5/2007

1/4 Cor. Secs. 9 & 10

176

- Found - Brass Cap (Ren. #112A)
13" Maple N.37°E., 27.2'
10" Hemlock snag N.73°W., 16.2'
Both with healed blaze.
- New - 8" fir N.53°W., 15.3'
6' steel post 2' north.
-

M153-3

Sec. Cor. 9, 10, 15, & 16

177

- Found - (BLM) Brass cap (pgs 12434-5)
36" cedar N.89°W., 62.7', with healed blaze.
- New - 4" Hemlock S.52 1/2°E., 9.9'
8" Fir S.57 1/2°W., 7.3'
6' steel post north 2'