

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

CORNER BETWEEN SECS. 22, 23, 26 and 27

At which point I found one of the original bearing trees standing and in good shape with scribe marks plainly legible. A fir 48 ins. diam bearing N 23°W 50 lks. Careful measurements disclosed the remnants of 2 other of the original bearing trees viz. charred roots and stump hole of the laurel N 70°E 69 lks. and the fir stump burned off level with the ground S 52°E 90 lks. Measuring in from these points, we located the hole in which the original corner stake stood and at the point set a 1"x36" iron pipe, with a brass cap stamped "County Surveyors Office T. 27 S R 3 W S 22, S 23, S 26, S 27." for the corner.

28 BEN B IRVING
D.C.S.
WIT. Milo Godfrey
Lester Kershner
May 14, 1947

M 16-78
C.S. 38/187

SECTION CORNER BETWEEN SECTIONS 23, 24, 25 and 26

The location of this corner was determined from the following bearing trees viz. a fir 72" dia. bears S 42°E 68 lks. This tree had fallen and no scribe marks were found. A fir 40 ins. dia. bears N 12°E 115 lks. (75.9') was recorded as N 22°E. A fir 30 ins. dia. N 20°W 41.6 ft. (63 lks) was recorded N 30°W 53 lks. a fir 30 ins. dia. S 85°W 18 lks. recorded as 43 lks. (now a rotten snag). The scribe marks were legible in the bark of these trees (3). The distance east to the small creek was also checked indetermining the location of the corner. The original trees in the north quadrants were re-scribed and a hemlock 12 ins. diam. bears S 1°W 10.3 ft. and a hemlock 10 ins. diam. bears S 85°E 23.3 ft. were reserved for new trees. At the corner I set a 1"x36" iron pipe with a brass cap, stamped "County Surveyors Office T 27 S R 3 W S 22, S 23, S 25, S 26"

27 BEN B IRVING
D.C.S.
WIT. Milo Godfrey
Lester Kershner
May 14, 1947

C.S. 38/187

SECTION CORNER BETWEEN SECTIONS 23 and 26

By proportional measurement, at the midpoint of this line I set a 1"x36" iron pipe with a brass cap, stamped "County Surveyors Office 1/2 S S 23 S 26." for the corner from which a fir 14 ins. diam., bears N 43°W 9.7 ft. and a fir 12 ins. diam. bears S 50°W 13.6 ft.

28 BEN B IRVING
D.C.S.
WIT. Milo Godfrey
Lester Kershner
May 14, 1947

CENTER 1/4 SECTION CORNER SECTION 23

I set a 1"x36" iron pipe with the brass cap, stamped "County Surveyor Office 1/4 S S 23" for the center 1/4 section corner and from which a fir 14 ins. in diam. bears S 30°W 44.4 ft. and a fir 10 ins. diam. bears N 3°E 45.9 ft.

29 BEN B IRVING
D.C.S.
WIT. Milo Godfrey
Lester Kershner
May 14, 1947

RE-RENEWED. SEE CORNER NO. #133
FD. 6-12-19 - B.A. M. 1/4 1/2 1/2 1/2

Sec. cor. to secs. 2 & 3, T 27 S, R 3 W., and 34 and 35, T 26 S, R-3 W.
Found 1 1/2 inch shaft and mound of stone.

30

SEE BLM RESURVEYS

1/4 corner to secs. 2 and 3.

Renewed from O. B. T., N. 80°E., 46.9 feet, scribed 1/4 S in fair condition. Set brass cap at corner marked County Surveyors Office 1/4 S 3/2 T 27 S R 3 W 1954. Blazed and scribed:
A 6 inch yewood, S. 49°E., 30.4 feet, marked 1/4 S S 2 CS BT.
A 10 inch R. Fir, S. 76 1/2°W., 107.9 feet, marked 1/4 S 3 CS BT.

31 James W. Byron, Dep.
County Surveyor
April, 1954
R. Irving
John Fee
C. S. File
46/20.

1/4 corner to secs. 1 and 2.

Found:
3 inch by 3 inch scribed post and 5/8 inch I. P. Old B. T. (snag), scribing visible, N. 50°40'E., 80 ft. diam. Set brass disk. Ren. #18
Blazed and scribed 40 inch Fir (snag), S. 61°W., 48.0 feet., marked 1/4 S 2 C. S. BT. Set brass disk.
Red Butte Lookout bears S. 48°E.
Old fence corner bears N. 74 1/2°W., 6.0 feet.

32

SEE CORNER NO. 173